

2760 Beverly Dr. Suite 9 Aurora, IL 60502 630.506.5535 www.allegiantfire.net Property:

Address:

City:

State:

Report to: Remedy Medical Properties, Inc.

RMP, 8 Salt Creek Ln

IL

8 Salt Creek Lane Hinsdale Zip: 60521 Date: 07/03/2023 Job Number: 29683797

Technician:

Jon Rocke, Zachary Ross

Annual Fire Sprinkler Inspection Report

	Central Station	DuComm	POS/Acct			8225	Out	285	IN 2		285
			GENERAL					YES	NO	N/A	Note#
Is th	ne building currently occ	upied?						V			
	the occupancy classific		tents remaine	d the same	e sinc	e the last inspect	ion?	<u></u>	$\overline{\Box}$	$\overline{\Box}$	
	all fire protection system							<u></u>			
Has	the system remained in	service without modific	cations or actu	ations of a	devic	es/alarms since la	st inspection?	V			
Fire	pump onsite?								✓		
_		SPRI	INKLERS (visibi	'e)				YES	NO	N/A	Note#
	e of damage or leaks?		2						Н		
	e of corrosion, foreign m		g ?						Н	Η.	
	alled in proper orientati	on?							Н	片.	
	d in glass bulbs?		61 1 : 1						Н	片.	
	re head box contains pr		-	ding wrenc	h(s):	,			Н	片.	
	utcheon plates are prese								Н	片.	
	imum clearance betwee								Н	片.	
Spri	nklers tested or replace	a per appropriate testin	g scheaule?							Ш.	
Spri	inkler heads in use and e	earliest date on heads:									
St	candard: Q	uick Response:	ES	SFR:		Dry Pend	dant:	_		-	
			PIPING					YES	NO	N/A	Note#
In g	ood condition with no e.	xternal corrosion?						V			
No	leaks or mechanical dan	nage?						~			
Cor	rect alignment/No exter	rnal loads?						~			
We	t Sprinkler piping not ex	posed to freezing tempe	eratures?					~			
Har	ngers/bracing not dama	ged or loose?						~			
		5/05 0504/	T. 454/T 604/1	IECTIONS.				V50	440	A / / A	A
Vici	ble and accessible?	FIRE DEPAR	RTMENT CONN	IECTIONS				YES	NO	N/A	Note#
	plings swivel and opera	te nronerlu?							H	∦ .	
	gs or caps in place?	te property:								∦ .	
	gs of cups in place: ntification signs are in pl	lace?								∦ .	
	drip valve is functional/									H .	
Duli	unp vaive is junctionally	not leaking:						•		Ш.	
		ANTI	-FREEZE SYSTE	MS				YES	NO	N/A	Note #
Hav	e all anti-freeze systems									•	
	per signage and placard									✓	
	LOCATION / AREA	A PROTECTED	TEMP	Note #		LOCATION /	AREA PROTECTE	-D		TEMP	Note #
1					3						
2					4						



2760 Beverly Dr. Suite 9 Aurora, IL 60502 630.506.5535 www. allegiant fire.net

FIVE YEAR REQUIREMENTS

Report to: Remedy Medical Properties, Inc. Property: RMP, 8 Salt Creek Ln Address: 8 Salt Creek Lane City: Hinsdale State: Zip:

IL

Date: 07/03/2023 Job Number: 29683797 Technician:

Jon Rocke, Zachary Ross

YES NO N/A Note#

Annual Fire Sprinkler Inspection Report

60521

Have all Check Valves, Pre-action Has the piping in all systems bee System Gauges tested or replace	n checked for obs	structive materials wi		•	rs?				Due 2027 Due 2027 Due 2027
	(CONTROL VALVES				YES	NO	N/A	Note #
All Control Valves in the correct (open or closed) p	position?							
Locked or supervised?									
Easily accessible?									
Free from damage or leaks?									
Proper signage in place?									
Tamper Switches operate proper	·ly?					~			
All Control Valves operated throu	ugh full range and	d return to normal po	sition?						
OS&Y Valves properly lubricated	?								
Description		Туре	Size			Location			Note#
City, Before Backflo	ow .	OS&Y	3"		Sprii	nkler Room			
After Backflow		OS&Y	3"		Sprinkler Room				
1st Floor Riser		Butterfly	2 1/2"		Sprinkler F		nkler Room		
2nd And 3rd Floor R		Butterfly	·			Sprinkler Room			
3rd Floor(Sectiona		Butterfly	2 1/2"		3rd Floor West Stair				
2nd Floor(Sections		Butterfly				nd Floor West Stair			
Elevator Top of Shaft (Se	Butterfly	1"			3rd Floor By Elevator				
Elevator Pit(Section	Butterfly	1" 1st Floor Wa		r Waiting Ro	ng Room				
	(*Any	 y additional control valves	will be listed on a	separate shee	t.)				
MAIN DRAIN				YES	· ,	NO	N/	/ 4	Note#
	MAIN DRAIN AND WATERFLOW TEST RESULTS YES NO N/A main drain test results differ more than 10% from previous test? □ ✓]	Wote #		
			PSI Static						
		Size of Test	Pressure	PSI Resid	dual PS	Pressure	Wate	rflow	
System #	Riser Size	Pipe	Before	Pressu		After	Time		Note #
1st Floor	2 1/2"	1 1/4"	70	55		60	Withi		
2nd & 3rd Floor	3"	1 1/4"	70	55		60	Withi	n 60	
3rd Floor West Stair(Sectional)	2 1/2"	>	>	>		>	Withi	n 60	
2nd Floor West Stair(Sectional)	2 1/2"	>	>	>		>	Withi	n 60	
Elevator Top of Shaft (Sectional)	1"	>	>	>		>	Withi	n 60	
Elevator Pit(Sectional)	1"	>	>	>		>	Withi	n 60	
	/**				. ((()				



2760 Beverly Dr. Suite 9 Aurora, IL 60502 630.506.5535 www.allegiantfire.net Report to: Remedy Medical Properties, Inc.
Property: RMP, 8 Salt Creek Ln
Address: 8 Salt Creek Lane
City: Hinsdale
State: IL Zip: 60521

 Date:
 07/03/2023

 Job Number:
 29683797

Technician:

Jon Rocke, Zachary Ross

Annual Fire Sprinkler Inspection Report

	THE INS	PECTOR SUGGESTS THE FOL	LOWING NECESSARY IMPROVEMENTS:	
Note#	(ti	hese suggestions are not the	result of an engineering survey)	
	MACDIFICA	TIONS OF CORRECTIONS NA	ADE DURING THE INCRECTION.	
	MODIFICA	TIONS OR CORRECTIONS INF	ADE DURING THIS INSPECTION:	
INISDECT	ION 8. SUGGESTED IMPROVEMENTS M	IEDE DISCHISSED WITH THE I	JNDERSIGNED OWNER OR OWNERS REPRESEI	\ITATI\/E+
			place of my inspection, and that all equipment tested now	
	upon completion of this inspection except as note			3
			\cap (1) \perp	
		•	(La Kache	
			C 400 0 . 2 . 4 . 4 . 4	
OWNER	/ REPRESENTATIVE SIGNATURE		INSPECTOR SIGNATURE	
	•			
	Steve Swat	07/03/2023	Jon Rocke, Zachary Ross	151246
PRINT N	AME	DATE	PRINT NAME	NICET #