

S.C. Department of Labor, Licensing and Regulation

P.O.Box 11329 Columbia, SC 29211

803-896-7630 FAX: 803-896-7650

www.llr.state.sc.us

			Ele	evator Repo	rt of Inspecti	on			
Elevator	1002716				Date	2024-01	2024-01-15		
	L	ocatio	on				Owner		
Building Name:	SOUTHEASTERN SPINE INSTITU			ГЕ	Owner Name:	HD MEDICAL PROPERTIES, LLC; REMEDY MEDICA			
Address:	1625 HOSPITAL DRIVE				Address:	1360 TRUXTUN AVE SUITE 201			
	MT PLEASA	NT		29464		N. CHAF	RLESTON	29405	
Lessee/Management Firm						SC			
Firm Name:	SOUTHEASTERN SPINE INSTITUTE								
Address:	1360 TRUX	TUN AV	E SUITE 201						
	N. CHARLES	TON		29405	Contract:	Υ			
	SC				Company:	THYSSE	 NKRUPP ELEVATOF	ł	
Next Inspection 2025-01-15 Type of Unit: 01 Passenger		Year Si 2025-01 beed: 150	•	e: Certificate P Yes Capacity: 04500	Active # of Floors:		Type of Machine: 02 Hydraulic sprinklers in MR:	# of Openings: 1 Are sprinklers in HW: Y	
Front Door Type	: Width:		Close Speed: 5.00	Torque:	Rear Door Type:	Width	: Close Speed	l: Torque:	
	In	spec	tor				Contact		
S.C. Code 41-16-180 Any owner; operator; or management company who fails to correct a violation of any safety standard promulgated pursuant to this chapter after being given written notice by the director of the standard and of the time set for its correction may be assessed a civil penalty of not more than one thousand dollars for each such violation. To request an extension, notify the Department: I hereby certify this is a true report of my inspection. James Wing					Name: Phone Number: Fax Number:	013 7 17 1200			
					Email Address: Signed On:	peoplefirst@lee-associates.com			
					-	gned On: 2024-01-15			
Inspector Signature:					Owner/Management Company Signature:				



Elevator Report of Inspection										
Elevator 100	2716	Date	2024-01-15							
	Violations									
8.6.5.14 - Periodic Testir	ng (Hydraulic) Category 1	CAT 1 test due, last	test 8-2022							
Machine Room [A17.1 8 to be maintained and p	3.6.10.1] - Fire service phase 1 & 2 monthly test log oosted in machine room	Update fire service log.								
Inspection Result										
Inspection Result: Vio										
Inspector comments:										