

# DETECTION

SYSTEMS & SERVICE INC.

## CERTIFICATION / INSPECTION REPORT

SUBSCRIBER		ALARM COMPANY	
Name	Salt Creek Campus 907	DETECTION SYSTEMS & SERVICE, INC.	
Address	907 Elm St	17W725 Butterfield, Suite D	
C-S-Z	Hinsdale, IL	Oakbrook Terrace, IL 60181	
Phone		Phone: (630) 705-9585	

FIRE ALARM CONTROL PANEL											
Manufacturer/model: Notifier NFW2-100						Number of Zones:					
Does panel indicate normal condition:	Y	<input checked="" type="checkbox"/>	N	<input type="checkbox"/>	Does the silence switch operate:	Y	<input checked="" type="checkbox"/>	N	<input type="checkbox"/>		
Are all indicating lights in working order:	Y	<input checked="" type="checkbox"/>	N	<input type="checkbox"/>	Are the batteries Properly charged:	Y	<input checked="" type="checkbox"/>	N	<input type="checkbox"/>		
Does trouble light operate:	Y	<input checked="" type="checkbox"/>	N	<input type="checkbox"/>	Batteries:	Qty: 2	Volt: 12	AH: 18			

FIRE DETECTION INITIATION AND ANNUNCIATION DEVICES											
Device	Qty	Tested	Cleaned	Pass	Fail	Device	Qty	Tested	Cleaned	Pass	Fail
Remote Annun.	1	1		1		Smoke Det. (Photo)	32	32		32	
Audio/Visual	40	40		40		Smoke Det.(Ion)					
Visuals only	23	23		23		Smoke Det. (Duct)	4	4		4	
Bells						Thermal Det. (ROR)					
Waterflow (Paddle)	4	4		4		Thermal Det. (FT)					
Waterflow (Pressure)						Manual Pull Station	8	8		8	
Valve Tamp. (OS&Y)	5	5		5							
Valve Tamp. (PIV)											
NAC Power Expander	3	3		3							

SPRINKLER SYSTEM SUPERVISORY DEVICES							
Main Drain Test	Static Pressure			psi	Residual Pressure (flowing)		psi
	Riser #1	Riser #2	Riser #3	Riser #4	Riser #5	Riser #6	
Waterflow	3rd fl	2nd fl	1st fl	Main			
Delay (secs)	44 sec	45 sec	43 sec	43 sec			

REMOTE MONITORING			
Monitoring Station Type: Central	Transmitter Type: Radio		
Monitoring Performed by: Ducom	Connection Date:		
Phone / Channel numbers used in transmission:			
Did Fire Alarm panel transmit properly for:	Alarm: yes	Trouble: yes	Alarm Trouble Over Ride: yes

**NOTES/COMMENTS**

Inspector name: \_\_\_\_\_ Inspection: \_\_\_\_\_ Pass:  Fail:

DEVIATIONS FROM NFPA72		
INSPECTION		
Inspection performed by: Manuel Godinez	NICET NO 236623	Date: 10-7-2025