

DETECTION

SYSTEMS & SERVICE INC.

CERTIFICATION / INSPECTION REPORT

SUBSCRIBER					ALARM COMPANY						
Name Office park of hinsdale					DETECTION SYSTEMS & SERVICE, INC.						
Address 12 salt creek ln					17W725 Butterfield, Suite D						
C-S-Z Hinsdale, IL					Oakbrook Terrace, IL 60181						
Phone					Phone: (630) 705-9585						
FIRE ALARM CONTROL PANEL											
Manufacturer/model: Vigilant VS4					Number of Zones:						
Does panel indicate normal condition: Y ☒ N ☐					Does the silence switch operate: Y ☒ N ☐						
Are all indicating lights in working order: Y ☒ N ☐					Are the batteries Properly charged: Y ☒ N ☐						
Does trouble light operate: Y ☒ N ☐					Batteries: Qty: 2 Volt: 12 AH: 12						
FIRE DETECTION INITIATION AND ANNUNCIATION DEVICES											
Device	Qty	Tested	Cleaned	Pass	Fail	Device	Qty	Tested	Cleaned	Pass	Fail
Remote Annun.	1	1		1		Smoke Det. (Photo)	153	153	153	153	
Audio/Visual	76	76		76		Smoke Det.(Ion)					
Visuals only	79	79		79		Smoke Det. (Duct)	21	21		21	
Bells	2	2		2		Thermal Det. (ROR)	6	4		4	
Waterflow (Paddle)	8	8		8		Thermal Det. (FT)					
Waterflow (Pressure)						Manual Pull Station	14	14		14	
Valve Tamp. (OS&Y)	10	10		10							
Valve Tamp. (PIV)											
NAC Power Expander	7	7		7							
SPRINKLER SYSTEM SUPERVISORY DEVICES											
Main Drain Test	Static Pressure 70 psi					Residual Pressure (flowing) 60 psi					
Waterflow	Riser #1 4th fl	Riser #2 3rd fl	Riser #3 2nd fl	Riser #4 1st fl	Riser #5 Main	Riser #6 East/west					
Delay (secs)	45	41	35	40	40	39/41					
REMOTE MONITORING											
Monitoring Station Type: Central					Transmitter Type: Radio						
Monitoring Performed by: Ducom					Connection Date:						
Phone / Channel numbers used in transmission:											
Did Fire Alarm panel transmit properly for:		Alarm: yes		Trouble: yes		Alarm Trouble Over Ride: yes					
NOTES/COMMENTS											
Tested dampers and 2nd floor door closures. Tested standpipe waterflow Manually tested ok.											
Inspector name: Inspection: Pass: ☒ Fail: ☐											
DEVIATIONS FROM NFPA72											
INSPECTION											
Inspection performed by: Manuel Godinez					NICET NO 236623		Date: 6-26-2026				