

Fire Alarm and Life Safety System Inspection Certificate

For

Wheaton Office
120 East Liberty Drive
Wheaton, IL 60187

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date
Dec 11, 2020

Building: Wheaton Office
Contact: Nathan Sands
Title: Property Manager



Company: SMG & CAS Security Holdings LLC
Contact: Bill White
Title: Inspector

Executive Summary

Generated by: BuildingReports.com

Building Information		
Building: Wheaton Office	Contact: Nathan Sands	
Address: 120 East Liberty Drive	Phone: 630-230-1221	
Address:	Fax:	
City/State/Zip: Wheaton, IL 60187	Mobile:	
Country: United States of America	Email: nsands@wavelandprop.com	
Inspection Performed By		
Company: SMG & CAS Security Holdings LLC	Inspector: Bill White	
Address: 120 King Street	Phone: 630-417-0231	
Address:	Fax:	
City/State/Zip: Elk Grove Village, Illinois 60007-1111	Mobile:	
Country: United States of America	Email: bill.white@smgsecurity.com	
System Control Unit		
Manufacturer: Silent Knight	Inspection Date: 12/11/2020	IDC Style:
Model Number: IFP-1000	Install Date: 09/18/2014	SLC Style:
Software Version:	Version Date: 09/18/2014	NAC Style: Y
Location: Pump Room	Current Protection: Breaker	
Monitoring		
Company: DuCom	Phone: 6306908245	Account #: 6339
Central Station Signal Verification		
Type:	Mfg:	Model #:
Test Time/Date:	Restore Time	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	25	18.80%	25	100.00%	25	100.00%	0	0%
Initiating	84	63.16%	84	100.00%	84	100.00%	0	0%
Supervisory	23	17.29%	23	100.00%	23	100.00%	0	0%
Indicating	1	0.75%	1	100.00%	1	100.00%	0	0%
Totals	133	100%	133	100.00%	133	100.00%	0	0%

Certification	
Company: SMG & CAS Security Holdings LLC	Building: Wheaton Office
Inspector: Bill White	Contact: Nathan Sands
	
Signed: Dec 11, 2020 8:58:29 AM	Signed: Dec 11, 2020 8:58:46 AM

Bill White Certifications	
Certification Type	Number
NICET Fire Alarm Systems Level I	135377

Inspection & Testing

Generated by: BuildingReports.com

Device Type	Location	Service	Time	Date
Building: Wheaton Office		Control Panel: 1 - Silent Knight IFP-1000		
<i>The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.</i>				
<i>Passed</i>				
Control				
Annunciator	North Main Entrance	Tested	7:37:08 AM	12/11/2020
Battery	2nd MPOP Room	Tested	7:40:15 AM	12/11/2020
Battery	2nd MPOP Room	Tested	7:40:19 AM	12/11/2020
Battery	4th MPOP Room	Tested	7:25:19 AM	12/11/2020
Battery	4th MPOP Room	Tested	7:25:22 AM	12/11/2020
Battery	4th MPOP Room	Tested	7:25:26 AM	12/11/2020
Battery	4th MPOP Room	Tested	7:25:29 AM	12/11/2020
Battery	4th MPOP Room	Tested	7:25:36 AM	12/11/2020
Battery	4th MPOP Room	Tested	7:25:39 AM	12/11/2020
Battery	4th MPOP Room	Tested	7:26:03 AM	12/11/2020
Battery	4th MPOP Room	Tested	7:26:07 AM	12/11/2020
Battery	Suite 190 FCPS Room	Tested	6:42:34 AM	12/11/2020
Battery	Suite 190 FCPS	Tested	6:42:01 AM	12/11/2020
Battery	FACP Pump Room	Tested	7:25:13 AM	12/11/2020
Battery	FACP Pump Room	Tested	7:25:16 AM	12/11/2020
Battery	FCPS Pump Room	Tested	7:40:22 AM	12/11/2020
Battery	FCPS Pump Room	Tested	7:40:25 AM	12/11/2020
Control Panel	Pump Room	Tested	7:00:03 AM	12/11/2020
Power Supply	2nd MPOP Room	Tested	7:39:39 AM	12/11/2020
Power Supply	4th MPOP Room	Tested	7:59:26 AM	12/11/2020
Power Supply	4th MPOP Room	Tested	7:59:30 AM	12/11/2020
Power Supply	4th MPOP Room	Tested	7:59:33 AM	12/11/2020
Power Supply	4th MPOP Room	Tested	7:59:37 AM	12/11/2020
Power Supply	Suite 190 Kitchen	Tested	6:41:03 AM	12/11/2020
Power Supply	Pump Room	Tested	7:59:23 AM	12/11/2020
Indicating				
Horn/Strobe	Horns Strobes Test Good 12-11-2020	Tested	7:59:00 AM	12/11/2020
Initiating				
Duct Detector	1st East Office	Tested	7:57:58 AM	12/11/2020
Duct Detector	2nd East Office Activ IT Closet	Tested	7:49:15 AM	12/11/2020
Duct Detector	2nd West Office Electrical closet	Tested	7:46:04 AM	12/11/2020
Duct Detector	3rd East Office Hallway	Tested	7:57:55 AM	12/11/2020
Duct Detector	3rd West Office	Tested	7:32:24 AM	12/11/2020
Duct Detector	4th East Office South	Tested	7:28:43 AM	12/11/2020
Duct Detector	4th West Office	Tested	7:23:30 AM	12/11/2020
Duct Detector	5th North IT Lab	Tested	7:21:49 AM	12/11/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Duct Detector	5th West Office	Tested	7:17:00 AM	12/11/2020
Duct Detector	Suite 190 Sushi Beverage Area	Tested	7:41:26 AM	12/11/2020
Duct Detector	Suite 190 Sushi Beverage Area	Tested	7:41:32 AM	12/11/2020
Duct Detector	Suite 190 Sushi Kitchen	Tested	7:41:29 AM	12/11/2020
Heat Detector	1st Main Electrical Room	Tested	7:58:50 AM	12/11/2020
Heat Detector	1st Main Electrical Room	Tested	7:58:54 AM	12/11/2020
Heat Detector	1st MPOP Room	Tested	7:58:47 AM	12/11/2020
Heat Detector	1st Electrical Room	Tested	7:58:57 AM	12/11/2020
Heat Detector	2nd Electrical Room	Tested	7:58:30 AM	12/11/2020
Heat Detector	2nd MPOP Room	Tested	7:58:26 AM	12/11/2020
Heat Detector	3rd Electrical Room	Tested	7:58:44 AM	12/11/2020
Heat Detector	3rd MPOP Room	Tested	7:58:41 AM	12/11/2020
Heat Detector	4th Electrical Room	Tested	7:58:37 AM	12/11/2020
Heat Detector	4th MPOP Room	Tested	7:58:34 AM	12/11/2020
Heat Detector	5th Electrical Room	Tested	7:58:16 AM	12/11/2020
Heat Detector	5th Elevator Room	Tested	7:58:07 AM	12/11/2020
Heat Detector	5th Elevator Room	Tested	7:58:13 AM	12/11/2020
Heat Detector	5th MPOP Room	Tested	7:58:19 AM	12/11/2020
Heat Detector	5th Shaft	Tested	7:36:12 AM	12/11/2020
Heat Detector	LL Pit	Tested	7:36:15 AM	12/11/2020
Heat Detector	LL Pit	Tested	7:36:19 AM	12/11/2020
Heat Detector	LL Pit	Tested	7:36:22 AM	12/11/2020
Heat Detector	Garage Electrical Room	Tested	7:58:23 AM	12/11/2020
Pull Station	1st Center Lobby	Tested	6:59:17 AM	12/11/2020
Pull Station	1st East Lobby	Tested	7:59:51 AM	12/11/2020
Pull Station	1st North Vestibule	Tested	7:59:44 AM	12/11/2020
Pull Station	1st South Vestibule	Tested	7:59:55 AM	12/11/2020
Pull Station	2nd East Stairs	Tested	7:44:19 AM	12/11/2020
Pull Station	2nd West Stairs	Tested	7:41:07 AM	12/11/2020
Pull Station	3rd East Stairs	Tested	7:59:47 AM	12/11/2020
Pull Station	3rd West Stairs	Tested	7:33:06 AM	12/11/2020
Pull Station	4th West Stairs	Tested	7:24:13 AM	12/11/2020
Pull Station	5th East Stairs	Tested	7:59:40 AM	12/11/2020
Pull Station	5th West Stairs	Tested	7:17:36 AM	12/11/2020
Pull Station	LL East Stairs	Tested	7:51:47 AM	12/11/2020
Pull Station	LL West Stairs	Tested	7:54:28 AM	12/11/2020
Pull Station	Suite 100 North Exit	Tested	8:00:03 AM	12/11/2020
Pull Station	Suite 140 Main Entrance	Tested	8:00:07 AM	12/11/2020
Pull Station	Suite 190 North Exit	Tested	8:00:10 AM	12/11/2020
Pull Station	Suite 190 North Main Entrance	Tested	8:00:15 AM	12/11/2020
Pull Station	Suite 190 West Dining Room Exit	Tested	8:00:18 AM	12/11/2020
Pull Station	Suite 190 West Kitchen Exit	Tested	8:00:22 AM	12/11/2020
Pull Station	Pump Room	Tested	7:59:59 AM	12/11/2020
Smoke Detector	1st Main Electrical Room	Tested/Cleaned	8:01:36 AM	12/11/2020
Smoke Detector	1st Main Electrical Room	Tested/Cleaned	8:01:41 AM	12/11/2020
Smoke Detector	1st Maintenance Elevator Lobby	Tested/Cleaned	8:01:56 AM	12/11/2020
Smoke Detector	1st MPOP Room	Tested/Cleaned	8:01:48 AM	12/11/2020
Smoke Detector	1st Electrical Room	Tested/Cleaned	8:01:44 AM	12/11/2020
Smoke Detector	1st Elevator Lobby	Tested/Cleaned	8:01:33 AM	12/11/2020
Smoke Detector	2nd Electrical Room	Tested/Cleaned	8:01:05 AM	12/11/2020

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd Elevator Lobby	Tested/Cleaned	8:01:08 AM	12/11/2020
Smoke Detector	2nd MPOP Room	Tested/Cleaned	8:01:52 AM	12/11/2020
Smoke Detector	3rd Electrical Room	Tested/Cleaned	8:01:29 AM	12/11/2020
Smoke Detector	3rd Elevator Lobby	Tested/Cleaned	8:01:12 AM	12/11/2020
Smoke Detector	3rd MPOP Room	Tested/Cleaned	8:01:15 AM	12/11/2020
Smoke Detector	4th Electrical Room	Tested/Cleaned	8:01:22 AM	12/11/2020
Smoke Detector	4th Elevator Lobby	Tested/Cleaned	8:01:18 AM	12/11/2020
Smoke Detector	4th MPOP Room	Tested/Cleaned	8:01:26 AM	12/11/2020
Smoke Detector	5th Electrical Room	Tested/Cleaned	8:00:48 AM	12/11/2020
Smoke Detector	5th Elevator Lobby	Tested/Cleaned	8:00:51 AM	12/11/2020
Smoke Detector	5th Elevator Room	Tested/Cleaned	8:00:40 AM	12/11/2020
Smoke Detector	5th Elevator Room	Tested/Cleaned	8:00:44 AM	12/11/2020
Smoke Detector	5th MPOP Room	Tested/Cleaned	8:00:55 AM	12/11/2020
Smoke Detector	5th Shaft	Tested/Cleaned	8:00:26 AM	12/11/2020
Smoke Detector	5th Shaft	Tested/Cleaned	8:00:30 AM	12/11/2020
Smoke Detector	LL Pit	Tested/Cleaned	8:00:33 AM	12/11/2020
Smoke Detector	LL Pit	Tested/Cleaned	8:00:37 AM	12/11/2020
Smoke Detector	Garage Electrical Room	Tested/Cleaned	8:00:58 AM	12/11/2020
Smoke Detector	Garage Elevator Lobby	Tested/Cleaned	8:01:02 AM	12/11/2020
Waterflow Switch	2nd East Stairs	Tested	8:04:12 AM	12/11/2020
Waterflow Switch	3rd East Stairs	Tested	8:04:09 AM	12/11/2020
Waterflow Switch	4th East Stairs	Tested	8:04:05 AM	12/11/2020
Waterflow Switch	5th East Stairs	Tested	8:04:02 AM	12/11/2020
Waterflow Switch	LL East Stairs	Tested	8:04:16 AM	12/11/2020
Waterflow Switch	Pump Room	Tested	8:03:54 AM	12/11/2020
Waterflow Switch	Pump Room	Tested	8:03:58 AM	12/11/2020
Supervisory				
Fire Pump Power	Pump Room	Tested	7:58:01 AM	12/11/2020
Fire Pump Trouble	4th East Stairs	Tested	7:29:21 AM	12/11/2020
Tamper Switch	1st West Stairs	Tested	8:03:43 AM	12/11/2020
Tamper Switch	2nd East Stairs	Tested	8:03:51 AM	12/11/2020
Tamper Switch	3rd East Stairs	Tested	8:03:36 AM	12/11/2020
Tamper Switch	4th East Stairs	Tested	8:03:29 AM	12/11/2020
Tamper Switch	5th East Stairs	Tested	8:03:32 AM	12/11/2020
Tamper Switch	LL East Stairs	Tested	8:03:47 AM	12/11/2020
Tamper Switch	Maintenance Garage Elevator Sticker On Outlet	Tested	8:03:22 AM	12/11/2020
Tamper Switch	Garage Elevator	Tested	8:03:15 AM	12/11/2020
Tamper Switch	Garage Elevator	Tested	8:03:18 AM	12/11/2020
Tamper Switch	Pump Room CLOSED	Tested	8:03:05 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:02:42 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:02:46 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:02:49 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:02:52 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:02:55 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:02:59 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:03:02 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:03:08 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:03:12 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:03:26 AM	12/11/2020
Tamper Switch	Pump Room	Tested	8:03:40 AM	12/11/2020

Service Summary

Generated by: BuildingReports.com

Building: Wheaton Office

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<i>Passed</i>		
Annunciator	Tested	1
Battery	Tested	16
Control Panel	Tested	1
Duct Detector	Tested	12
Fire Pump Power	Tested	1
Fire Pump Trouble	Tested	1
Heat Detector	Tested	19
Horn/Strobe	Tested	1
Power Supply	Tested	7
Pull Station	Tested	20
Smoke Detector	Tested/Cleaned	26
Tamper Switch	Tested	21
Waterflow Switch	Tested	7
Total		133
Grand Total		133

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Wheaton Office **Control Panel: 1 - Silent Knight IFP-1000**

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type	Category	% of Inventory	Quantity
Power Supply	Control	5.26%	7
Battery	Control	12.03%	16
Pull Station	Initiating	15.04%	20
Control Panel	Control	0.75%	1
Duct Detector	Initiating	9.02%	12
Fire Pump Trouble	Supervisory	0.75%	1
Heat Detector	Initiating	14.29%	19
Annunciator	Control	0.75%	1
Fire Pump Power	Supervisory	0.75%	1
Horn/Strobe	Indicating	0.75%	1
Smoke Detector	Initiating	19.55%	26
Tamper Switch	Supervisory	15.79%	21
Waterflow Switch	Initiating	5.26%	7

Type	Qty	Model #	Description	Install Date
<i>New (under 90 days)</i>				
Horn/Strobe	1			12/11/2020
<i>In Service - 90 Days - 1 Year</i>				
DuraCell				
Battery	2	Dura12-8F	Sealed Lead Acid	01/11/2020
<i>In Service - 2 Years to 3 Years</i>				
Duracell				
Battery	2	Dura12-8F	Sealed Lead Acid	05/29/2018
Power Patrol				
Battery	2	SLA1075	Sealed Lead Acid	05/18/2018
<i>In Service - 5 Years to 10 Years</i>				
Master				
Fire Pump Power	1	MCA-50-46-HX		09/18/2014
Milwaukee				
Tamper Switch	2	BSB-SCSO		09/18/2014
Potter Electric				
Tamper Switch	3	OSYSU-2		09/18/2014
Waterflow Switch	2	VSR-F		09/18/2014
Power Patrol				
Battery	8	SLA1075	Sealed Lead Acid	09/18/2014
Silent Knight				

Control Panel	1	IFP-1000		09/18/2014
Fire Pump Trouble	1	PS-DA		09/18/2014
Heat Detector	17	SD505-HT		09/18/2014
Heat Detector	2	SD505-HT	Fixed Temperature	09/18/2014
Power Supply	7	5499		09/18/2014
Pull Station	20	PS-DA	Dual Action	09/18/2014
Smoke Detector	26	SD505-APS	Photoelectric	09/18/2014
System Sensor				
Duct Detector	8	RTS451	Photoelectric	09/18/2014
Duct Detector	4	RTS451KEY	Photoelectric	09/18/2014
Waterflow Switch	5	WFD25		09/18/2014
Victaulic				
Tamper Switch	1	705		09/18/2014
Tamper Switch	13	705W		09/18/2014
Tamper Switch	2	728		09/18/2014
Interstate				
Battery	2	BSL1116	Sealed Lead Acid	06/24/2014
Silent Knight				
Annunciator	1	RA-100	LED List	04/18/2014

Zone Address Report

Generated by: BuildingReports.com

Building: Wheaton Office	Control Panel: 1 - Silent Knight IFP-1000
--------------------------	--

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
Zone/Circuit: M				
01	Waterflow Switch	Pump Room		30565189
01	Pull Station	Suite 100 North Exit	Dual Action	39732916
02	Waterflow Switch	Pump Room		30565190
02	Pull Station	Suite 140 Main Entrance	Dual Action	39732917
03	Fire Pump Power	Pump Room		32703771
03	Tamper Switch	Pump Room		30565184
03	Tamper Switch	Pump Room		30565185
03	Tamper Switch	Pump Room		30565186
04	Tamper Switch	Pump Room		30565172
04	Tamper Switch	Pump Room		30565173
05	Tamper Switch	Pump Room		30565176
05	Tamper Switch	Pump Room		30565178
05	Tamper Switch	Pump Room		30565179
05	Tamper Switch	Pump Room		30565180
05	Tamper Switch	Pump Room		30565182
05	Tamper Switch	Pump Room		30565183
05	Tamper Switch	Pump Room CLOSED		30565181
06	Pull Station	1st East Lobby	Dual Action	32703913
09	Pull Station	Pump Room	Dual Action	32703915
10	Smoke Detector	1st Main Electrical Room	Photoelectric	32703997
11	Heat Detector	1st Main Electrical Room		32703998
12	Pull Station	1st South Vestibule	Dual Action	32703914
13	Pull Station	1st Center Lobby	Dual Action	32703912
14	Heat Detector	1st Main Electrical Room		32703999
15	Smoke Detector	1st Main Electrical Room	Photoelectric	32704000
16	Smoke Detector	1st Maintenance Elevator Lobby	Photoelectric	32704001
17	Smoke Detector	1st Electrical Room	Photoelectric	32704003
18	Heat Detector	1st Electrical Room		32704002
19	Smoke Detector	1st Elevator Lobby	Photoelectric	32703986
22	Smoke Detector	1st MPOP Room	Photoelectric	32703996
23	Heat Detector	1st MPOP Room		32703995
24	Heat Detector	Garage Electrical Room	Fixed Temperature	32703970
25	Smoke Detector	Garage Electrical Room	Photoelectric	32703969
26	Heat Detector	LL Pit		32703779
27	Smoke Detector	LL Pit	Photoelectric	32703783
28	Smoke Detector	Garage Elevator Lobby	Photoelectric	32703971
31	Smoke Detector	LL Pit	Photoelectric	32703782
32	Heat Detector	LL Pit		32703778
34	Heat Detector	LL Pit		32703777

35	Pull Station	LL West Stairs	Dual Action	32703911
36	Pull Station	LL East Stairs	Dual Action	32703910
37	Pull Station	2nd East Stairs	Dual Action	32703909
38	Duct Detector	1st East Office	Photoelectric	32703898
39	Duct Detector	2nd East Office Activ IT Closet	Photoelectric	32703897
40	Smoke Detector	2nd Electrical Room	Photoelectric	32703974
41	Heat Detector	2nd Electrical Room		32703973
42	Smoke Detector	2nd Elevator Lobby	Photoelectric	32703975
45	Heat Detector	2nd MPOP Room		32703972
46	Smoke Detector	2nd MPOP Room	Photoelectric	32703994
47	Pull Station	2nd West Stairs	Dual Action	32703908
49	Duct Detector	2nd West Office Electrical closet	Photoelectric	32703895
50	Pull Station	3rd East Stairs	Dual Action	32703905
51	Tamper Switch	1st West Stairs		32703775
51	Tamper Switch	Maintenance Garage Elevator Sticker On Outlet		32703774
52	Duct Detector	3rd East Office Hallway	Photoelectric	32703894
53	Heat Detector	3rd Electrical Room		32703988
54	Smoke Detector	3rd Electrical Room	Photoelectric	32703989
55	Smoke Detector	3rd Elevator Lobby	Photoelectric	32703990
56	Pull Station	Suite 190 West Dining Room Exit	Dual Action	39732920
57	Pull Station	Suite 190 West Kitchen Exit	Dual Action	39732921
58	Heat Detector	3rd MPOP Room		32703987
59	Smoke Detector	3rd MPOP Room	Photoelectric	32703984
60	Pull Station	3rd West Stairs	Dual Action	32703904
61	Pull Station	1st North Vestibule	Dual Action	32703903
62	Duct Detector	3rd West Office	Photoelectric	32703893
63	Fire Pump Trouble	4th East Stairs		32703902
65	Duct Detector	4th East Office South	Photoelectric	32703892
66	Heat Detector	4th Electrical Room		32703981
67	Smoke Detector	4th Electrical Room	Photoelectric	32703982
68	Smoke Detector	4th Elevator Lobby	Photoelectric	32703983
70	Duct Detector	Suite 190 Sushi Beverage Area	Photoelectric	32703966
71	Heat Detector	4th MPOP Room		32703976
72	Smoke Detector	4th MPOP Room	Photoelectric	32703977
73	Pull Station	4th West Stairs	Dual Action	32703901
75	Duct Detector	4th West Office	Photoelectric	32703891
76	Pull Station	5th East Stairs	Dual Action	32703900
78	Duct Detector	5th North IT Lab	Photoelectric	32703890
80	Heat Detector	5th Electrical Room		32703856
81	Smoke Detector	5th Electrical Room	Photoelectric	32703857
82	Heat Detector	5th Shaft		32703776
83	Smoke Detector	5th Shaft	Photoelectric	32703781
84	Heat Detector	5th Elevator Room		32703855
85	Smoke Detector	5th Elevator Room	Photoelectric	32703854
86	Smoke Detector	5th Elevator Lobby	Photoelectric	32703858
87	Duct Detector	Suite 190 Sushi Beverage Area	Photoelectric	32703968
88	Duct Detector	Suite 190 Sushi Kitchen	Photoelectric	32703967
90	Smoke Detector	5th Shaft	Photoelectric	32703780
92	Pull Station	Suite 190 North Main Entrance	Dual Action	39732919
93	Heat Detector	5th Elevator Room		32703852
94	Smoke Detector	5th Elevator Room	Photoelectric	32703853
95	Heat Detector	5th MPOP Room	Fixed Temperature	32703873

96	Smoke Detector	5th MPOP Room	Photoelectric	32703872
97	Pull Station	5th West Stairs	Dual Action	32703899
98	Pull Station	Suite 190 North Exit	Dual Action	39732918
99	Duct Detector	5th West Office	Photoelectric	32703889
103	Waterflow Switch	2nd East Stairs		32703866
104	Tamper Switch	2nd East Stairs		32703865
105	Waterflow Switch	3rd East Stairs		32703863
106	Tamper Switch	3rd East Stairs		32703864
107	Waterflow Switch	4th East Stairs		32703862
108	Tamper Switch	4th East Stairs		32703861
109	Waterflow Switch	5th East Stairs		32703860
110	Tamper Switch	5th East Stairs		32703859
123	Tamper Switch	Garage Elevator		32703772
124	Tamper Switch	Garage Elevator		32703773
125	Waterflow Switch	LL East Stairs		32703867
126	Tamper Switch	LL East Stairs		32703868