Fire Alarm and Life Safety System Inspection Certificate

For

Wheaton Office 120 East Liberty Drive Wheaton, IL 60187

Tested to NFPA 72 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Inspection Date Dec 10, 2021

> Building: Wheaton Office Contact: Nathan Sands Title: Property Manager

Company: SMG & CAS Security Holdings LLC
Contact: Bill White
Title: Inspector

Executive Summary

Generated by: BuildingReports.com

Building Information

Building: Wheaton Office Contact: Nathan Sands Address: 120 East Liberty Drive Phone: 630-230-1221

Address: Fax: City/State/Zip: Wheaton, IL 60187 Mobile:

Country: United States of America Email: nsands@wavelandprop.com

Inspection Performed By

Company: SMG & CAS Security Holdings LLC **Inspector:** Bill White Address: 120 King Street Phone: 630-417-0231

Address: Fax:

City/State/Zip: Elk Grove Village, Illinois

Mobile: 60007-1111

Country: United States of America Email: bill.white@smgsecurity.com

System Control Unit

Manufacturer: Silent Knight Inspection Date: 12/10/2021 IDC Style: Model Number: IFP-1000 Install Date: 09/18/2014 SLC Style: NAC Style: Y Software Version: Version Date: 09/18/2014

Location: Pump Room **Current Protection: Breaker**

Monitoring

Company: DuCom **Phone:** 6306908245 Account #: 6339

Inspection Summary								
Catagony	Total	Items	Serv	riced	Pas	sed	Failed	/Other
Category	Qty	%	Qty	%	Qty	%	Qty	%
Control	25	18.80%	25	100.00%	25	100.00%	0	0.00%
Indicating	1	0.75%	1	100.00%	1	100.00%	0	0.00%
Initiating	84	63.16%	84	100.00%	84	100.00%	0	0.00%
Supervisory	23	17.29%	23	100.00%	23	100.00%	0	0.00%
Totals	133	100%	133	100.00%	133	100.00%	0	0.00%

Certification

Company: SMG & CAS Security Holdings LLC

Inspector: Bill White

Signed: Dec 10, 2021

Building: Wheaton Office **Contact:** Nathan Sands

Signed: Dec 10, 2021

Inspection & Testing

Generated by: BuildingReports.com

Building: Wheaton Office

Control Panel: 1 - Silent Knight IFP-1000

Download Date: 12/21/2021

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date		
Passed						
Control						
Annunciator	North Main Entrance	Tested	7:11:14 AM	12/10/2021		
Battery	2nd MPOP Room	Tested	9:35:14 AM	12/10/2021		
Battery	2nd MPOP Room	Tested	9:35:17 AM	12/10/2021		
Battery	4th MPOP Room	Tested	9:24:44 AM	12/10/2021		
Battery	4th MPOP Room	Tested	9:24:49 AM	12/10/2021		
Battery	4th MPOP Room	Tested	9:24:53 AM	12/10/2021		
Battery	4th MPOP Room	Tested	9:25:01 AM	12/10/2021		
Battery	4th MPOP Room	Tested	9:25:10 AM	12/10/2021		
Battery	4th MPOP Room	Tested	9:25:13 AM	12/10/2021		
Battery	4th MPOP Room	Tested	9:25:16 AM	12/10/2021		
Battery	4th MPOP Room	Tested	9:25:19 AM	12/10/2021		
Battery	FACP Pump Room	Tested	6:44:32 AM	12/10/2021		
Battery	FACP Pump Room	Tested	6:44:35 AM	12/10/2021		
Battery	FCPS Pump Room	Tested	6:44:09 AM	12/10/2021		
Battery	FCPS Pump Room	Tested	6:44:12 AM	12/10/2021		
Battery	Suite 190 FCPS	Tested	8:07:15 AM	12/10/2021		
Battery	Suite 190 FCPS Room	Tested	8:07:11 AM	12/10/2021		
Control Panel	Pump Room	Tested	6:43:43 AM	12/10/2021		
Power Supply	2nd MPOP Room	Tested	9:35:21 AM	12/10/2021		
Power Supply	4th MPOP Room	Tested	9:24:21 AM	12/10/2021		
Power Supply	4th MPOP Room	Tested	9:24:24 AM	12/10/2021		
Power Supply	4th MPOP Room	Tested	9:24:28 AM	12/10/2021		
Power Supply	4th MPOP Room	Tested	9:24:35 AM	12/10/2021		
Power Supply	Pump Room	Tested	6:44:06 AM	12/10/2021		
Power Supply	Suite 190 Kitchen	Tested	8:07:44 AM	12/10/2021		
Indicating						
Horn/Strobe	Horns Strobes Test Good 12-10-2021	Tested	6:43:47 AM	12/10/2021		
Initiating						
Duct Detector	1st East Office	Tested	7:53:48 AM	12/10/2021		
Duct Detector	2nd East Office Activ IT Closet	Tested	7:52:23 AM	12/10/2021		
Duct Detector	2nd West Office Electrical closet	Tested	7:50:56 AM	12/10/2021		
Duct Detector	3rd East Office Hallway	Tested	7:45:55 AM	12/10/2021		
Duct Detector	3rd West Office	Tested	7:47:11 AM	12/10/2021		
Duct Detector	4th East Office South	Tested	7:44:18 AM	12/10/2021		
Duct Detector	4th West Office	Tested	7:43:18 AM	12/10/2021		
Duct Detector	5th North IT Lab	Tested	7:41:09 AM	12/10/2021		

Device Type	Location	Service	Time	Date
	Passed			
Duct Detector	5th West Office	Tested	7:40:12 AM	12/10/2021
Duct Detector	Suite 190 Sushi Beverage Area	Tested	7:02:55 AM	12/10/2021
Duct Detector	Suite 190 Sushi Beverage Area	Tested	7:03:03 AM	12/10/2021
Duct Detector	Suite 190 Sushi Kitchen	Tested	7:47:22 AM	12/10/2021
Heat Detector	1st Electrical Room	Tested	8:52:13 AM	12/10/2021
Heat Detector	1st MPOP Room	Tested	8:57:22 AM	12/10/2021
Heat Detector	1st Main Electrical Room	Tested	8:52:16 AM	12/10/2021
Heat Detector	1st Main Electrical Room	Tested	8:52:19 AM	12/10/2021
Heat Detector	2nd Electrical Room	Tested	9:33:23 AM	12/10/2021
Heat Detector	2nd MPOP Room	Tested	9:35:28 AM	12/10/2021
Heat Detector	3rd Electrical Room	Tested	9:28:52 AM	12/10/2021
Heat Detector	3rd MPOP Room	Tested	9:31:01 AM	12/10/2021
Heat Detector	4th Electrical Room	Tested	9:21:09 AM	12/10/2021
Heat Detector	4th MPOP Room	Tested	9:24:40 AM	12/10/2021
Heat Detector	5th Electrical Room	Tested	9:04:13 AM	12/10/2021
Heat Detector	5th Elevator Room	Tested	9:04:06 AM	12/10/2021
Heat Detector	5th Elevator Room	Tested	9:04:09 AM	12/10/2021
Heat Detector	5th MPOP Room	Tested	9:05:17 AM	12/10/2021
Heat Detector	5th Shaft	Tested	6:42:59 AM	12/10/2021
Heat Detector	Garage Electrical Room	Tested	9:55:07 AM	12/10/2021
Heat Detector	LL Pit	Tested	6:42:38 AM	12/10/2021
Heat Detector	LL Pit	Tested	6:42:51 AM	12/10/2021
Heat Detector	LL Pit	Tested	6:42:55 AM	12/10/2021
Pull Station	1st Center Lobby	Tested	7:09:46 AM	12/10/2021
Pull Station	1st East Lobby	Tested	6:53:57 AM	12/10/2021
Pull Station	1st North Vestibule	Tested	7:11:03 AM	12/10/2021
Pull Station	1st South Vestibule	Tested	7:10:28 AM	12/10/2021
Pull Station	2nd East Stairs	Tested	7:49:00 AM	12/10/2021
Pull Station	2nd West Stairs	Tested	7:50:00 AM	12/10/2021
Pull Station	3rd East Stairs	Tested	7:45:33 AM	12/10/2021
Pull Station	3rd West Stairs	Tested	7:46:44 AM	12/10/2021
Pull Station	4th West Stairs	Tested	7:42:54 AM	12/10/2021
Pull Station	5th East Stairs	Tested	7:38:36 AM	12/10/2021
Pull Station	5th West Stairs	Tested	7:39:47 AM	12/10/2021
Pull Station	Pump Room	Tested	6:51:29 AM	12/10/2021
Pull Station	LL East Stairs	Tested	6:54:48 AM	12/10/2021
Pull Station	LL West Stairs	Tested	6:55:52 AM	12/10/2021
Pull Station	Suite 100 North Exit	Tested	6:59:35 AM	12/10/2021
Pull Station	Suite 140 Main Entrance	Tested	6:53:23 AM	12/10/2021
Pull Station	Suite 190 North Exit	Tested	7:06:13 AM	12/10/2021
Pull Station	Suite 190 North Main Entrance	Tested	7:02:29 AM	12/10/2021
Pull Station	Suite 190 West Dining Room Exit	Tested	7:05:24 AM	12/10/2021
Pull Station	Suite 190 West Kitchen Exit	Tested	7:04:10 AM	12/10/2021
Smoke Detector	1st Electrical Room	Tested/Cleaned	8:52:02 AM	12/10/2021
Smoke Detector	1st Elevator Lobby	Tested/Cleaned	7:59:07 AM	12/10/2021
Smoke Detector	1st MPOP Room	Tested/Cleaned	8:57:15 AM	12/10/2021
Smoke Detector	1st Main Electrical Room	Tested/Cleaned	8:52:07 AM	12/10/2021
Smoke Detector	1st Main Electrical Room	Tested/Cleaned	8:57:12 AM	12/10/2021
Smoke Detector	1st Maintenance Elevator Lobby	Tested/Cleaned	7:59:01 AM	12/10/2021
Smoke Detector	2nd Electrical Room	Tested/Cleaned	9:33:20 AM	12/10/2021

Device Type	Location	Service	Time	Date
	Passed		<u>'</u>	
Smoke Detector	2nd Elevator Lobby	Tested/Cleaned	8:04:37 AM	12/10/2021
Smoke Detector	2nd MPOP Room	Tested/Cleaned	9:35:25 AM	12/10/2021
Smoke Detector	3rd Electrical Room	Tested/Cleaned	9:28:56 AM	12/10/2021
Smoke Detector	3rd Elevator Lobby	Tested/Cleaned	8:03:36 AM	12/10/2021
Smoke Detector	3rd MPOP Room	Tested/Cleaned	9:31:09 AM	12/10/2021
Smoke Detector	4th Electrical Room	Tested/Cleaned	9:21:28 AM	12/10/2021
Smoke Detector	4th Elevator Lobby	Tested/Cleaned	8:02:33 AM	12/10/2021
Smoke Detector	4th MPOP Room	Tested/Cleaned	9:25:36 AM	12/10/2021
Smoke Detector	5th Electrical Room	Tested/Cleaned	9:03:37 AM	12/10/2021
Smoke Detector	5th Elevator Lobby	Tested/Cleaned	8:01:33 AM	12/10/2021
Smoke Detector	5th Elevator Room	Tested/Cleaned	9:03:50 AM	12/10/2021
Smoke Detector	5th Elevator Room	Tested/Cleaned	9:03:54 AM	12/10/2021
Smoke Detector	5th MPOP Room	Tested/Cleaned	9:07:33 AM	12/10/2021
Smoke Detector	5th Shaft	Tested/Cleaned	6:43:03 AM	12/10/2021
Smoke Detector	5th Shaft	Tested/Cleaned	6:43:09 AM	12/10/2021
Smoke Detector	Garage Electrical Room	Tested/Cleaned	9:55:10 AM	12/10/2021
Smoke Detector	Garage Elevator Lobby	Tested/Cleaned	8:06:06 AM	12/10/2021
Smoke Detector	LL Pit	Tested/Cleaned	6:42:43 AM	12/10/2021
Smoke Detector	LL Pit	Tested/Cleaned	6:42:47 AM	12/10/2021
Waterflow Switch	2nd East Stairs	Tested	7:49:10 AM	12/10/2021
Waterflow Switch	3rd East Stairs	Tested	7:45:09 AM	12/10/2021
Waterflow Switch	4th East Stairs	Tested	7:44:41 AM	12/10/2021
Waterflow Switch	5th East Stairs	Tested	7:38:57 AM	12/10/2021
Waterflow Switch	Pump Room	Tested	7:34:12 AM	12/10/2021
Waterflow Switch	Pump Room	Tested	7:34:18 AM	12/10/2021
Waterflow Switch	LL East Stairs	Tested	7:53:12 AM	12/10/2021
Supervisory				/ /
Fire Pump Power	Pump Room	Tested	7:33:24 AM	12/10/2021
Fire Pump Trouble	4th East Stairs	Tested	7:44:31 AM	12/10/2021
Tamper Switch	1st West Stairs	Tested	7:53:26 AM	12/10/2021
Tamper Switch	2nd East Stairs	Tested	7:49:14 AM	12/10/2021
Tamper Switch	3rd East Stairs	Tested	7:45:12 AM	12/10/2021
Tamper Switch	4th East Stairs	Tested	7:44:44 AM	12/10/2021
Tamper Switch	5th East Stairs	Tested	7:39:01 AM	12/10/2021
Tamper Switch	Garage Elevator	Tested	7:53:15 AM	12/10/2021
Tamper Switch	Garage Elevator	Tested	7:53:19 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:33:36 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:33:41 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:33:47 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:33:51 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:33:56 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:34:57 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:35:02 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:35:02 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:35:09 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:35:12 AM	12/10/2021
Tamper Switch	Pump Room	Tested	7:35:12 AM	12/10/2021
Tamper Switch	Pump Room CLOSED	Tested	7:35:17 AM	12/10/2021
Tamper Switch	Maintenance Garage Elevator Sticker On Outlet	Tested	7:53:22 AM	12/10/2021
Tamper Switch	LL East Stairs	Tested	7:53:38 AM	12/10/2021

Service Summary

Generated by: BuildingReports.com

Building: Wheaton Office

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
	Passed	
Annunciator	Tested	1
Battery	Tested	16
Control Panel	Tested	1
Duct Detector	Tested	12
Fire Pump Power	Tested	1
Fire Pump Trouble	Tested	1
Heat Detector	Tested	19
Horn/Strobe	Tested	1
Power Supply	Tested	7
Pull Station	Tested	20
Smoke Detector	Tested/Cleaned	26
Tamper Switch	Tested	21
Waterflow Switch	Tested	7
Total		133
Grand Total		133

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Wheaton Office

Control Panel: 1 - Silent Knight IFP-1000

Download Date: 12/21/2021

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	% of Inventory	Quantity		
Annunciator		Control	0.75%	1		
Battery		Control	12.03%	16		
Control Panel		Control	0.75%	1		
Duct Detector		Initiating	9.02%	12		
Fire Pump Power		Supervisory	0.75%	1		
Fire Pump Trouble		Supervisory	0.75%	1		
Heat Detector		Initiating	14.29%	19		
Horn/Strobe		Indicating	0.75%	1		
Power Supply		Control	5.26%	7		
Pull Station		Initiating	15.04%	20		
Smoke Detector		Initiating	19.55%	26		
Tamper Switch		Supervisory	15.79%	21		
Waterflow Switch		Initiating	5.26%	7		
Type	Qty	Model #	Description	Install Date		
		New (u	nder 90 days)			
Horn/Strobe	1	·	•	12/10/2021		
In Service - 1 Year to 2 Years						
DuraCell						
Battery	2	Dura12-8F	Sealed Lead Acid	01/11/2020		
		In Service -	3 Years to 5 Years			
Duracell						
Battery	2	Dura12-8F	Sealed Lead Acid	05/29/2018		
Power Patrol						
Battery	2	SLA1075	Sealed Lead Acid	05/18/2018		
		In Service	5 Years to 10 Years			
AES						
Smoke Detector	1	SD505-APS	Photoelectric	09/18/2014		
Fire Lite						
Pull Station	1	BG-12LX	Dual Action	09/18/2014		
Master						
Fire Pump Power	1	MCA-50-46-HX		09/18/2014		
Milwaukee						
Tamper Switch	2	BSB-SCSO		09/18/2014		
Tamper Switch		B3B 3C3O		05/10/2011		

Tamper Switch	3	OSYSU-2		09/18/2014
Waterflow Switch	2	VSR-F		09/18/2014
Power Patrol				
Battery	8	SLA1075	Sealed Lead Acid	09/18/2014
Silent Knight				
Control Panel	1	IFP-1000		09/18/2014
Fire Pump Trouble	1	PS-DA		09/18/2014
Heat Detector	17	SD505-HT		09/18/2014
Heat Detector	2	SD505-HT	Fixed Temperature	09/18/2014
Power Supply	7	5499		09/18/2014
Pull Station	19	PS-DA	Dual Action	09/18/2014
Smoke Detector	25	SD505-APS	Photoelectric	09/18/2014
System Sensor				
Duct Detector	8	RTS451	Photoelectric	09/18/2014
Duct Detector	4	RTS451KEY	Photoelectric	09/18/2014
Waterflow Switch	5	WFD25		09/18/2014
Victaulic				
Tamper Switch	1	705		09/18/2014
Tamper Switch	13	705W		09/18/2014
Tamper Switch	2	728		09/18/2014
Interstate				
Battery	2	BSL1116	Sealed Lead Acid	06/24/2014
Silent Knight				
Annunciator	1	RA-100	LED List	04/18/2014

Zone Address Report

Generated by: BuildingReports.com

Building: Wheaton Office

Control Panel: 1 - Silent Knight
IFP-1000

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Туре	ScanID				
Zone/Cir	Zone/Circuit: M							
01	Waterflow Switch	Pump Room		30565189				
01	Pull Station	Suite 100 North Exit	Dual Action	39732916				
02	Waterflow Switch	Pump Room		57331475				
02	Pull Station	Suite 140 Main Entrance	Dual Action	39732917				
03	Fire Pump Power	Pump Room		32703771				
03	Tamper Switch	Pump Room		30565184				
03	Tamper Switch	Pump Room		30565185				
03	Tamper Switch	Pump Room		30565186				
04	Tamper Switch	Pump Room		30565172				
04	Tamper Switch	Pump Room		30565173				
05	Tamper Switch	Pump Room		30565176				
05	Tamper Switch	Pump Room		30565178				
05	Tamper Switch	Pump Room		30565179				
05	Tamper Switch	Pump Room		30565180				
05	Tamper Switch	Pump Room		30565182				
05	Tamper Switch	Pump Room		30565183				
05	Tamper Switch	Pump Room CLOSED		30565181				
06	Pull Station	1st East Lobby	Dual Action	32703913				
09	Pull Station	Pump Room	Dual Action	32703915				
10	Smoke Detector	1st Main Electrical Room	Photoelectric	32703997				
11	Heat Detector	1st Main Electrical Room		32703998				
12	Pull Station	1st South Vestibule	Dual Action	32703914				
13	Pull Station	1st Center Lobby	Dual Action	32703912				
14	Heat Detector	1st Main Electrical Room		32703999				
15	Smoke Detector	1st Main Electrical Room	Photoelectric	32704000				
16	Smoke Detector	1st Maintenance Elevator Lobby	Photoelectric	32704001				
17	Smoke Detector	1st Electrical Room	Photoelectric	32704003				
18	Heat Detector	1st Electrical Room		32704002				
19	Smoke Detector	1st Elevator Lobby	Photoelectric	32703986				
22	Smoke Detector	1st MPOP Room	Photoelectric	32703996				
23	Heat Detector	1st MPOP Room		32703995				
24	Heat Detector	Garage Electrical Room	Fixed Temperature	32703970				
25	Smoke Detector	Garage Electrical Room	Photoelectric	32703969				
26	Heat Detector	LL Pit		32703779				
27	Smoke Detector	LL Pit	Photoelectric	32703783				
28	Smoke Detector	Garage Elevator Lobby	Photoelectric	32703971				
31	Smoke Detector	LL Pit	Photoelectric	32703782				
32	Heat Detector	LL Pit		32703778				
34	Heat Detector	LL Pit		32703777				

35	Pull Station	LL West Stairs	Dual Action	32703911
36	Pull Station	LL East Stairs	Dual Action	32703910
37	Pull Station	2nd East Stairs	Dual Action	32703909
38	Duct Detector	1st East Office	Photoelectric	32703898
39	Duct Detector	2nd East Office Activ IT Closet	Photoelectric	32703897
40	Smoke Detector	2nd Electrical Room	Photoelectric	32703974
41	Heat Detector	2nd Electrical Room		32703973
42	Smoke Detector	2nd Elevator Lobby	Photoelectric	32703975
45	Heat Detector	2nd MPOP Room		32703972
46	Smoke Detector	2nd MPOP Room	Photoelectric	32703994
47	Pull Station	2nd West Stairs	Dual Action	32703908
49	Duct Detector	2nd West Office Electrical closet	Photoelectric	32703895
50	Pull Station	3rd East Stairs	Dual Action	32703905
51	Tamper Switch	1st West Stairs		32703775
51	Tamper Switch	Maintenance Garage Elevator Sticker O	n	32703774
		Outlet		
52	Duct Detector	3rd East Office Hallway	Photoelectric	32703894
53	Heat Detector	3rd Electrical Room		32703988
54	Smoke Detector	3rd Electrical Room	Photoelectric	32703989
55	Smoke Detector	3rd Elevator Lobby	Photoelectric	32703990
56	Pull Station	Suite 190 West Dining Room Exit	Dual Action	39732920
57	Pull Station	Suite 190 West Kitchen Exit	Dual Action	39732921
58	Heat Detector	3rd MPOP Room		32703987
59	Smoke Detector	3rd MPOP Room	Photoelectric	32703984
60	Pull Station	3rd West Stairs	Dual Action	32703904
61	Pull Station	1st North Vestibule	Dual Action	32703903
62	Duct Detector	3rd West Office	Photoelectric	32703893
63	Fire Pump Trouble	4th East Stairs		32703902
65	Duct Detector	4th East Office South	Photoelectric	32703892
66	Heat Detector	4th Electrical Room		32703981
67	Smoke Detector	4th Electrical Room	Photoelectric	32703982
68	Smoke Detector	4th Elevator Lobby	Photoelectric	32703983
70	Duct Detector	Suite 190 Sushi Beverage Area	Photoelectric	32703966
71	Heat Detector	4th MPOP Room		32703976
72	Smoke Detector	4th MPOP Room	Photoelectric	32703977
73	Pull Station	4th West Stairs	Dual Action	32703901
75	Duct Detector	4th West Office	Photoelectric	32703891
76	Pull Station	5th East Stairs	Dual Action	32703900
78	Duct Detector	5th North IT Lab	Photoelectric	32703890
80	Heat Detector	5th Electrical Room		32703856
81	Smoke Detector	5th Electrical Room	Photoelectric	32703857
82	Heat Detector	5th Shaft		32703776
83	Smoke Detector	5th Shaft	Photoelectric	32703781
84	Heat Detector	5th Elevator Room		32703855
85	Smoke Detector	5th Elevator Room	Photoelectric	32703854
86	Smoke Detector	5th Elevator Lobby	Photoelectric	32703858
87	Duct Detector	Suite 190 Sushi Beverage Area	Photoelectric	32703968
88	Duct Detector	Suite 190 Sushi Kitchen	Photoelectric	32703967
90	Smoke Detector	5th Shaft	Photoelectric	32703780
92	Pull Station	Suite 190 North Main Entrance	Dual Action	39732919
93	Heat Detector	5th Elevator Room		32703852
94	Smoke Detector	5th Elevator Room	Photoelectric	32703853
95	Heat Detector	5th MPOP Room	Fixed Temperature	32703873

96	Smoke Detector	5th MPOP Room	Photoelectric	32703872
97	Pull Station	5th West Stairs	Dual Action	32703899
98	Pull Station	Suite 190 North Exit	Dual Action	39732918
99	Duct Detector	5th West Office	Photoelectric	32703889
103	Waterflow Switch	2nd East Stairs		32703866
104	Tamper Switch	2nd East Stairs		32703865
105	Waterflow Switch	3rd East Stairs		32703863
106	Tamper Switch	3rd East Stairs		32703864
107	Waterflow Switch	4th East Stairs		32703862
108	Tamper Switch	4th East Stairs		32703861
109	Waterflow Switch	5th East Stairs		32703860
110	Tamper Switch	5th East Stairs		32703859
123	Tamper Switch	Garage Elevator		32703772
124	Tamper Switch	Garage Elevator		32703773
125	Waterflow Switch	LL East Stairs		32703867
126	Tamper Switch	LL East Stairs		32703868