





FIRE PROTECTION DIVISION

24 Hr Emergency Service 888.217.7055

Sprinkler Inspection Certificate

For

120 E Liberty 120 E Liberty Wheaton, IL 60187

Tested to NFPA 25 Standards

This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

Annual Inspection Inspection Date Apr 1, 2021

> Building: 120 E Liberty Contact: Nathan Sands Title: Building Engineer

Company: Shambaugh & Son Contact: Chris Kilian Title: Sprinkler Fitter

Executive Summary

Generated by: BuildingReports.com

Building Information

Building: 120 E Liberty **Contact:** Nathan Sands **Address:** 120 E Liberty **Phone:** (630) 230-1221

Address: Fax: City/State/Zip: Wheaton, IL 60187 Mobile:

Country: United States of America Email: nsands@wavelandprop.com

Inspection Performed By

Company: Shambaugh & SonInspector: Chris KilianAddress: 2820 Thatcher RoadPhone: (630) 514-6587

Address: Unit 1 Fax:
City/State/Zip: Downers Grove, Illinois 60515 Mobile:

Country: United States Email: ckilian@shambaugh.com

System Control Unit

System Type	System Location	Protected Area	Devices
Deluge		Riser #03	9
Deluge		Riser #04	9
Fire Pump		Building-	10
Service Main		Building-	2
Wet Pipe		Building-	5
Wet Pipe		Riser #01	5
Wet Pipe		Riser #02	4

Inspection Summary

Catagory	Total Items		Serv	/iced	Pas	sed	Failed/Other		
Category:	Qty	%	Qty	%	Qty	%	Qty	%	
Device	10	22.73%	10	100.00%	10	100.00%	0	0%	
Alarm	9	20.45%	9	100.00%	8	88.89%	1	11.11%	
Valve	21	47.73%	21	100.00%	21	100.00%	0	0%	
Hose	1	2.27%	1	100.00%	1	100.00%	0	0%	
Pump	2	4.55%	2	100.00%	2	100.00%	0	0%	
Sprinkler	1	2.27%	1	100.00%	1	100.00%	0	0%	
Totals	44	100%	44	100.00%	43	97.73%	1	2.27%	

Verification

VERIFIED SERVICE MEMBER BUILDING REPORTS Company: Shambaugh & Son

Inspector: Chris Kilian

_

Signed: Apr 1, 2021

Building: 120 E Liberty
Contact: Nathan Sands

Discrepancy Report

Generated by: BuildingReports.com

Building: 120 E Liberty

The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is subject to a recall or part of a manufacturer's replacement/upgrade program is included.

Device Type		Manufacturer	ModelNumber	Date	Qty							
		Items listed for Reca	all or Replacement/Upgrade									
	No items found during this inspection.											
ScanID	Location		Problem	Reference								
		Wet Pip	e, Riser #02									
Waterflow \$	Switch											
30565190 Ground Pump Room												

Proposed Solutions Report

Generated by: BuildingReports.com

Building: 120 E Liberty

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix						
Wet Pipe, Riser #02											
Waterflow Switch											
30565190	Ground Pump Room	Replace/Test	VSR-F	T/M							
			PO #: (none)	T/M							

Inspection & Testing

Generated by: BuildingReports.com

Building: 120 E Liberty

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
	Pa	ssed		
Deluge, Riser #03	<u> </u>			
Pressure Switch	Ground Pump Room	Annual	8:31:07 AM	04/01/2021
Pressure Switch	Ground Pump Room	Annual	8:31:53 AM	04/01/2021
Drain	Ground Pump Room	Annual	8:30:45 AM	04/01/2021
Gauge	Ground Pump Room	Annual	8:31:27 AM	04/01/2021
Gauge	Ground Pump Room	Annual	8:39:39 AM	04/01/202
Air Compressor	Ground Pump Room	Annual	8:39:53 AM	04/01/202
Check Valve	Ground Pump Room	Annual	8:40:32 AM	04/01/202
Control Valve	Ground Pump Room	Annual	8:29:49 AM	04/01/202
Deluge Valve	Ground Pump Room	Annual	8:39:35 AM	04/01/202
Deluge, Riser #04				
Pressure Switch	5th Closet	Annual	8:55:55 AM	04/01/202
Pressure Switch	5th Closet	Annual	8:56:30 AM	04/01/202
Drain	5th Closet	Annual	8:56:10 AM	04/01/202
Gauge	5th Closet	Annual	8:55:46 AM	04/01/202
Gauge	5th Closet	Annual	8:55:57 AM	04/01/202
Air Compressor	5th Closet	Annual	8:56:19 AM	04/01/202
Check Valve	5th Closet	Annual	8:55:35 AM	04/01/202
Control Valve	5th Closet	Annual	8:56:05 AM	04/01/202
Deluge Valve	5th Closet	Annual	8:55:28 AM	04/01/202
Fire Pump, Buildi	ng-			
Tamper Switch	Ground Pump Room	Annual	8:19:55 AM	04/01/202
Check Valve	Ground Pump Room	Annual	8:20:16 AM	04/01/202
Check Valve	Ground Pump Room	Annual	8:40:08 AM	04/01/202
Control Valve	Ground Pump Room	Annual	8:19:44 AM	04/01/202
Control Valve	Ground Pump Room	Annual	8:19:52 AM	04/01/202
Control Valve	Ground Pump Room	Annual	8:20:09 AM	04/01/202
Control Valve	Ground Pump Room	Annual	8:20:30 AM	04/01/202
Control Valve	Ground Pump Room	Annual	8:20:41 AM	04/01/202
Control Valve	Ground Pump Room	Annual	8:20:59 AM	04/01/202

Device Type	Location		Service	Time	Date
Control Valve	Ground Pump Room		Annual	8:21:18 AM	04/01/2021
Service Main, Build	ing-				
Fire Dep't	Ground Outside		Annual	8:32:16 AM	04/01/2021
Connection					
Check Valve	Ground Pump Room		Annual	8:32:21 AM	04/01/2021
Wet Pipe, Building-					
Tamper Switch	Ground Pump Room		Annual	8:19:22 AM	04/01/2021
Tamper Switch	Ground Pump Room		Annual	8:19:33 AM	04/01/2021
Sprinkler Box	Ground Pump Room		Annual	8:32:00 AM	04/01/2021
Control Valve	Ground Pump Room		Annual	8:19:20 AM	04/01/2021
Control Valve	Ground Pump Room		Annual	8:19:29 AM	04/01/2021
Wet Pipe, Riser #01					
Waterflow Switch	Ground Pump Room		Annual	8:30:11 AM	04/01/2021
Drain	Ground Pump Room		Annual	8:29:52 AM	04/01/2021
Gauge	Ground Pump Room		Annual	8:30:38 AM	04/01/2021
Control Valve	Ground Pump Room		Annual	8:29:34 AM	04/01/2021
Inspector's Test	Ground Pump Room		Annual	8:30:04 AM	04/01/2021
Wet Pipe, Riser #02					
Drain	Ground Pump Room		Annual	8:29:58 AM	04/01/2021
Gauge	Ground Pump Room		Annual	8:30:32 AM	04/01/2021
Control Valve	Ground Pump Room		Annual	8:29:42 AM	04/01/2021
		Failed/Other			
Wet Pipe, Riser #02					
Waterflow Switch	Ground Pump Room		Annual	8:37:58 AM	04/01/2021

Wet Pipe Fire Sprinkler Systems

Generated by: BuildingReports.com

Buildin	g: 120 E Libe	rty							Building-	
as to type o	n lists out all the de f component, pressi nent was actually te	ure readings, res _l	ponse time, etc. If	a compe	onent has an O	K checkbo	x that	is che	cked, then	
			Alarm	ıs						
Tamper S	Switch									
Location			Manufactur	er	Zone/Addr	ess	OK	(ScanID	
Ground Pum	np Room		Potter Electr	ric	1		Z		30565173	
Туре		Description			Number of	Turns				
OS & Y	' '									
Tamper S	3witch									
Location	_		Manufactur		Zone/Addr	ess	OK		ScanID 30565172	
Type Description Number of Turns OS & Y Supervisory										
Otl\	/-live		Compon	enis						
Control \		No. del		0:	Danitian	01-1		OK	0ID	
Туре	Manufacturer	Model	Ground Pump	Size	Position	Status	is OK		ScanID	
OS&Y	Clow	2638	Room	6"	Open	Supervise	sed 🗷		30565174	
Description										
Main Contro										
Main Control \	l City									
	l City	Model	Location	Size	Position	Status		ОК	ScanID	
_	ol City Valve	Model 2638	Location Ground Pump Room	Size	Position Open	Status Supervise		ok ☑	ScanID 30565175	
Control \	Valve Manufacturer Clow		Ground Pump							
Control \ Type OS&Y	Valve Manufacturer Clow		Ground Pump							
Control \ Type OS&Y Description	Valve Manufacturer Clow		Ground Pump	6"						
Control \ Type OS&Y Description	Valve Manufacturer Clow Il System		Ground Pump Room	6"						
Control \ Type OS&Y Description Main Contro Sprinkler Oty Tool	Valve Manufacturer Clow I System	2638	Ground Pump Room	6" 2S		Supervise				
Control \ Type OS&Y Description Main Contro Sprinkler Oty Tool	Manufacturer Clow Ol System The Box Cloy Cloy Cloy Cloy Cloy Cloy Cloy Cloy	2638	Ground Pump Room	6"	Open	Supervise	ed	₩.	30565175	

This section lists out all the devices and components that have been associated with a Wet Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was actually tested. However, for Pass/Fail test results, see the Inspection and Testing section.

Alarms										
Water	flow Switch									
Туре	Mar	nufacturer	Model #	Se	C	Size	e Zone/Addi	ress	ок	ScanID
Vane	Pott	ter Electric	VSR-F	32		3"	1		M	30565189
				Compone	ents					
Contro	l Valve									
Туре	Manufactu	rer Model	Loc	cation	Size	Posit	tion Status	;	ок	ScanID
Butterfly	Victaulic	705W	Gro Roo	ound Pump om	4"	Open	n Superv	vised	Z	30565184
Description	on									
Isolation										
Inspec	tor's Test									
Manufact	urer	Model #	Pressure p	si Valve Tri	p Time s	sec	Water Flow Tim	ne sec	ок	ScanID
TestanDra	ain	1000				·	32		Z	47712764
Location										
Ground Po	ump Room									
				Device	?S					
Drain										
Current Ir	nspection									
Туре	Location		Size	Supply psi	Restore	ed	Residual psi	Sec	ок	ScanID
Main	Ground Pump Ro	oom	2"	155	157		60 City 150w/ FP	J.	¥	30565191
Previous	Inspections									
February	17, 2020									
Туре	Location		Size	Supply psi	Static p	osi	Residual psi	Sec	ок	ScanID
Main	Ground Pump Ro	oom	2"	155	157		60 City 150w/ FP		Ø	30565191
April 5, 20	019									
Туре	Location		Size	Supply psi	Static p	osi	Residual psi	Sec	ок	ScanID
Main	Ground Pump Ro	oom	2"		155		62 City 150w/ FP		V	30565191
Gauge										
Location				S	Service D	Date				
Ground Po	ump Room			C	3/18/200)7				
Туре	Manufa	acturer	Model #	#	Static p	si F	Fill Type	Size	ок	ScanID
System Pi	ressure Ashcrof	ft			157	r	n/a	1/4	Z	30565187
Buildi	ng: 120 E L	iberty								Riser #02

This section lists out all the devices and components that have been associated with a Wet Pipe System and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was actually tested. However, for Pass/Fail test results, see the Inspection and Testing section.

	Alarms											
Water	flow Switch											
Туре	Manufa	acturer	Model #	ŧ s	ес	Size	Zone/Add	ress	ок	ScanID		
Vane	Potter I	Electric	VSR-F			4"	1			30565190		
				Compon	ents							
Contro	ol Valve											
Туре	Manufacturer	Model	Lo	cation	Size	Posit	ion Status	;	ОК	ScanID		
Butterfly	Victaulic	705W	Gro Ro	ound Pump om	4"	Open	Super	vised	×	30565185		
Descripti	ion											
Isolation												
	Devices											
Drain												
Current I	nspection											
Туре	Location		Size	Supply psi	Restor	ed	Residual psi	Sec	ок	ScanID		
Main	Ground Pump Roon	١	2"	155	157 60 City 150w /FP				v	30565192		
Previous	Inspections											
February	17, 2020											
Туре	Location		Size	Supply psi	Static	psi	Residual psi	Sec	ОК	ScanID		
Main	Ground Pump Room	า	2"	155	157		60 City 150w /FP		Z	30565192		
April 5, 2	019											
Туре	Location		Size	Supply psi	Static	psi	Residual psi	Sec	ок	ScanID		
Main	Ground Pump Room	า	2"		156		62 City 150w /FP		☑	30565192		
Gauge								·				
Location					Service	Date						
Ground P	ump Room			(03/18/20	07						
Туре	Manufactu	irer	Model	#	Static p	osi F	ill Type	Size	ок	ScanID		
System P	ressure Ashcroft				157	n	/a	1/4	₩.	30565188		

Private Fire Service Mains

Generated by: BuildingReports.com

Building: 120 E Liberty Building-

This section lists out all the devices and components that have been associated with a Private Fire Service Main and provides details as to type of component, pressure readings, response time, etc. If a component has an OK checkbox that is checked, then that component was actually tested. However, for Pass/Fail test results, see the Inspection and Testing section.

Components										
Check Valve										
Type Location Internal Date Size OK ScanID										
Grooved	ooved Ground Pump Room 03/18/2014 4" ☑ 32859042									
			Devices							
Fire Dep	't Connection									
L	ocation	Туре	BallDrip	Rotating Swivels	Size	ок	ScanID			
Ground Outside Siamese No Yes 4" ☑ 30565196										

Deluge Fire Sprinkler Systems Generated by: BuildingReports.com

Buildi	Building: 120 E Liberty Riser #03															
as to type	ion lists out o e of compone ponent was c	ent, pre	ssure rea	dings,	response	e time, etc.	If a	compo	nent	has	an O	K checkb	ox the	ıt is o	checi	
Air Co	mpressor															
Location	ı	М	fr.	Mod	el#	Phase		On	psi	Of	f psi		5	Seria	l No	
Ground F	Pump Room	G Ai	eneral r	OL1	1016AC	1		25		30			OL11	0-80	37 0	5 06
Туре		D	escriptio	n		Rated Speed		Hor	sepower Volt				ts Amps		ок	ScanID
Automatio	c	Ta	ankless			1740		.17				115 /230	5.2/2 6	2.	Ø	32859048
Alarms																
Pressure Switch																
Туре		Desc	ription		Manufa	acturer	L	-ow	Hig	h	Zone	e/Addres	s	ОК		ScanID
Pressure	Switch	Super	visory		Potter I		2	24			1			~		32859046
Pressure	Switch	Alarm	<u> </u>		Potter I	Electric					1			×		32859047
						Compo	ne	nts								
Check	Valve															
Туре	Loca	tion				Intern	al D	ate				Si	ze	ок		ScanID
Grooved	Groui	nd Pum	p Room			03/18/	2014	4				2.5	5"	V		30565194
Contro	ol Valve															
Туре	Manuf	facture	r Mode	el	Loc	cation		Size	Pos	itio	า	Status		ОК		ScanID
Butterfly	Victau	lic	705W	1	Gro Ro	ound Pump om	0	2"	Оре	en		Supervis	sed	¥		30565186
Descripti	on															
Isolation																
Deluge	e Valve															
Manufact	urer	Мс	del #	Loc	ation				S	eria	l #	S	Size		ок	ScanID
Viking		F-1	I	Gro	und Pum	np Room						2	2.5"		V	30565193
Туре		Po	sition	Sta	itus		Rei	note p	si V	alve	psi		Sole	noid		Sec
Pneumati	С	Tri	m Open	Su	pervised		155	5	10	65			24vd	С		5
Water psi	i		Air Pre	essure)		Trip	Air ps	i			Tri	p Tim	ie		
155			35				5					5				
						Devi	ces	5								
Drain																
Current II	nspection															
								Restor	ed							

Туре	Location		Size	Supply psi	si psi Residual			al psi	psi Sec Ol			ScanID
Main	Ground Pump	Room	1.25"	160	160		60 City /FP	150w		¥	;	32859045
Previous	Inspections											
February	17, 2020											
Туре	Location		Size	Supply psi	Static p	osi	Residu	al psi	Sec	ОК		ScanID
Main	Ground Pump	Room	1.25"	160	160		60 City /FP	150w		V		32859045
April 5, 2	019											
Туре	Location		Size	Supply psi	Static p	osi	Residu	al psi	Sec	ок		ScanID
Main	Ground Pump	Room	1.25"		155		62 City /FP	150w		M		32859045
Gauge	Gauge											
Location					Service [Date						
Ground P	ump Room				03/18/200)7						
Туре	Manı	‡	Static p	si Fi	II Type		Size	ок		ScanID		
Air Pressu	ure Viking	g			30	n/	'a	1	/4	Y	3	2859043
Gauge												
Location Service Date												
Ground P	ump Room				03/18/200)8						
Туре	Manu	ıfacturer	Model #	‡	Static p	si Fi	II Type		Size	ОК		ScanID
System P	ressure Vikino	g			155	n/	'a	1	/4	Z	3	2859044
Buildi	ing: 120 E	Liberty									R	iser #04
as to type	ion lists out all e of component, ponent was acti	pressure read	dings, response	time, etc. Ij	^c a compo	nent ho	as an Ol	K checkl	ox the	at is cl	heck	
Air Co	mpressor											
Location	ı	Mfr.	Model #	Phase	On psi Off psi Serial No.							
5th Close	et	General Air	OL11016AC	1	20	3	34		OL11	0-08 4	17 O	5 48
				Rated								
Туре		Description	n	Speed		sepow	er	Volts	Am		OK	ScanID
Automati	C 	Tankless		1740	.17			115 /230	5.2/ 6	2.	₩.	32859054
				Alarn	ıs							
Press	ure Switch											
Туре		escription	Manufa		Low	High	Zone	/Addres	SS	OK		ScanID
Pressure		larm	Potter I		0.4		1			Z		32859049
Pressure	Switch S	upervisory	Potter I		24		1			☑	,	32859051
	\/ I			Compon	ents							
Check					_							
Туре	Locatio	n		Date			S	ize	ОК		ScanID	

Grooved 5th Closet				03/18/2014					2.5"		V		30565199		
Control Valve															
Туре	Manufact	urer	Model		Loc	ation	S	ize P	ositi	on	Status	5	ОК		ScanID
Butterfly	Victaulic		705W		5th	Closet	2'	' C	pen		Super	vised	V		30565198
Descripti	on														
Isolation															
Deluge	e Valve														
Manufact	turer	Mode	el#	Location	n				Ser	ial#		Size		OK	ScanID
Viking		F-1		5th Close	et							2.5"		V	30565197
Туре		Posit	tion	Status			Rem	ote psi	Valv	e psi		Sole	noid		Sec
Pneumati	С	Trim	Open	Supervis	sed		135		135			24vc	lc		5
Water ps	i		Air Pres	sure		Т	rip /	Air psi			Т	rip Tin	ne		
130			34			5	5				5	i			
						Devid	ces								
Drain															
Current I	nspection														
Туре	Location			Size		Supply ps	si R	estored si	d	Residu	ıal psi	Sec	ок		ScanID
Main	5th Closet			1.25	"	130	12	25		60 City /FP	150w	,	Z		32859055
Previous	Inspections														
February	17, 2020														
Туре	Location			Size		Supply ps	si S	tatic ps	si	Residu	ıal psi	Sec	ОК		ScanID
Main	5th Closet			1.25	"	130	12	25		60 City /FP	150w		¥		32859055
April 5, 2	019														
Туре	Location			Size		Supply ps	si S	tatic ps	si	Residu	ıal psi	Sec	ОК		ScanID
Main	5th Closet			1.25	"	135	13	33		60 City /FP	150w		Z		32859055
Gauge															
Location							Ser	vice Da	ate						
5th Close	t						03/	18/2008	3						
Туре	Manuf	actur	er	Mod	del #		St	atic psi	i Fi	II Type		Size	ОК		ScanID
Air Pressi Gauge	· · ·						34		n/	a		1/4	V		32859052
Location							Ser	vice Da	ate						
5th Close	t						03/	18/2008	3						
Туре	Manuf	actur	er	Mod	del #		St	atic psi	i Fi	II Type		Size	ок		ScanID
System D	ressure Viking						13	5	n/	a		1/4	Z		32859053

Fire Pump Testing Generated by: BuildingReports.com

Building-

Building: 120 E Liberty

type of comp	lists out all the de conent, pressure re vas actually tested	adings, response	time, etc. If a cor	nponen	t has an OK ci	heckbox	that is d	checked				
			Alarm	lS								
Tamper Switch												
Location			Manufactur	er	Zone/Add	Iress		ок	ScanID			
Ground Pum	p Room		Potter Electr	Potter Electric			1		30565176			
Туре		Description			Number o	f Turns						
OS & Y		Supervisory										
			Compon	ents								
Check Va	lve											
Туре	Location		Internal	Date			Size	ок	ScanID			
Grooved	Ground Pump	Room	03/18/20	14			6"	Z	32859040			
Grooved	Ground Pump	Room	03/18/20	14			6"	\checkmark	32859041			
Control V	alve											
Туре	Manufacturer	Model	Location	Size	Position	Status	S	ОК	ScanID			
Butterfly	Victaulic	728	Ground Pump Room	1"	Open	Super	vised	Ø	30565182			
Description												
Suction JP												
Control V	alve											
Туре	Manufacturer	Model	Location	Size	Position	Status	S	ок	ScanID			
OS&Y	Kennedy	KS-RW	Ground Pump Room	6"	Open	Super	vised	☑	30565177			
Description												
Discharge												
Control V	alve											
Туре	Manufacturer	Model	Location	Size	Position	Status	S	ок	ScanID			
Butterfly	Victaulic	705W	Ground Pump Room	6"	Open	Super	vised	☑	30565179			
Description												
By-pass												
Control Valve												
Туре	Manufacturer	Model	Location	Size	Position	Statu	S	ок	ScanID			
Butterfly	Victaulic	705W	Ground Pump Room	6"	Open	Super	vised	☑	30565180			
Description												

By-pass										
Control Valve										
Туре	Manufacturer	Model	Location	Size	Position	Status	ок	ScanID		
Butterfly	Victaulic	705W	Ground Pump Room	6"	Closed	Supervised	Ø	30565181		
Description										
Test Header										
Control Valve										
Туре	Manufacturer	Model	Location	Size	Position	Status	ок	ScanID		
Butterfly	Victaulic	705W	Ground Pump Room	6"	Open	Supervised	×	30565178		
Description										
Discharge										
Control V	alve									
Туре	Manufacturer	Model	Location	Size	Position	Status	ок	ScanID		
Butterfly	Victaulic	728	Ground Pump Room	1"	Open	Supervised	☑	30565183		
Description										
Discharge JP										

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: 120 E Liberty

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Type		Category	%	of Inventory	Quantity
Control Valve		Valve		29.55%	13
Tamper Switch		Alarm		6.82%	3
Check Valve		Valve		11.36%	5
Drain		Device		9.09%	4
Inspector's Test		Valve		2.27%	1
Waterflow Switch		Alarm		4.55%	2
Gauge		Device		13.64%	6
Pressure Switch		Alarm		9.09%	4
Sprinkler Box		Sprinkler		2.27%	1
Fire Dep't Connection		Hose		2.27%	1
Deluge Valve		Valve		4.55%	2
Air Compressor		Pump		4.55%	2
Device Type	Qty	Model #	Туре	Description	Install Date
		In Service	- 5 Years to	10 Years	
Deluge, Riser #03					
Air Compressor	1	OL11016AC	Automatic	Tankless	03/18/2014
Pressure Switch	1	PS10-2	Pressure Switch	Alarm	03/18/2014
Pressure Switch	1	PS40-2	Pressure Switch	Supervisory	03/18/2014
Control Valve	1	705W	Butterfly	Isolation	03/18/2014
Check Valve	1	E-1	Grooved		03/18/2014
Deluge Valve	1	F-1	Pneumatic		03/18/2014
Gauge	1		Air Pressure		03/18/2014
Gauge	1		System Pressure		03/18/2014
Drain	1		Main		03/18/2014
Deluge, Riser #04					
Air Compressor	1	OL11016AC	Automatic	Tankless	03/18/2014
Pressure Switch	1	PS10-2	Pressure Switch	Alarm	03/18/2014
Pressure Switch	1	PS40-2	Pressure Switch	Supervisory	03/18/2014
Control Valve	1	705W	Butterfly	Isolation	03/18/2014
Check Valve	1	E-1	Grooved		03/18/2014
Deluge Valve	1	F-1	Pneumatic		03/18/2014
	1	1-1	Air Pressure		03/18/2014
Gauge	ا 4				
Gauge	1		System Pressure		03/18/2014
Drain	1		Main		03/18/2014
Fire Pump, Building-					

Control Valve	1	KS-RW	OS&Y	Discharge	03/18/2014
Tamper Switch	1	OSYSU-2	OS & Y	Supervisory	03/18/2014
·	•	717	Grooved	Supervisory	
Check Valve	2			D	03/18/2014
Control Valve	2	705W	Butterfly	By-pass	03/18/2014
Control Valve	1	705W	Butterfly	Discharge	03/18/2014
Control Valve	1	705W	Butterfly	Test Header	03/18/2014
Control Valve	1	728	Butterfly	Discharge JP	03/18/2014
Control Valve	1	728	Butterfly	Suction JP	03/18/2014
Service Main, Building] -				
Fire Dep't Connection	1		Siamese		03/18/2014
Check Valve	1	717	Grooved		03/18/2014
Wet Pipe, Building-					
Control Valve	1	2638	OS&Y	Main Control City	03/18/2014
Control Valve	1	2638	OS&Y	Main Control System	03/18/2014
Tamper Switch	2	OSYSU-2	OS & Y	Supervisory	03/18/2014
Sprinkler Box	1				03/18/2014
Wet Pipe, Riser #01					
Gauge	1		System Pressure		03/18/2014
Drain	1	171N	Main		03/18/2014
Waterflow Switch	1	VSR-F	Vane	Alarm	03/18/2014
Inspector's Test	1	1000			03/18/2014
Control Valve	1	705W	Butterfly	Isolation	03/18/2014
Wet Pipe, Riser #02			-		
Gauge	1		System Pressure		03/18/2014
Drain	1	171N	Main		03/18/2014
Waterflow Switch	1	VSR-F	Vane	Alarm	03/18/2014
Control Valve	1	705W	Butterfly	Isolation	03/18/2014

Notes & Recommendations

Generated by: BuildingReports.com

Building: 120 E Liberty

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by SystemID.

Note	Device Type	Location	Comment	ScanID						
Gen	General Note									
	Need casing relief for fire pump									
Deluge, Riser #03										
2	Deluge Valve	Ground Pump Room	Passed	30565193						
	Quick trip									
Delu	Deluge, Riser #04									
3	Deluge Valve	5th Closet	Passed	30565197						
	Quick trip									
Wet	Pipe, Riser #02									
4	Waterflow Switch	Ground Pump Room		30565190						
	No adjustment available going off in 9 seconds									