Bay City Medical Office Building LLC. 4 Columbus Ave.

Monthly Fire Extinguisher Inspection

At least monthly, the organization inspects portable fire extinguishers. The completion dates of the inspections are documented.

Inspected By: Joe Ostroski

Title:	Facilities Engineer		Date:	11/17/22						
ldentifier	Location	Number of Exting.	Type of Exting.	Nov						
1415-ext	corridor leading to rad		abc	PASS						
1406-ext	n.w entrance		abc	PASS]
1426-ext	s.e entrance		abc	PASS]
1650-ext	across from nurses station		abc	PASS						
1651-ext	N entrance		abc	PASS						
2000-ext	outside center stair case		abc	PASS						
212-ext	exit to stair case S		abc	PASS]
207-ext	Electrical closet		abc	PASS						<u> </u>
2160-ext	Staff lounge in hall		abc	PASS						<u> </u>
3106-ext	across from nurses station		abc	PASS						j
3250-ext	alcove outside comm rm		abc	PASS]
1550-ext	door between patiant room and exam		abc	PASS]
2457-ext	outside storage		abc	PASS]
2455-ext	between nurses station and reception area		abc	PASS						j
2456-ext	stairwell exit		abc	PASS]
1002-ext	w entrance		abc	PASS]
127-ext	n entrance 1st floor		abc	PASS						<u> </u>
128-ext	north corridor off lobby		abc	PASS						<u> </u>
129-ext	s entrance		abc	PASS]
3111-ext	outside center stair well 3rd floor		abc	PASS						j
3008-ext	3rd floor s exit		abc	PASS						j
2477-ext	N stairwell Exit #rd floor		abc	PASS						j
2488-ext	Suite 250		abc	PASS						j
219-ext	Suite 210 treatmen t area behind N nurse station		abc	PASS						j
140-ext	Suite 140 corridore		abc	PASS						j
340-ext	Suite 340 LHF office		abc	PASS]
1001-ext	Med Gas RM		abc	PASS]
2407-ext	Suite 240 East wall		abc	PASS						
2600-ext	Suite 260 center coridor		abc	PASS						
3600-ext	Suite 360 corridor		abc	PASS						

ldentifier	Location	Number of Exting.	Type of Exting.	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sept	Oct	Nov	Dec
Please use the fo	ollowing key:														
P = Pass															
F = Fail															
1 = Equipment n	nissing/not located in designated areas														
2 = Equipment a	ccess or visibility obstructed														
3 = Nameplate o	pperating instructions not legible for facing outward														
4 = Safety seals, tamper indicator, lock pin broke/missing															
5 = CO2 extinguisher not full/requires recharge															
6 = Pressure gauge indicator out of range/position															
7 = Rehang brac	ket/insufficient equipment support														
	lamaged, replacement required														
8 = Equipment of	amagea, replacement required														