

601 Porter Street Petoskey Michigan 49770 231-348-2875

FAX 231-348-3179 www.johnegreen.com

| Date: 8/31/2021 BACKFLOW DEVICE TEST REPORT | | | | | | | | |
|---|-----------------------------|-----------------|----------------|-------------------------|-------------|-------|--|--|
| New Installation: Annual Inspection: | | | Repair: 🗌 | | | | | |
| Name of Premises: Service Address: | | tchell St. Peto | skey, MI 49770 | JEG Job No.: | | | | |
| Type of Device: | SVB | | | | | | | |
| Location of Device: | Eye Glass S | ink above ceili | ng | Accessibility: Good | | | | |
| Manufacturer: | Watts | Model: 008P | PCQT Size: | 1/2'' | Serial No. | 41360 | | |
| Responsible Person Contacted: Phone: | | | | | | | | |
| Line Pressure | REDUCED P | RESSURE PRIN | CIPLE ASSEMBLY | | | | | |
| PSI 66 | | | | PRESSURE VACUUM BREAKER | | | | |
| | Double Check Valve Assembly | | | | | | | |
| Initial Test | 1st Check | 2nd Check | Relief | Air Inlet | Check Valve | | | |
| Pass 🗸 | Closed | Closed | Opened | Opened 🗸 | Closed 🗸 | | | |
| Fail | Leaked 🗌 | Leaked 🗌 | Malf | Malf | Leaked | | | |
| 2nd Shut Off | PSID | PSID | PSID | PSID 2.0 | PSID | 1.4 | | |
| Closed 🗸 | | | | | | | | |
| Leaked | | | | | | | | |
| | | | | | | | | |
| | 1st Check | 2nd Check | Relief | Air Inlet | Check Valve | | | |
| | Closed | Closed 🗌 | Opened | Opened | Closed | | | |
| Final Test | Leaked 🗌 | Leaked 🗌 | Malf | Malf | Leaked | | | |
| | PSID | PSID | PSID | PSID | PSID | | | |
| Pass | | | | | | | | |
| Fail 🗌 | | | | | | | | |

Above report is certified to be true and correct: Signature: Kerin Com

| Name: Kevin Coen | | | Cert. No.: | 36974 |
|----------------------|-----------------------|---------------|---------------|---------|
| Gauge Number: TK-99E | Serial Number: 636762 | | | |
| Test Type: ASSE | | Testing Firm: | John E. Green | Company |