



Chicago Backflow, Inc.

ALSP
NAPERVILLE
ELGIN

708-389-5600
630-276-7070
847-760-8210

ROCKFORD
LIBERTYVILLE
CHICAGO

815-502-5081
847-849-8181
312-332-2182

BACKFLOW PREVENTION ASSEMBLY TEST AND CERTIFICATION REPORT

Address 30715 HIGHLAND PKWY
DOWNERS GROVE

WILKINS 975 457186 3/4 EQUIPMENT MAKE UP

MAKE AND MODEL		SER. NO.		SIZE		SERVICE	
LOCATION		TEST RESULTS					
NAME	DATE	CCCDW	C.V. #1	C.V. #2	RELIEF	REPAIRS/COMMENTS	PASS/FAIL
ALAU KINDLER	8/18	XC 4324	8.4	3.2	2.8	20-40 PSI REBUILT RV	PASS
ALAU KINDLER	8/19	XC 4324	8.6	3.4	2.8	30-50 PSI L.O.A.F	PASS
ALAU KINDLER	8/20	XC 4324	8.8	3.2	2.8	25-45 PSI L.O.A.F	PASS
ALAU KINDLER	8/21	XC 4324	8.3	3.1	2.4	45 PSI L.O.A.F	PASS
ALAU KINDLER	8/22	XC 4324	8.4	2.2	2.8	45 PSI L.O.A.F	PASS

This document is the exclusive and proprietary property of Chicago Backflow, Inc.

CBI Corporate Office
12607 S. Laramie Avenue, Alsip, IL 60803

WEB - www.chicagobackflow.com

FAX - 708-389-5632

E-mail - contact@backflow.com



BACKFLOW PREVENTER TEST REPORT

PLUMBING INSPECTION DEPARTMENT

PHONE

FAX

PERMIT #

☒ ORIGINAL TESTTIME 11 AM / PM DATE 1/5/22 DISTRICT ☐ RETEST ☒ PASS ☐ FAILTEST KIT Wilkins TG5 CALIBRATION DATE 2/25/22ADDRESS 3875 Highland Parkway OWNER Leaside Property CompanyCONTACT Josh Schmitt PHONE 312-859-2415 FAX CONTRACTOR Great Lakes Plumbing Co. PHONE 773-489-0400DEVICE = ☒ RP ☐ DC ☐ DCDA ☐ PVB SUPPLY PRESSURE 110 PSIGMFR Watts SIZE 2" MODEL# LF00914 SERIAL# 213879ON LINE TO Irrigation SystemEXACT LOCATION Concrete Mechanical Room**CHECK VALVE #1****CHECK VALVE #2****RELIEF VALVE**INITIAL TEST CLOSED TIGHT ☒ CLOSED TIGHT ☒ ☒ OPENED @LEAKED ☐ LEAKED ☐ 7.4 PSID / RP ZONE8.2 PSID 1.6 PSID ☐ DID NOT OPENCOMMENTS ☐ COMMENTS ☐ COMMENTS ☐FINAL TEST CLOSED TIGHT ☐ CLOSED TIGHT ☐ ☐ OPENED @ ☒ PSID**CONTROL VALVE #1****CONTROL VALVE #2****TEST COCKS**TYPE Ball TYPE Ball ☒ COMPLETERW ☐ RW ☐ ☐ MISSING #CLOSED TIGHT ☒ CLOSED TIGHT ☒ ☐ DAMAGEDLEAKED ☐ LEAKED ☐ ☐ COMMENTSCOMMENTS ☐ COMMENTS ☐COMMENTS New installation - DOF testCCCDI# XC 2756 PLUMBING LICENSE# 116200CCCDI NAME (PRINT) Terrence Wilkins SIGNATURE [Signature]



Chicago Backflow, Inc.

ALSF
NAPERVILLE
ELGIN

708-389-5600
630-276-7070
847-740-8210

ROCKFORD
LIBERTYVILLE
CHICAGO

815-502-5000
847-849-8000
312-332-2112

BACKFLOW PREVENTION ASSEMBLY TEST AND CERTIFICATION REPORT

Address 3075 HIGHLAND PARKY
DOWNSIDE GROVE, IL

WAF 957 UF 1714 4" DOMESTIC

MAKE AND MODEL			SER. NO.		SIZE		SERVICE	
LOCATION								
NAME	DATE	CCCD#	C.V. #1	C.V. #2	RELIEF	REPAIRS/COMMENTS		PASS/FAIL
ALAN KIMMER	8/18/21	XC 4324	10.6	3.6	2.8	6ops1 REPLACES 5/12TH-1895		PASS
ALAN KIMMER	8/14/22	XC 4324	10.8	3.2	2.6	6ops1		PASS

This document is the exclusive and proprietary property of Chicago Backflow, Inc.

CBI Corporate Office
12607 S. Laramie Avenue, Alsip, IL 60803

WEB - www.chicagobackflow.com

FAX - 708-389-5632

E-mail - contact@backflow.com



Chicago Backflow, Inc.

ALSP
NAPERVILLE
ELGIN

708-389-5600
630-276-7070
847-750-9210

ROCKFORD-
LIBERTYVILLE
CHICAGO

815-502-5001
847-849-8101
312-332-2112

BACKFLOW PREVENTION ASSEMBLY TEST AND CERTIFICATION REPORT

Address **3075 HIGHLAND PARKWAY
DOWNERS GROVE, IL**

AMES 20055 38M0323 8"

FIRE PROTECTION

MAKE AND MODEL			SER. NO.			SIZE	SERVICE
LOCATION			Pump Room				
NAME	DATE	CODE#	C.V. #1	C.V. #2	RELIEF	REPAIRS/COMMENTS	PASS/FAIL
ALAV KIMONER	8/17/19	XC 4324	3.0	2.6	X	60psi	PASS
ALAV KIMONER	8/17/20	XC 4324	3.6	2.0	X	65psi	PASS
ALAV KIMONER	8/18/21	XC 4324	3.2	2.4	X	60psi	PASS
ALAV KIMONER	8/4/22	XC 4324	3.4	2.6	X	65psi	PASS

This document is the exclusive and proprietary property of Chicago Backflow, Inc.

CBI Corporate Office
12607 S. Laramie Avenue, Ahip, IL 60803

WEB - www.chicagobackflow.com

FAX - 708-389-5632

E-mail - contact@backflow.com

CBI

CHICAGO BACKFLOW, INC.

Protecting your drinking water

Chicago Backflow, Inc.ALSP
NAPERVILLE
ELGIN708-389-5600
630-276-7870
847-760-9210ROCKFORD
LIBERTYVILLE
CHICAGO815-502-5001
847-849-8101
312-332-2112**BACKFLOW PREVENTION ASSEMBLY TEST AND CERTIFICATION REPORT**Address **3075 HIGHLAND PARKWAY
DOWNERS GROVE, IL****WATTS 607 98564 3/4 A/R BYPASS**

MAKE AND MODEL		SER. NO.		SIZE		SERVICE	
LOCATION		Pump Room					
NAME	DATE	CCCD#	C.V. #1	C.V. #2	RELIEF	REPAIRS/COMMENTS	PASS/FAIL
ALAN WARE	8/7/19	XC 4324	1.8	2.0	X	60psi	PASS
ALAN WARE	8/17/20	XC 4324	1.9	2.0	X	60psi	PASS
ALAN WARE	8/18/21	XC 4324	2.2	2.2	X	60psi REPLACED #4 T.C.	PASS
ALAN WARE	8/4/22	XC 4324	2.0	2.0	X	60psi	PASS

This document is the exclusive and proprietary property of Chicago Backflow, Inc.

CBI Corporate Office
12607 S. Laramie Avenue, Alsip, IL 60803WEB - www.chicagobackflow.com

FAX - 708-389-5632

E-mail - contact@backflow.com