

Test Status  Not Tested  Passed  Failed

Facility Name: HORIZON HEALTH CENTER Address: 19900 HAGGERTY Address 2:

City: LIVONIA State: MI Zip Code: 48152-1046

Type: PVB Size: 2 Meter #: Manufacturer: FEBCO Model: 765

Serial: 08655 Permit:  Containment  Isolation  Fire Protection

Location Comments: Lawn Sprinkler System on south wall

Shut Off Valve 1:  Closed  Leaked Shut Off Valve 2:  Closed  Leaked Line Pressure: 50 Initial Test Date: 04/19/2023

Table with 5 columns: 1st Check, 2nd Check, Relief Valve, PVB/SVB Air Inlet, PVB/SVB Check Valve. Each column contains status options (Closed, Leaked, Opened, etc.) and a PSID value.

Tester/Repair Comments:

Tester Name: Barrie Rudnick Testing Company: Complete Quality Construction & Maintenance LLC

Tester Cert #: 26042 Gauge Manufacturer: MIDWEST Gauge Model: 845-3 Gauge Serial #: 07143192 Calibration Date: 02/10/2023

Table with 5 columns: 1st Check, 2nd Check, Relief Valve, PVB/SVB Air Inlet, PVB/SVB Check Valve. Each column contains status options and a PSID value.

Final Test Date:

Test Status  Not Tested  Passed  Failed

Facility Name

Address

Address 2

HORIZON HEALTH CENTER

19900 HAGGERTY

City

State

Zip Code

LIVONIA

MI

48152-1046

Type:

Size:

Meter #:

Manufacturer:

Model:

RPBP

0.75

Watts

909CW

Serial:

Permit:

76223

Containment

Isolation

Fire Protection

Location Comments:

Cooling Tower - 2nd Floor

Shut Off Valve 1:

Shut Off Valve 2:

Line Pressure:

Initial Test Date:

Closed  Leaked

Closed  Leaked

45

04/19/2023

1st Check	2nd Check	Relief Valve	PVB/SVB Air Inlet	PVB/SVB Check Valve
<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input checked="" type="checkbox"/> Opened <input type="checkbox"/> Did Not Open <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Failed	<input type="checkbox"/> Held <input type="checkbox"/> Failed
PSID: 8.2	PSID: 6.2	PSID: 2.6	PSID: 0	PSID: 0

Tester/Repair Comments:

Tester Name:

Testing Company:

Barrie Rudnick

Complete Quality Construction & Maintenance LLC

Tester Cert #:

Gauge Manufacturer:

Gauge Model:

Gauge Serial #:

Calibration Date:

26042

MIDWEST

845-3

07143192

02/10/2023

1st Check	2nd Check	Relief Valve	PVB/SVB Air Inlet	PVB/SVB Check Valve
<input type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Did Not Open <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Failed	<input type="checkbox"/> Held <input type="checkbox"/> Failed
PSID: 0	PSID: 0	PSID: 0	PSID: 0	PSID: 0

Final Test Date:

Test Status  Not Tested  Passed  Failed

Facility Name: HORIZON HEALTH CENTER Address: 19900 HAGGERTY Address 2:

City: LIVONIA State: MI Zip Code: 48152-1046

Type: DDCV Size: 4 Meter #: Manufacturer: WILKINS Model: 350DA

Serial: N03741 Permit:  Containment  Isolation  Fire Protection

Location Comments: Fire Protection in Mechanical Room

Shut Off Valve 1:  Closed  Leaked Shut Off Valve 2:  Closed  Leaked Line Pressure: 50 Initial Test Date: 04/19/2023

Table with 5 columns: 1st Check, 2nd Check, Relief Valve, PVB/SVB Air Inlet, PVB/SVB Check Valve. Each column contains status options (Closed, Leaked, Opened, etc.) and a PSID field with value 2 or 0.

Tester/Repair Comments:

Tester Name: Barrie Rudnick Testing Company: Complete Quality Construction & Maintenance LLC

Tester Cert #: 26042 Gauge Manufacturer: MIDWEST Gauge Model: 845-3 Gauge Serial #: 07143192 Calibration Date: 02/10/2023

Table with 5 columns: 1st Check, 2nd Check, Relief Valve, PVB/SVB Air Inlet, PVB/SVB Check Valve. Each column contains status options and a PSID field with value 0.

Final Test Date:

Test Status  Not Tested  Passed  Failed

Facility Name: HORIZON HEALTH CENTER Address: 19900 HAGGERTY Address 2:

City: LIVONIA State: MI Zip Code: 48152-1046

Type: RPBP Size: 1.5 Meter #: Manufacturer: Watts Model: 909M1QT

Serial: 291599 Permit:  Containment  Isolation  Fire Protection

Location Comments: Dialysis Feed Line - \*\*\*APTR\*\*\*

Shut Off Valve 1:  Closed  Leaked Shut Off Valve 2:  Closed  Leaked Line Pressure: 50 Initial Test Date: 04/19/2023

1st Check	2nd Check	Relief Valve	PVB/SVB Air Inlet	PVB/SVB Check Valve
<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input checked="" type="checkbox"/> Opened <input type="checkbox"/> Did Not Open <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Failed	<input type="checkbox"/> Held <input type="checkbox"/> Failed
PSID: 7.6	PSID: 5.6	PSID: 3.4	PSID: 0	PSID: 0

Tester/Repair Comments:

Tester Name: Barrie Rudnick Testing Company: Complete Quality Construction & Maintenance LLC

Tester Cert #: 26042 Gauge Manufacturer: MIDWEST Gauge Model: 845-3 Gauge Serial #: 07143192 Calibration Date: 02/10/2023

1st Check	2nd Check	Relief Valve	PVB/SVB Air Inlet	PVB/SVB Check Valve
<input type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Did Not Open <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Failed	<input type="checkbox"/> Held <input type="checkbox"/> Failed
PSID: 0	PSID: 0	PSID: 0	PSID: 0	PSID: 0

Final Test Date:

Test Status  Not Tested  Passed  Failed

Facility Name: HORIZON HEALTH CENTER Address: 19900 HAGGERTY Address 2:

City: LIVONIA State: MI Zip Code: 48152-1046

Type: RPBP Size: 3 Meter #: Manufacturer: Watts Model: 909

Serial: 159556 Permit:  Containment  Isolation  Fire Protection

Location Comments: Containment Device in Mechanical Room

Shut Off Valve 1:  Closed  Leaked Shut Off Valve 2:  Closed  Leaked Line Pressure: 45 Initial Test Date: 04/19/2023

1st Check	2nd Check	Relief Valve	PVB/SVB Air Inlet	PVB/SVB Check Valve
<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input checked="" type="checkbox"/> Opened <input type="checkbox"/> Did Not Open <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Failed	<input type="checkbox"/> Held <input type="checkbox"/> Failed
PSID: 8.8	PSID: 58	PSID: 2.4	PSID: 0	PSID: 0

Tester/Repair Comments:

Tester Name: Barrie Rudnick Testing Company: Complete Quality Construction & Maintenance LLC

Tester Cert #: 26042 Gauge Manufacturer: MIDWEST Gauge Model: 845-3 Gauge Serial #: 07143192 Calibration Date: 02/10/2023

1st Check	2nd Check	Relief Valve	PVB/SVB Air Inlet	PVB/SVB Check Valve
<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input checked="" type="checkbox"/> Opened <input type="checkbox"/> Did Not Open <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Failed	<input type="checkbox"/> Held <input type="checkbox"/> Failed
PSID: 8.8	PSID: 6.4	PSID: 3.8	PSID: 0	PSID: 0

Final Test Date: 04/20/2023

Test Status  Not Tested  Passed  Failed

Facility Name: HORIZON HEALTH CENTER Address: 19900 HAGGERTY Address 2:

City: LIVONIA State: MI Zip Code: 48152-1046

Type: DCV Size: 0.75 Meter #: Manufacturer: Wilkins Model: 950xl

Serial: 1295725 Permit:  Containment  Isolation  Fire Protection

Location Comments: Fire Protection By-Pass in Meter Room

Shut Off Valve 1:  Closed  Leaked Shut Off Valve 2:  Closed  Leaked Line Pressure: 50 Initial Test Date: 04/20/2023

1st Check	2nd Check	Relief Valve	PVB/SVB Air Inlet	PVB/SVB Check Valve
<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input checked="" type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Did Not Open <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Failed	<input type="checkbox"/> Held <input type="checkbox"/> Failed
PSID: 2	PSID: 2.2	PSID: 0	PSID: 0	PSID: 0

Tester/Repair Comments:

Tester Name: Barrie Rudnick Testing Company: Complete Quality Construction & Maintenance LLC

Tester Cert #: 26042 Gauge Manufacturer: MIDWEST Gauge Model: 845-3 Gauge Serial #: 07143192 Calibration Date: 02/10/2023

1st Check	2nd Check	Relief Valve	PVB/SVB Air Inlet	PVB/SVB Check Valve
<input type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input type="checkbox"/> Closed <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Did Not Open <input type="checkbox"/> Leaked	<input type="checkbox"/> Opened <input type="checkbox"/> Failed	<input type="checkbox"/> Held <input type="checkbox"/> Failed
PSID: 0	PSID: 0	PSID: 0	PSID: 0	PSID: 0

Final Test Date: