

B Safe Security Yarnell Security Systems Choice Security Services Inspection Report

Customer DOC 4518 UNION DEPOSIT MOB LLC
 Address 4518 Union deposit Rd
 City Harrisburg, PA 17111
 Phone # _____
 C/S Account # MC 52898

System type: Fire Burg _____ Other _____

Period: Mths _____ Bi-Mthly _____ Qrtly _____ Semi - Ann _____ Ann

Zone	Smoke Det	Heat Det	Water Flow	Valve Super	Pull Station	Duct Det	Pump Running	Pump Super	Room Temp F	Other	Pass	Fail
32	X										X	
8	X										X	
43	X										X	
45					X						X	
37			X								X	
33	X										X	
32	X										X	
31						X					X	
30						X					X	
29						X					X	
27						X					X	
35				X							X	
36					X						X	
34					X						X	

Comments Service tested; smoke detectors, pull stations, water flows, valve tamper and communications. Service also replaced BG-12 pull station and 5, 12 volt / 7 Amp Hour Batteries.

Date 3 / 31 / 2023

Customer Name _____

Technician Name Randy D. Lewis Jr.

Customer Signature _____

Technician Signature [Signature]