

CUSTOMER NAME: Old Bridge Medical Office Building LLC
BUILDING NAME: 12083385 - Old Bridge Medical Office Building LLC
BUILDING ADDRESS: 2 Hospital Plaza Suite 495, OLD BRIDGE, NJ, 08857 , US
CONTACT NAME: Jason Brenner
CONTACT E-MAIL: jbrenner@landmarkleadership.com
CONTACT ROLE: Building Engineer
CONTACT PHONE: 7323369627
INSPECTION TYPE: Fire Alarm v2
FREQUENCY: Annual
WORK ORDER: 51941574
INSPECTION END DATE: 06/09/2022

INSPECTORS: John W Mall
INSPECTOR LICENSE: P00423
ACCOUNT NAME: Johnson Controls North America
OFFICE ADDRESS: 200 Forge Way Rockaway, NJ 07866
OFFICE PHONE: 9735864418
OFFICE LICENSE: P00423
TIMEZONE: GMT-04:00

FIRE ALARM INSPECTION REPORT

General Inspection Notes

- June 2022 Annual Test & Inspection of all accessible and contractual Fire Alarm Devices. Includes Battery and Panel checks for voltage, condition, age, charging circuits and load testing for all system Fire Alarm Panels & Boosters. Audio/ Visuals were tested and passed, and all priority one relay trips were also tested and passed. Johnson Controls Central Station Monitoring received all activated signals sent from Fire Alarm Panel. As always Customer should review entire Inspection Report for complete details.

Building Notes

- This was an annual test & inspection of your Fire Alarm Safety System.

 System outputs/auxiliary controls, i.e. elevator recall, HVAC/Fan Shutdown, Door Holders/Release and all signal/notification devices were tested and are operational unless otherwise noted in this report.

 Any Questions regarding this report should be directed to our Inspection Supervisor Joseph Pearce at (201) 230-0096

DEVICE DEFICIENCIES

No device deficiencies in this inspection.

INSPECTION RESULTS SUMMARY				
DEVICE TYPE	INVENTORY COUNT	PASSED	FAILED	CANNOT INSPECT
Alternate Elevator Recall	1	1	0	0
Annunciator	2	2	0	0
Battery	13	11	0	2
Duct Detector	8	8	0	0
Heat Detector	3	3	0	0
Panel	13	13	0	0
Primary Elevator Recall	1	1	0	0
Pull Station	21	21	0	0
Smoke Detector	214	214	0	0
Tamper Switch	12	0	0	0
Water Flow Switch	5	0	0	0
Horn/Strobe	5	5	0	0
Strobe	4	4	0	0
TOTAL	302	283	0	2

Panels/Initiating Devices

INSPECTION RESULTS SUMMARY				
DEVICE TYPE	INVENTORY COUNT	PASSED	FAILED	CANNOT INSPECT
Alternate Elevator Recall	1	1	0	0
Annunciator	2	2	0	0
Battery	13	11	0	2
Duct Detector	8	8	0	0
Heat Detector	3	3	0	0
Panel	13	13	0	0
Primary Elevator Recall	1	1	0	0
Pull Station	21	21	0	0
Smoke Detector	214	214	0	0
Tamper Switch	12	0	0	0
Water Flow Switch	5	0	0	0

FACP PANELS									
#	LOCATION	DESCRIPTION	MANUFACTURER	MODEL	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
1	—	1FL FACP Room (Edwards EST)	Edwards	EST	Panel	—	John W Mall	06/08/2022	Passed
Is the panel in a normal condition at the start of the inspection?									Yes
Alarm, Supervisory, and Trouble Signals (Inputs)									Yes
Circuit Supervisory (Including Opens, Shorts & Ground Faults)									Yes
Alarm verification sequence verified									Yes
POWER SUPPLY SUPV - LOSS OF AC POWER/BATTS									Yes
Fuses/Lamps/LED Tested & Verified									Yes
INTERFACE EQUIP VERIFICATION OF REQUIRED SIGNALS									Yes
MAIN POWER SUPPLY TESTED UNDER FULL LOAD									Yes
DOOR HOLDERS									Yes
REMOTE ANNUNCIATOR(S) - OPERATION/VERIFICATION									Yes
INITIATING DEVICES TEST									Yes
ELEVATOR RECALL FUNCTION & SHUNT TRIP OPERATION									Yes
HVAC SHUT DOWN									Yes
MASTERBOX / CENTRAL STATION CONNECTION TESTED									Yes
MASTERBOX / CENTRAL STATION ACCOUNT #									ACCT# 212-1353
ALARM NOTIFICATION APPLIANCES TESTED									Yes
MULTIPLEX COMMUNICATIONS TESTED									Yes
Primary Power- Nominal Voltage									120
Primary Power- Amps									2
Primary Power- Location									Electric Room
Primary Power- Overcurrent Protection Type/Amps									2
Disconnecting means location									Turn off breaker.

Panels/Initiating Devices

NAC PANELS									
#	LOCATION	DESCRIPTION	MANUFACTURER	MODEL	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
1	—	1FL FACP Room (#1)	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes
2	—	1FL FACP Room (#2)	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes
3	—	1FL FACP Room (#3)	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes
4	—	1FL FACP Room (#5)	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes
5	—	3FL Electric Room Bottom Left	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes

Panels/Initiating Devices

NAC PANELS									
#	LOCATION	DESCRIPTION	MANUFACTURER	MODEL	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
6	—	3FL Electric Room Bottom Right	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes
7	—	3FL Electric Room Middle	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes
8	—	3FL Electric Room Top	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes
9	—	4FL Electric Room Bottom Left	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes
10	—	4FL Electric Room Bottom Right	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes

Panels/Initiating Devices

NAC PANELS									
#	LOCATION	DESCRIPTION	MANUFACTURER	MODEL	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
11	—	4FL Electric Room Top Left	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes
12	—	4FL Electric Room Top Right	Edwards	IO500	Panel	—	John W Mall	06/08/2022	Passed
Lamps/LEDs/LCDs									Yes
Fuses									Yes
Primary Power Supply									Yes
Secondary Power Supply									Yes
Trouble Signals									Yes
Ground-fault monitoring									Yes
Panel supervision									Yes

BATTERIES							
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
1	—	1FL FACP Room (#1)	Battery	—	John W Mall	06/08/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							26.58
Voltage without charger							26.55
Load Voltage Test							Pass
Load Voltage Test Results (%)							95
2	—	1FL FACP Room (#2)	Battery	—	John W Mall	06/08/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							26.57
Voltage without charger							26.52
Load Voltage Test							Pass
Load Voltage Test Results (%)							90

Panels/Initiating Devices

BATTERIES							
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
3	—	1FL FACP Room (#3)	Battery	—	John W Mall	06/08/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							26.72
Voltage without charger							26.68
Load Voltage Test							Pass
Load Voltage Test Results (%)							90
4	—	1FL FACP Room (#5)	Battery	—	John W Mall	06/08/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							26.51
Voltage without charger							26.47
Load Voltage Test							Pass
Load Voltage Test Results (%)							90
5	—	1FL FACP Room Main FACP	Battery	—	John W Mall	06/08/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							18
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							27.91
Voltage without charger							26.70
Load Voltage Test							Pass
Load Voltage Test Results (%)							90
6	—	3FL Electric Room Bottom Left	Battery	—	John W Mall	06/09/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							26.54
Voltage without charger							26.51
Load Voltage Test							Pass
Load Voltage Test Results (%)							80

Panels/Initiating Devices

BATTERIES							
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
7	—	3FL Electric Room Bottom Right	Battery	—	John W Mall	06/09/2022	Cannot Inspect
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Reason cannot inspect: Previous Failure, New Replacement Batteries to be delivered to site this week and installed by Jason Brenner.							
8	—	3FL Electric Room Middle	Battery	—	John W Mall	06/09/2022	Cannot Inspect
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7.0
Reason cannot inspect: Previous Failure, New Replacement Batteries to be delivered to site this week and installed by Jason Brenner.							
9	—	3FL Electric Room Top	Battery	—	John W Mall	06/09/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							26.61
Voltage without charger							26.56
Load Voltage Test							Pass
Load Voltage Test Results (%)							80
10	—	4FL Electric Room Bottom Left	Battery	—	John W Mall	06/09/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							26.60
Voltage without charger							26.56
Load Voltage Test							Pass
Load Voltage Test Results (%)							80
11	—	4FL Electric Room Bottom Right	Battery	—	John W Mall	06/09/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							26.53
Voltage without charger							26.50
Load Voltage Test							Pass
Load Voltage Test Results (%)							80

Panels/Initiating Devices

BATTERIES							
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
12	—	4FL Electric Room Top Left	Battery	—	John W Mall	06/09/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							26.54
Voltage without charger							26.51
Load Voltage Test							Pass
Load Voltage Test Results (%)							80
13	—	4FL Electric Room Top Right	Battery	—	John W Mall	06/09/2022	Passed
Quantity (Enter 2 if answering for a set)							2
Amp hour rating							7
Visual inspection							Pass
Batteries less than 5 years?							Pass
Manufacturer Date Code							7/18
Voltage with charger							26.62
Voltage without charger							26.55
Load Voltage Test							Pass
Load Voltage Test Results (%)							80

SMOKE DETECTORS								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
1	—	1FL Corridor By 302B	1-048	Smoke Detector	—	John W Mall	06/09/2022	Passed
2	—	1FL Corridor By Data Closet	1-039	Smoke Detector	—	John W Mall	06/09/2022	Passed
3	—	1FL Corridor By Data Closet	1-040	Smoke Detector	—	John W Mall	06/09/2022	Passed
4	—	1FL Corridor By Electric Room 224	1-033	Smoke Detector	—	John W Mall	06/09/2022	Passed
5	—	1FL Corridor By Elevator MR	1-081	Smoke Detector	—	John W Mall	06/09/2022	Passed
6	—	1FL Corridor By Holding	1-036	Smoke Detector	—	John W Mall	06/09/2022	Passed
7	—	1FL Corridor By Registration	1-055	Smoke Detector	—	John W Mall	06/09/2022	Passed
8	—	1FL Corridor By Room 204	1-054	Smoke Detector	—	John W Mall	06/09/2022	Passed
9	—	1FL Corridor By Room 205	1-052	Smoke Detector	—	John W Mall	06/09/2022	Passed
10	—	1FL Corridor By Room 212	1-037	Smoke Detector	—	John W Mall	06/09/2022	Passed
11	—	1FL Corridor By Room 214	1-038	Smoke Detector	—	John W Mall	06/09/2022	Passed

Panels/Initiating Devices

SMOKE DETECTORS								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
12	—	1FL Corridor By Room 220	1-035	Smoke Detector	—	John W Mall	06/09/2022	Passed
13	—	1FL Corridor By Room 222	1-034	Smoke Detector	—	John W Mall	06/09/2022	Passed
14	—	1FL Corridor By Room 227	1-059	Smoke Detector	—	John W Mall	06/09/2022	Passed
15	—	1FL Corridor By Room 232	1-057	Smoke Detector	—	John W Mall	06/09/2022	Passed
16	—	1FL Corridor By Room 233A	1-060	Smoke Detector	—	John W Mall	06/09/2022	Passed
17	—	1FL Corridor By Room 239	1-053	Smoke Detector	—	John W Mall	06/09/2022	Passed
18	—	1FL Corridor By Room 243A	1-058	Smoke Detector	—	John W Mall	06/09/2022	Passed
19	—	1FL Corridor By Room 313A	1-056	Smoke Detector	—	John W Mall	06/09/2022	Passed
20	—	1FL Corridor By Stair 1	1-046	Smoke Detector	—	John W Mall	06/09/2022	Passed
21	—	1FL Corridor By Switch Gear Room	1-079	Smoke Detector	—	John W Mall	06/09/2022	Passed
22	—	1FL Corridor Suite 110	1-092	Smoke Detector	—	John W Mall	06/09/2022	Passed
23	—	1FL Corridor Suite 110	1-093	Smoke Detector	—	John W Mall	06/09/2022	Passed
24	—	1FL Corridor Suite 110	1-091	Smoke Detector	—	John W Mall	06/09/2022	Passed
25	—	1FL Corridor Suite 110	1-089	Smoke Detector	—	John W Mall	06/09/2022	Passed
26	—	1FL Corridor Suite 110	1-094	Smoke Detector	—	John W Mall	06/09/2022	Passed
27	—	1FL Data Room 213	1-041	Smoke Detector	—	John W Mall	06/09/2022	Passed
28	—	1FL East Entrance	1-043	Smoke Detector	—	John W Mall	06/09/2022	Passed
29	—	1FL Electric Room 107	1-072	Smoke Detector	—	John W Mall	06/09/2022	Passed
30	—	1FL Electric Room 108	1-074	Smoke Detector	—	John W Mall	06/09/2022	Passed
31	—	1FL Electric Room 224	1-073	Smoke Detector	—	John W Mall	06/09/2022	Passed
32	—	1FL Elevator 1 Lobby	1-044	Smoke Detector	—	John W Mall	06/09/2022	Passed
33	—	1FL Elevator 1 Rear Lobby	1-080	Smoke Detector	—	John W Mall	06/09/2022	Passed
34	—	1FL Elevator 2 Rear Lobby	1-042	Smoke Detector	—	John W Mall	06/09/2022	Passed
35	—	1FL Elevator Lobby 2&3	1-102	Smoke Detector	—	John W Mall	06/09/2022	Passed
36	—	1FL Elevator Lobby Area	1-045	Smoke Detector	—	John W Mall	06/09/2022	Passed
37	—	1FL Elevator MR 1	1-065	Smoke Detector	—	John W Mall	06/09/2022	Passed
38	—	1FL Elevator MR 1&2	1-088	Smoke Detector	—	John W Mall	06/09/2022	Passed
39	—	1FL Elevator MR 2&3	1-067	Smoke Detector	—	John W Mall	06/09/2022	Passed

Panels/Initiating Devices

SMOKE DETECTORS								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
40	—	1FL Fire Panel Room	1-071	Smoke Detector	—	John W Mall	06/09/2022	Passed
41	—	1FL Fire Pump Room	1-070	Smoke Detector	—	John W Mall	06/09/2022	Passed
42	—	1FL Fire Pump Room	1-069	Smoke Detector	—	John W Mall	06/09/2022	Passed
43	—	1FL Lobby 105	1-078	Smoke Detector	—	John W Mall	06/09/2022	Passed
44	—	1FL Lobby At East Vestibule	1-087	Smoke Detector	—	John W Mall	06/09/2022	Passed
45	—	1FL Mail Room 102	1-077	Smoke Detector	—	John W Mall	06/09/2022	Passed
46	—	1FL Mens Room	1-076	Smoke Detector	—	John W Mall	06/09/2022	Passed
47	—	1FL Nurse Station 318	1-050	Smoke Detector	—	John W Mall	06/09/2022	Passed
48	—	1FL Room 314	1-049	Smoke Detector	—	John W Mall	06/09/2022	Passed
49	—	1FL Room 318	1-051	Smoke Detector	—	John W Mall	06/09/2022	Passed
50	—	1FL Stair 1	1-061	Smoke Detector	—	John W Mall	06/09/2022	Passed
51	—	1FL Stair 2	1-062	Smoke Detector	—	John W Mall	06/09/2022	Passed
52	—	1FL Waiting Room Suite 110	1-090	Smoke Detector	—	John W Mall	06/09/2022	Passed
53	—	1FL West Entrance	1-047	Smoke Detector	—	John W Mall	06/09/2022	Passed
54	—	1FL Women's Room	1-075	Smoke Detector	—	John W Mall	06/09/2022	Passed
55	—	2FL Bridge	1-098	Smoke Detector	—	John W Mall	06/09/2022	Passed
56	—	2FL Bridge Hosp	1-106	Smoke Detector	—	John W Mall	06/09/2022	Passed
57	—	2FL Corridor By Double Doors	1-023	Smoke Detector	—	John W Mall	06/09/2022	Passed
58	—	2FL Corridor By Exam Room 105	1-063	Smoke Detector	—	John W Mall	06/09/2022	Passed
59	—	2FL Corridor By Fire Doors	1-014	Smoke Detector	—	John W Mall	06/09/2022	Passed
60	—	2FL Corridor By Fire Doors	1-017	Smoke Detector	—	John W Mall	06/09/2022	Passed
61	—	2FL Corridor By Fire Doors	1-031	Smoke Detector	—	John W Mall	06/09/2022	Passed
62	—	2FL Corridor By Locker Room	1-021	Smoke Detector	—	John W Mall	06/09/2022	Passed
63	—	2FL Corridor By Room 107	1-032	Smoke Detector	—	John W Mall	06/09/2022	Passed
64	—	2FL Corridor By Room 303	1-009	Smoke Detector	—	John W Mall	06/09/2022	Passed
65	—	2FL Corridor By Room 309	1-008	Smoke Detector	—	John W Mall	06/09/2022	Passed
66	—	2FL Corridor By Room 311A	1-006	Smoke Detector	—	John W Mall	06/09/2022	Passed
67	—	2FL Corridor By Room 311B	1-028	Smoke Detector	—	John W Mall	06/09/2022	Passed
68	—	2FL Corridor By Room 311B	1-086	Smoke Detector	—	John W Mall	06/09/2022	Passed
69	—	2FL Corridor By Room 312	1-082	Smoke Detector	—	John W Mall	06/09/2022	Passed

Panels/Initiating Devices

SMOKE DETECTORS								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
70	—	2FL Corridor By Room 408	1-029	Smoke Detector	—	John W Mall	06/09/2022	Passed
71	—	2FL Corridor By Room 413A	1-030	Smoke Detector	—	John W Mall	06/09/2022	Passed
72	—	2FL Corridor By Room 419A	1-027	Smoke Detector	—	John W Mall	06/09/2022	Passed
73	—	2FL Corridor By Room 422	1-025	Smoke Detector	—	John W Mall	06/09/2022	Passed
74	—	2FL Corridor By Room 423	1-026	Smoke Detector	—	John W Mall	06/09/2022	Passed
75	—	2FL Corridor By Room 427	1-024	Smoke Detector	—	John W Mall	06/09/2022	Passed
76	—	2FL Corridor By Room 600	1-019	Smoke Detector	—	John W Mall	06/09/2022	Passed
77	—	2FL Corridor By Room 602	1-016	Smoke Detector	—	John W Mall	06/09/2022	Passed
78	—	2FL Corridor By Room 608	1-011	Smoke Detector	—	John W Mall	06/09/2022	Passed
79	—	2FL Corridor By Room 612	1-013	Smoke Detector	—	John W Mall	06/09/2022	Passed
80	—	2FL Corridor By Room 612	1-012	Smoke Detector	—	John W Mall	06/09/2022	Passed
81	—	2FL Corridor By Room 612	1-010	Smoke Detector	—	John W Mall	06/09/2022	Passed
82	—	2FL Corridor By Stair 2	1-018	Smoke Detector	—	John W Mall	06/09/2022	Passed
83	—	2FL Corridor By Suite 503	1-005	Smoke Detector	—	John W Mall	06/09/2022	Passed
84	—	2FL Corridor To Hospital	1-020	Smoke Detector	—	John W Mall	06/09/2022	Passed
85	—	2FL Corridor West	1-001	Smoke Detector	—	John W Mall	06/09/2022	Passed
86	—	2FL Corridor West	1-003	Smoke Detector	—	John W Mall	06/09/2022	Passed
87	—	2FL Corridor West By Bridge	1-002	Smoke Detector	—	John W Mall	06/09/2022	Passed
88	—	2FL Corridor West By Doors	1-004	Smoke Detector	—	John W Mall	06/09/2022	Passed
89	—	2FL Data Closet 507	1-064	Smoke Detector	—	John W Mall	06/09/2022	Passed
90	—	2FL Elevator 1 Rear Lobby	1-104	Smoke Detector	—	John W Mall	06/09/2022	Passed
91	—	2FL Elevator Lobby 1	1-101	Smoke Detector	—	John W Mall	06/09/2022	Passed
92	—	2FL Elevator Lobby 2&3	1-100	Smoke Detector	—	John W Mall	06/09/2022	Passed
93	—	2FL Elevator Lobby Vestibule	1-095	Smoke Detector	—	John W Mall	06/09/2022	Passed
94	—	2FL Lobby By 504	1-103	Smoke Detector	—	John W Mall	06/09/2022	Passed
95	—	2FL Main Lobby	1-015	Smoke Detector	—	John W Mall	06/09/2022	Passed
96	—	2FL PACU 311A	1-085	Smoke Detector	—	John W Mall	06/09/2022	Passed
97	—	2FL PACU Nurses Station	1-084	Smoke Detector	—	John W Mall	06/09/2022	Passed

Panels/Initiating Devices

SMOKE DETECTORS								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
98	—	2FL Room 324	1-083	Smoke Detector	—	John W Mall	06/09/2022	Passed
99	—	2FL Stair 1	1-022	Smoke Detector	—	John W Mall	06/09/2022	Passed
100	—	2FL Stair 2 Landing	1-007	Smoke Detector	—	John W Mall	06/08/2022	Passed
101	—	3FL 3rd Floor Suite 330 Rear Corridor by Room 3312	2-113	Smoke Detector	—	John W Mall	06/08/2022	Passed
102	—	3FL 310 Corridor By Reception	2-053	Smoke Detector	—	John W Mall	06/08/2022	Passed
103	—	3FL 310 Corridor By Xray Room	2-052	Smoke Detector	—	John W Mall	06/08/2022	Passed
104	—	3FL 310 Main Corridor 3110	2-095	Smoke Detector	—	John W Mall	06/08/2022	Passed
105	—	3FL 310 Main Corridor 3114	2-094	Smoke Detector	—	John W Mall	06/08/2022	Passed
106	—	3FL 310 Staff Lounge	2-096	Smoke Detector	—	John W Mall	06/08/2022	Passed
107	—	3FL 310 Waiting Room 3101	2-097	Smoke Detector	—	John W Mall	06/08/2022	Passed
108	—	3FL 320 3201 Waiting Room	2-114	Smoke Detector	—	John W Mall	06/08/2022	Passed
109	—	3FL 320 3203 Data Closet	2-116	Smoke Detector	—	John W Mall	06/08/2022	Passed
110	—	3FL 320 3204 Corridor	2-115	Smoke Detector	—	John W Mall	06/08/2022	Passed
111	—	3FL 320 3208 Kitchen	2-117	Smoke Detector	—	John W Mall	06/08/2022	Passed
112	—	3FL 330 Waiting Room by Door	2-109	Smoke Detector	—	John W Mall	06/08/2022	Passed
113	—	3FL 340 Corridor By Patient Bath	2-091	Smoke Detector	—	John W Mall	06/08/2022	Passed
114	—	3FL Charting 3-410	2-061	Smoke Detector	—	John W Mall	06/08/2022	Passed
115	—	3FL Clean Linen 305	2-073	Smoke Detector	—	John W Mall	06/08/2022	Passed
116	—	3FL Corr 300A	2-079	Smoke Detector	—	John W Mall	06/08/2022	Passed
117	—	3FL Corridor 300H	2-081	Smoke Detector	—	John W Mall	06/08/2022	Passed
118	—	3FL Corridor 300 H By 307	2-084	Smoke Detector	—	John W Mall	06/08/2022	Passed
119	—	3FL Corridor 300 H By 307	2-082	Smoke Detector	—	John W Mall	06/08/2022	Passed
120	—	3FL Corridor 300 H By 400	2-083	Smoke Detector	—	John W Mall	06/08/2022	Passed
121	—	3FL Corridor 300K	2-080	Smoke Detector	—	John W Mall	06/08/2022	Passed
122	—	3FL Corridor At Doors 500	2-058	Smoke Detector	—	John W Mall	06/08/2022	Passed
123	—	3FL Corridor At Fire Door	2-069	Smoke Detector	—	John W Mall	06/08/2022	Passed
124	—	3FL Corridor At Reception	2-059	Smoke Detector	—	John W Mall	06/08/2022	Passed
125	—	3FL Corridor Before Door	2-070	Smoke Detector	—	John W Mall	06/08/2022	Passed

Panels/Initiating Devices

SMOKE DETECTORS								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
126	—	3FL Corridor By 410	2-066	Smoke Detector	—	John W Mall	06/08/2022	Passed
127	—	3FL Corridor By Bathrooms	2-056	Smoke Detector	—	John W Mall	06/08/2022	Passed
128	—	3FL Corridor By Data Closet	2-087	Smoke Detector	—	John W Mall	06/08/2022	Passed
129	—	3FL Corridor By Exam #1	2-093	Smoke Detector	—	John W Mall	06/08/2022	Passed
130	—	3FL Corridor By Exam #4	2-092	Smoke Detector	—	John W Mall	06/08/2022	Passed
131	—	3FL Corridor By Exam Room	2-060	Smoke Detector	—	John W Mall	06/08/2022	Passed
132	—	3FL Corridor By Medical Storage	2-067	Smoke Detector	—	John W Mall	06/08/2022	Passed
133	—	3FL Corridor By Staff Bath	2-064	Smoke Detector	—	John W Mall	06/08/2022	Passed
134	—	3FL Corridor By Staff Bath	2-065	Smoke Detector	—	John W Mall	06/08/2022	Passed
135	—	3FL Corridor By Stair	2-072	Smoke Detector	—	John W Mall	06/08/2022	Passed
136	—	3FL Corridor By Suite 3-100	2-057	Smoke Detector	—	John W Mall	06/08/2022	Passed
137	—	3FL Corridor CNTR Hall	2-071	Smoke Detector	—	John W Mall	06/08/2022	Passed
138	—	3FL Corridor CNTR To Door	2-068	Smoke Detector	—	John W Mall	06/08/2022	Passed
139	—	3FL Corridor North	2-046	Smoke Detector	—	John W Mall	06/08/2022	Passed
140	—	3FL Corridor North	2-048	Smoke Detector	—	John W Mall	06/08/2022	Passed
141	—	3FL Electric Room 300	2-050	Smoke Detector	—	John W Mall	06/08/2022	Passed
142	—	3FL Elevator Lobby PE1/PE2	2-085	Smoke Detector	—	John W Mall	06/08/2022	Passed
143	—	3FL Elevator Lobby SE1	2-086	Smoke Detector	—	John W Mall	06/08/2022	Passed
144	—	3FL Elevator Lobby Vestibule	2-049	Smoke Detector	—	John W Mall	06/08/2022	Passed
145	—	3FL Janitor Closet 305	2-047	Smoke Detector	—	John W Mall	06/08/2022	Passed
146	—	3FL Men's Room	2-055	Smoke Detector	—	John W Mall	06/08/2022	Passed
147	—	3FL Nurse Control	2-077	Smoke Detector	—	John W Mall	06/08/2022	Passed
148	—	3FL Nurse Station 407	2-062	Smoke Detector	—	John W Mall	06/08/2022	Passed
149	—	3FL PACU By Iso Room 1	2-063	Smoke Detector	—	John W Mall	06/08/2022	Passed
150	—	3FL Semi Restrict Corridor	2-074	Smoke Detector	—	John W Mall	06/08/2022	Passed
151	—	3FL Semi Restrict Corridor	2-076	Smoke Detector	—	John W Mall	06/08/2022	Passed
152	—	3FL Semi Restrict Corridor	2-078	Smoke Detector	—	John W Mall	06/08/2022	Passed
153	—	3FL Stair 1	2-054	Smoke Detector	—	John W Mall	06/08/2022	Passed

Panels/Initiating Devices

SMOKE DETECTORS								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
154	—	3FL Stair 2	1-096	Smoke Detector	—	John W Mall	06/08/2022	Passed
155	—	3FL Stretcher Alcove	2-075	Smoke Detector	—	John W Mall	06/08/2022	Passed
156	—	3FL Suite 330 Corridor By Reception	2-111	Smoke Detector	—	John W Mall	06/08/2022	Passed
157	—	3FL Suite 330 Corridor By Room 3309	2-112	Smoke Detector	—	John W Mall	06/08/2022	Passed
158	—	3FL Suite 330 Waiting Room By Receptionist	2-110	Smoke Detector	—	John W Mall	06/08/2022	Passed
159	—	3FL Women's Room	2-045	Smoke Detector	—	John W Mall	06/08/2022	Passed
160	—	4FL 42 Outside Demo Storage	2-099	Smoke Detector	—	John W Mall	06/08/2022	Passed
161	—	4FL 420 By Soiled Holding	2-105	Smoke Detector	—	John W Mall	06/08/2022	Passed
162	—	4FL 420 Corridor 4-200	2-100	Smoke Detector	—	John W Mall	06/08/2022	Passed
163	—	4FL 420 Corridor 4-200A	2-108	Smoke Detector	—	John W Mall	06/08/2022	Passed
164	—	4FL 420 Corridor 4-200C	2-104	Smoke Detector	—	John W Mall	06/08/2022	Passed
165	—	4FL 420 Hall By 4-212	2-107	Smoke Detector	—	John W Mall	06/08/2022	Passed
166	—	4FL 420 Hall By 4-214	2-106	Smoke Detector	—	John W Mall	06/08/2022	Passed
167	—	4FL 420 Hall By Conference Room	2-098	Smoke Detector	—	John W Mall	06/08/2022	Passed
168	—	4FL 420 Hall By Exam Room 2	2-102	Smoke Detector	—	John W Mall	06/08/2022	Passed
169	—	4FL 420 Hall By Exam Room 4	2-103	Smoke Detector	—	John W Mall	06/08/2022	Passed
170	—	4FL 420 Hall By Managers Office	2-101	Smoke Detector	—	John W Mall	06/09/2022	Passed
171	—	4FL 420 Waste Holding 4-217	2-153	Smoke Detector	—	John W Mall	06/09/2022	Passed
172	—	4FL 480 4801 Waiting Room	2-119	Smoke Detector	—	John W Mall	06/08/2022	Passed
173	—	4FL 480 4801 Waiting Room	1-118	Smoke Detector	—	John W Mall	06/08/2022	Passed
174	—	4FL Core Data/Elec Room	2-044	Smoke Detector	—	John W Mall	06/08/2022	Passed
175	—	4FL Corridor By Stair 2	2-016	Smoke Detector	—	John W Mall	06/08/2022	Passed
176	—	4FL Corridor By Suite 410	2-008	Smoke Detector	—	John W Mall	06/08/2022	Passed
177	—	4FL Corridor By Suite 410	2-007	Smoke Detector	—	John W Mall	06/08/2022	Passed
178	—	4FL Corridor By Suite 430	2-009	Smoke Detector	—	John W Mall	06/08/2022	Passed
179	—	4FL Corridor By Suite 430	2-010	Smoke Detector	—	John W Mall	06/08/2022	Passed

Panels/Initiating Devices

SMOKE DETECTORS								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
180	—	4FL Corridor By Suite 450	2-011	Smoke Detector	—	John W Mall	06/08/2022	Passed
181	—	4FL Corridor By Suite 470	2-012	Smoke Detector	—	John W Mall	06/08/2022	Passed
182	—	4FL Corridor By Suite 480	2-014	Smoke Detector	—	John W Mall	06/08/2022	Passed
183	—	4FL Corridor By Suite 480	2-013	Smoke Detector	—	John W Mall	06/08/2022	Passed
184	—	4FL Corridor By Suite 490	2-015	Smoke Detector	—	John W Mall	06/08/2022	Passed
185	—	4FL Corridor By Suite 4711	2-022	Smoke Detector	—	John W Mall	06/08/2022	Passed
186	—	4FL Elevator Lobby PE1/PE2	2-089	Smoke Detector	—	John W Mall	06/08/2022	Passed
187	—	4FL Elevator Lobby SE1	2-088	Smoke Detector	—	John W Mall	06/08/2022	Passed
188	—	4FL Elevator Lobby Vestibule	2-006	Smoke Detector	—	John W Mall	06/08/2022	Passed
189	—	4FL Elevator Shaft PE1	2-004	Smoke Detector	—	John W Mall	06/09/2022	Passed
190	—	4FL Elevator Shaft PE2	2-003	Smoke Detector	—	John W Mall	06/09/2022	Passed
191	—	4FL Elevator Shaft SE1	2-002	Smoke Detector	—	John W Mall	06/09/2022	Passed
192	—	4FL Lobby Corridor North	2-005	Smoke Detector	—	John W Mall	06/08/2022	Passed
193	—	4FL Men's Bath 403	2-036	Smoke Detector	—	John W Mall	06/08/2022	Passed
194	—	4FL Stair 1	2-001	Smoke Detector	—	John W Mall	06/08/2022	Passed
195	—	4FL Stair 2	1-097	Smoke Detector	—	John W Mall	06/08/2022	Passed
196	—	4FL Suite 410 By 4106	2-034	Smoke Detector	—	John W Mall	06/08/2022	Passed
197	—	4FL Suite 410 By Bathroom	2-031	Smoke Detector	—	John W Mall	06/08/2022	Passed
198	—	4FL Suite 410 By Reception	2-033	Smoke Detector	—	John W Mall	06/08/2022	Passed
199	—	4FL Suite 410 Waiting	2-032	Smoke Detector	—	John W Mall	06/08/2022	Passed
200	—	4FL Suite 430 Corridor	2-028	Smoke Detector	—	John W Mall	06/08/2022	Passed
201	—	4FL Suite 430 Corridor	2-027	Smoke Detector	—	John W Mall	06/08/2022	Passed
202	—	4FL Suite 430 Corridor	2-026	Smoke Detector	—	John W Mall	06/08/2022	Passed
203	—	4FL Suite 430 Room 4309	2-029	Smoke Detector	—	John W Mall	06/08/2022	Passed
204	—	4FL Suite 430 Waiting	2-030	Smoke Detector	—	John W Mall	06/08/2022	Passed
205	—	4FL Suite 450 Corridor	2-024	Smoke Detector	—	John W Mall	06/08/2022	Passed
206	—	4FL Suite 450 Waiting	2-025	Smoke Detector	—	John W Mall	06/08/2022	Passed

Panels/Initiating Devices

SMOKE DETECTORS								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
207	—	4FL Suite 470 Regist.	2-021	Smoke Detector	—	John W Mall	06/08/2022	Passed
208	—	4FL Suite 470 Room 4705	2-023	Smoke Detector	—	John W Mall	06/08/2022	Passed
209	—	4FL Suite 470 Waiting	2-020	Smoke Detector	—	John W Mall	06/08/2022	Passed
210	—	4FL Suite 490 Corridor	2-018	Smoke Detector	—	John W Mall	06/08/2022	Passed
211	—	4FL Suite 490 Corridor	2-118	Smoke Detector	—	John W Mall	06/08/2022	Passed
212	—	4FL Suite 490 RM 4906	2-019	Smoke Detector	—	John W Mall	06/08/2022	Passed
213	—	4FL Suite 490 Waiting	2-017	Smoke Detector	—	John W Mall	06/08/2022	Passed
214	—	4FL Women's Bathroom 404	2-035	Smoke Detector	—	John W Mall	06/08/2022	Passed

DUCT DETECTORS								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
1	—	4FL RTU-1 Return Corridor By 480	2-037	Duct Detector	—	John W Mall	06/08/2022	Passed
2	—	4FL RTU-1 Supply Corridor By 480	2-038	Duct Detector	—	John W Mall	06/08/2022	Passed
3	—	4FL RTU-2 Return Corridor By 450	2-040	Duct Detector	—	John W Mall	06/08/2022	Passed
4	—	4FL RTU-2 Supply Corridor By 450	2-039	Duct Detector	—	John W Mall	06/08/2022	Passed
5	—	4FL RTU-4 Return Closet Space By 410	2-051	Duct Detector	—	John W Mall	06/08/2022	Passed
6	—	4FL RTU-4 Supply Corridor By 410	2-043	Duct Detector	—	John W Mall	06/08/2022	Passed
7	—	RTU-3 Return Corridor By 430	2-042	Duct Detector	—	John W Mall	06/08/2022	Passed
8	—	RTU-3 Supply Corridor By 430	2-041	Duct Detector	—	John W Mall	06/08/2022	Passed

CONNECTED DEVICES								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
1	—	1FL Corridor By Switchgear Room	1-133	Pull Station	—	John W Mall	06/09/2022	Passed
2	—	1FL East Vestibule	1-131	Pull Station	—	John W Mall	06/09/2022	Passed
3	—	1FL Electric Room	1-130	Pull Station	—	John W Mall	06/09/2022	Passed
4	—	1FL Elevator MR 1	1-066	Heat Detector	—	John W Mall	06/09/2022	Passed
5	—	1FL Elevator MR 2&3	1-068	Heat Detector	—	John W Mall	06/09/2022	Passed
6	—	1FL Elevator MR Car 1	1-099	Heat Detector	—	John W Mall	06/09/2022	Passed
7	—	1FL Fire Panel Room	1-129	Pull Station	—	John W Mall	06/09/2022	Passed
8	—	1FL Fire Pump Room	1-128	Pull Station	—	John W Mall	06/09/2022	Passed

Panels/Initiating Devices

CONNECTED DEVICES								
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
9	—	1FL Lobby East	—	Annunciator	—	John W Mall	06/08/2022	Passed
10	—	1FL Lobby West	—	Annunciator	—	John W Mall	06/08/2022	Passed
11	—	1FL Outpatient 103	1-172	Pull Station	—	John W Mall	06/09/2022	Passed
12	—	1FL South East Exit	1-189	Pull Station	—	John W Mall	06/09/2022	Passed
13	—	1FL Stair 2	1-179	Pull Station	—	John W Mall	06/09/2022	Passed
14	—	1FL West Vestibule	1-132	Pull Station	—	John W Mall	06/09/2022	Passed
15	—	1st fl stsr2	—	Tamper Switch	—	—	—	Not Inspected
16	—	2FL Bridge	1-173	Pull Station	—	John W Mall	06/09/2022	Passed
17	—	2FL Stair 1	1-126	Pull Station	—	John W Mall	06/09/2022	Passed
18	—	2FL Stair 2	1-127	Pull Station	—	John W Mall	06/09/2022	Passed
19	—	2nd fl stair	—	Tamper Switch	—	—	—	Not Inspected
20	—	3FL 340 Corridor By Clean Up	2-090	Pull Station	—	John W Mall	06/08/2022	Passed
21	—	3FL 340 Corridor Rear Exit	2-148	Pull Station	—	John W Mall	06/08/2022	Passed
22	—	3FL 340 Waiting Area	2-147	Pull Station	—	John W Mall	06/08/2022	Passed
23	—	3FL Stair 1	2-135	Pull Station	—	John W Mall	06/08/2022	Passed
24	—	3FL Stair 2	1-188	Pull Station	—	John W Mall	06/08/2022	Passed
25	—	3fl stsr2	—	Tamper Switch	—	—	—	Not Inspected
26	—	4FL 420 Corridor 4-300	2-151	Pull Station	—	John W Mall	06/08/2022	Passed
27	—	4FL 420 Waiting Area 4-100	2-152	Pull Station	—	John W Mall	06/08/2022	Passed
28	—	4FL Stair 1	2-134	Pull Station	—	John W Mall	06/08/2022	Passed
29	—	4fl stair 2	—	Tamper Switch	—	—	—	Not Inspected
30	—	4FL Stair 2	2-133	Pull Station	—	John W Mall	06/08/2022	Passed
31	—	Alternate Elevator Recall	—	Alternate Elevator Recall	—	John W Mall	06/09/2022	Passed
32	—	Primary Elevator Recall	—	Primary Elevator Recall	—	John W Mall	06/09/2022	Passed
33	—	Pump rm bfly	—	Tamper Switch	—	—	—	Not Inspected
34	—	Pump rm bfly	—	Tamper Switch	—	—	—	Not Inspected
35	—	Pump rm bfly	—	Tamper Switch	—	—	—	Not Inspected
36	—	Pump rm bfly	—	Tamper Switch	—	—	—	Not Inspected
37	—	Pump rm bfly	—	Tamper Switch	—	—	—	Not Inspected
38	—	Pump rm bfly	—	Tamper Switch	—	—	—	Not Inspected
39	—	Pump rm osy	—	Tamper Switch	—	—	—	Not Inspected
40	—	Pump rm osy	—	Tamper Switch	—	—	—	Not Inspected

Panels/Initiating Devices

WATER FLOW DEVICES							
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
1	—	Pump rm	Water Flow Switch	—	—	—	Not Inspected
2	—	Stair well1 1st fl	Water Flow Switch	—	—	—	Not Inspected
3	—	Stair well1. 2nd fl	Water Flow Switch	—	—	—	Not Inspected
4	—	Stair well1 3rd fl	Water Flow Switch	—	—	—	Not Inspected
5	—	Stair well1. 4th fl	Water Flow Switch	—	—	—	Not Inspected

Notification Devices

INSPECTION RESULTS SUMMARY				
DEVICE TYPE	INVENTORY COUNT	PASSED	FAILED	CANNOT INSPECT
Horn/Strobe	5	5	0	0
Strobe	4	4	0	0

AUDIBLE VISIBLE DEVICES W/DB							
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
1	—	1FL All Horn/Strobes	Horn/Strobe	—	John W Mall	06/09/2022	Passed
2	—	1FL Outside Building All Horns & Strobes	Horn/Strobe	—	John W Mall	06/09/2022	Passed
3	—	2FL All Horn/Strobes	Horn/Strobe	—	John W Mall	06/09/2022	Passed
4	—	3FL All Horn/Strobes	Horn/Strobe	—	John W Mall	06/09/2022	Passed
5	—	4FL All Horn/Strobes	Horn/Strobe	—	John W Mall	06/09/2022	Passed

DEVICES							
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT
1	—	1FL All Strobes	Strobe	—	John W Mall	06/09/2022	Passed
2	—	2FL All Strobes	Strobe	—	John W Mall	06/09/2022	Passed
3	—	3FL All Strobes	Strobe	—	John W Mall	06/09/2022	Passed
4	—	4FL All Strobes	Strobe	—	John W Mall	06/09/2022	Passed

General Deficiencies and Recommendations

1.	List of other deficiencies you have found during this inspection	Not Applicable
2.	Recommendations noted and explained to the customer.	Not Applicable

Inspector Signature _____ <i>John W. Mall</i>	Inspector Name _____ John W. Mall	Date _____ 06/09/2022
Signature of the Building Engineer _____ <i>JASON BRENNER No SIGN COVID-19 RESTRICTIONS</i>	Printed name of the Building Engineer _____ Jason Brenner	Date _____ 06/09/2022

TERMS AND CONDITIONS

- 1. Limitation of Liability; Limitations Of Remedy.** It is understood and agreed by the Customer that Company is not an insurer and that insurance coverage, if any, shall be obtained by the Customer and that amounts payable to Company hereunder are based upon the value of the services and the scope of liability set forth in this agreement and are unrelated to the value of the Customer's property and the property of others located on the premises. Customer agrees to look exclusively to the Customer's insurer to recover for injuries or damage in the event of any loss or injury and that Customer releases and waives all right of recovery against Company arising by way of subrogation. Company makes no guaranty or Warranty, including any implied warranty of merchantability or fitness for a particular purpose that equipment or services supplied by Company will detect or avert occurrences or the consequences there from that the equipment or service was designed to detect or avert.

It is impractical and extremely difficult to fix the actual damages, if any, which may proximately result from failure on the part of Company to perform any of its obligations under this agreement. Accordingly, Customer agrees that, Company shall be exempt from liability for any loss, damage or injury arising directly or indirectly from occurrences, or the consequences therefrom, which the equipment or service was designed to detect or avert. Should Company be found liable for any loss, damage or injury arising from a failure of the equipment or service in any respect, Company's liability shall be limited to an amount equal to the agreement price (as increased by the price for any additional work) or where the time and material payment term is selected, Customer's time and material payments to Company. Where this agreement covers multiple sites, liability shall be limited to the amount of the payments allocable to the site where the incident occurred. Such sum shall be complete and exclusive. If Customer desires Company to assume greater liability, the parties shall amend this agreement by attaching a rider setting forth the amount of additional liability and the additional amount payable by the Customer for the assumption by Company of such greater liability, provided however that such rider shall in no way be interpreted to hold Company as an insurer. **IN NO EVENT SHALL COMPANY BE LIABLE FOR ANY DAMAGE, LOSS, INJURY, OR ANY OTHER CLAIM ARISING FROM ANY SERVICING, ALTERATIONS, MODIFICATIONS, CHANGES, OR MOVEMENTS OF THE COVERED SYSTEM(S) OR ANY OF ITS COMPONENT PARTS BY THE CUSTOMER OR ANY THIRD PARTY. COMPANY SHALL NOT BE LIABLE FOR INDIRECT, INCIDENTAL OR CONSEQUENTIAL DAMAGES OF ANY KIND, INCLUDING BUT NOT LIMITED TO DAMAGES ARISING FROM THE USE, LOSS OF THE USE, PERFORMANCE, OR FAILURE OF THE COVERED SYSTEM(S) TO PERFORM.** The limitations of liability set forth in this agreement shall inure to the benefit of all parents, subsidiaries and affiliates of Company, whether direct or indirect, Company's employees, agents, officers and directors.

- 2. Limited Warranty.** COMPANY WARRANTS THAT ITS WORKMANSHIP AND MATERIAL FURNISHED UNDER THIS AGREEMENT WILL BE FREE FROM DEFECTS FOR A PERIOD OF NINETY (90) DAYS FROM THE DATE OF FURNISHING. Where Company provides product or equipment of others, Company will warrant the product or equipment only to the extent warranted by such third party. EXCEPT AS EXPRESSLY SET FORTH HEREIN, COMPANY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO THE SERVICES PERFORMED OR THE PRODUCTS, SYSTEMS OR EQUIPMENT, IF ANY, SUPPORTED HEREUNDER. COMPANY MAKES NO WARRANTY OR REPRESENTATION, AND UNDERTAKES NO OBLIGATION TO ENSURE BY THE SERVICES PERFORMED UNDER THIS AGREEMENT, THAT COMPANY'S PRODUCTS OR THE SYSTEMS OR EQUIPMENT OF THE CUSTOMER WILL CORRECTLY HANDLE THE PROCESSING OF CALENDAR DATES BEFORE OR AFTER DECEMBER 31, 1999.
- 3. Indemnity.** Customer agrees to indemnify, hold harmless and defend Company against any and all losses, damages, costs, including expert fees and costs, and expenses including reasonable defense costs, arising from any and all third party claims for personal injury, death, property damage or economic loss, including specifically any damages resulting from the exposure of workers to Hazardous Conditions whether or not Customer pre-notifies Company of the existence of said hazardous conditions, arising in any way from any act or omission of Customer or Company relating in any way to this agreement, including but not limited to the Services under this agreement, whether such claims are based upon contract, warranty, tort (including but not limited to active or passive negligence), strict liability or otherwise. Company reserves the right to select counsel to represent it in any such action.
- 4. Hazardous Materials.** Customer represents that, except to the extent that Company has been given written notice of the following hazards prior to the execution of this agreement, to the best of Customer's knowledge there is no:
 - o "permit confined space," as defined by OSHA, or space in which work must be performed that, because of its construction, location, contents or work activity therein, accumulation of a hazardous gas, vapour, dust or fume or the creation of an ox
 - o risk of infectious disease,
 - o need for air monitoring, respiratory protection, or other medical risk
 - o asbestos, asbestos-containing material, formaldehyde or other potentially toxic or otherwise hazardous material contained in or on the surface of the floors, walls, ceilings, insulation or other structural components of the area of any building

All of the above are hereinafter referred to as "Hazardous Conditions". Company shall have the right to rely on the representations listed above. If hazardous conditions are encountered by Company during the course of Company's work, the discovery of such conditions shall constitute an event beyond Company's control and Company shall have no obligation to further perform in the area where the hazardous conditions exist until the area has been made safe by Customer as certified in writing by an independent testing agency, and Customer shall pay disruption expenses and re-mobilization expenses as determined by Company. This agreement does not provide for the cost of capture, containment or disposal of any hazardous waste materials, or hazardous materials, encountered in any of the Covered System(s) and/or during performance of the Services. Said materials shall at all times remain the responsibility and property of Customer. Company shall not be responsible for the testing, removal or disposal of such hazardous materials.

- 5. Equipment Disconnections.** This represents Company's notice to you that the system(s)/device(s) listed on the face of this agreement as temporarily or permanently disconnected are no longer in service and, thus, cannot detect, perform and/or report oc
- 6. General.** Unless otherwise specified, work shall be performed during company's regular business hours,, exclusive of Saturdays, Sundays and Company holidays. All work is subject to review and rebilling in accordance with the terms and conditions of Customer's agreement/contract with Company, if one is in effect. Company shall not be responsible for failure to render services due to causes beyond its control, including but not limited to material shortages, work stoppages, fires, civil disobedience or unrest, severe weather, fire or any other cause beyond the control of Company. Customer is aware that the Limitation of Liability and other provisions set forth in any existing agreement/contract, if one is in effect, or set forth above, apply to services performed and materials supplied. The terms of this agreement shall govern notwithstanding any inconsistent or additional terms and conditions in any purchase order or other document submitted by Customer.

DEVICE NOTE IMAGE APPENDICES