

- New
- Existing
- Removed
- Replacement

BACKFLOW ASSEMBLY TEST REPORT

Property Owner **DOC-1710 N Randall Rd MOB, LLC**

Mailing Address **1710 N Randall Rd Elgin, IL 60123**

Phone: **866-322-4547**

Assembly Address **1710 N Randall Rd Elgin, IL 60123**

R.P.B.A. D.C.V.A. R.P.D.A. D.C.D.A. P.V.B.A. S.V.B.A. A.V.B. AIR GAP

SIZE: **3/4"** MAKE: **Wilkins**

MODEL: **950 XL**

Syncta ID **S512-759BJ**

Serial # **2163666 XLD**

Assembly Location: **Sprinkler room on north side of building**

INITIAL TEST RESULTS	REDUCED PRESSURE ASSEMBLY	DOUBLE CHECK	P.V.B.A. / S.V.B.A.		INITIAL TEST PASSED <input checked="" type="checkbox"/> FAILED <input type="checkbox"/> DATE 01/25/23 SYSTEM PSI _____
	#1 CHECK PRESS DROP _____ (A) RELIEF VALVE OPENED AT _____ (B) MIN 2 PSID BUFFER A - B = _____ MIN 3 PSI	CHECK #1 TIGHT <input checked="" type="checkbox"/> 2.2 LEAKED <input type="checkbox"/> PSID CHECK #2 TIGHT <input checked="" type="checkbox"/> 2.0 LEAKED <input type="checkbox"/> PSID	AIR INLET OPENED AT PSDI DID NOT OPEN <input type="checkbox"/>	CHECK PRESS DROP PSDI FAILED <input type="checkbox"/>	
BYPASS CHECK	RELIEF VALVE PASS <input type="checkbox"/> FAIL <input type="checkbox"/>				

COMMENTS
REPAIRS
AND/OR
PARTS

TEST AFTER REPAIRS	REDUCED PRESSURE ASSEMBLY	D.C.V.A.	P.V.B.A. / S.V.B.A.		AFTER REPAIRS DATE _____ PASSED <input type="checkbox"/>
	#1 CHECK PRESS DROP _____ (A) RELIEF VALVE OPENED _____ (B) MIN 2 PSID BUFFER A - B = _____ MIN 3 PSI	CHECK #1 TIGHT <input type="checkbox"/> PSID CHECK #2 TIGHT <input type="checkbox"/> PSID	OPENED AT PSDI DID NOT OPEN <input type="checkbox"/>	PRESS DROP PSDI FAILED <input type="checkbox"/>	

IN COMPLETING AND SUBMITTING THIS TEST REPORT, THE TESTER CERTIFIES THAT THE ASSEMBLY HAS BEEN TESTED AND MAINTAINED IN ACCORDANCE WITH ALL APPLICABLE RULES AND REGULATIONS OF THE WATER SYSTEM, AND STATE REGULATIONS

GAUGE CALIBRATION DATE **02-21-2022** DETECTOR METER READING _____

TESTER SIGNATURE

Gary Dohogne
B & A Plumbing

847-985-2444

619 Estes Ave Schaumburg, IL 60193

State Testers

Certification # **XC5931**

Gauge # **06153250**

REPORT RECEIVED BY: _____

- SERVICE RESTORED
- FOUND OFF, LEFT OFF

- New
- Existing
- Removed
- Replacement

BACKFLOW ASSEMBLY TEST REPORT

Property Owner **DOC-1710 N Randall Rd MOB, LLC**

Mailing Address **1710 N Randall Rd Elgin, IL 60123**

Phone: **866-322-4547**

Assembly Address **1710 N Randall Rd Elgin, IL 60123**

R.P.B.A. D.C.V.A. R.P.D.A. D.C.D.A. P.V.B.A. S.V.B.A. A.V.B. AIR GAP

SIZE: **4"** MAKE: **Wilkins** MODEL: **350 ADA**

Syncta ID **S897-777IJ** Serial # **V04815**

Assembly Location: **Sprinkler room on north side of building**

INITIAL TEST RESULTS	REDUCED PRESSURE ASSEMBLY	DOUBLE CHECK	P.V.B.A. / S.V.B.A.		INITIAL TEST PASSED <input checked="" type="checkbox"/> FAILED <input type="checkbox"/> DATE 01/25/23 SYSTEM PSI _____
	#1 CHECK PRESS DROP _____ (A) RELIEF VALVE OPENED AT _____ (B) MIN 2 PSID BUFFER A - B = _____ MIN 3 PSI	CHECK #1 TIGHT <input checked="" type="checkbox"/> 3.4 LEAKED <input type="checkbox"/> PSID CHECK #2 TIGHT <input checked="" type="checkbox"/> 3.0 LEAKED <input type="checkbox"/> PSID	AIR INLET OPENED AT PSDI DID NOT OPEN <input type="checkbox"/>	CHECK PRESS DROP PSDI FAILED <input type="checkbox"/>	
BYPASS CHECK	RELIEF VALVE PASS <input type="checkbox"/> FAIL <input type="checkbox"/>				

COMMENTS
REPAIRS
AND/OR
PARTS

TEST AFTER REPAIRS	REDUCED PRESSURE ASSEMBLY	D.C.V.A.	P.V.B.A. / S.V.B.A.		AFTER REPAIRS DATE _____ PASSED <input type="checkbox"/>
	#1 CHECK PRESS DROP _____ (A) RELIEF VALVE OPENED _____ (B) MIN 2 PSID BUFFER A - B = _____ MIN 3 PSI	CHECK #1 TIGHT <input type="checkbox"/> PSID CHECK #2 TIGHT <input type="checkbox"/> PSID	OPENED AT PSDI DID NOT OPEN <input type="checkbox"/>	PRESS DROP PSDI FAILED <input type="checkbox"/>	

IN COMPLETING AND SUBMITTING THIS TEST REPORT, THE TESTER CERTIFIES THAT THE ASSEMBLY HAS BEEN TESTED AND MAINTAINED IN ACCORDANCE WITH ALL APPLICABLE RULES AND REGULATIONS OF THE WATER SYSTEM, AND STATE REGULATIONS

GAUGE CALIBRATION DATE **02-21-2022** DETECTOR METER READING _____

TESTER SIGNATURE

Gary Dohogne 847-985-2444
B & A Plumbing
619 Estes Ave Schaumburg, IL 60193

State Testers
 Certification # **XC5931**
 Gauge # **06153250**

REPORT RECEIVED BY: _____

- SERVICE RESTORED
- FOUND OFF, LEFT OFF

- New
- Existing
- Removed
- Replacement

BACKFLOW ASSEMBLY TEST REPORT

Property Owner **DOC-1710 N Randall Rd MOB, LLC**

Mailing Address **1710 N Randall Rd Elgin, IL 60123**

Phone: **866-322-4547**

Assembly Address **1710 N Randall Rd Elgin, IL 60123**

R.P.B.A. D.C.V.A. R.P.D.A. D.C.D.A. P.V.B.A. S.V.B.A. A.V.B. AIR GAP

SIZE: **4"** MAKE: **Wilkins** MODEL: **475**

Syncta ID **S290-932ME** Serial # **Q02074**

Assembly Location: **Sprinkler room on north side of building**

INITIAL TEST RESULTS	REDUCED PRESSURE ASSEMBLY #1 CHECK PRESS DROP <u>7.8</u> (A) RELIEF VALVE OPENED AT <u>2.8</u> (B) MIN 2 PSID BUFFER A - B = <u>5.0</u> MIN 3 PSI	DOUBLE CHECK CHECK #1 TIGHT <input checked="" type="checkbox"/> LEAKED <input type="checkbox"/> PSID	P.V.B.A. / S.V.B.A. AIR INLET OPENED AT PSID	CHECK PRESS DROP PSID	INITIAL TEST PASSED <input checked="" type="checkbox"/> FAILED <input type="checkbox"/> DATE 01/25/23 SYSTEM PSI _____
	BYPASS CHECK	RELIEF VALVE PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>	CHECK #2 TIGHT <input checked="" type="checkbox"/> 7.2 LEAKED <input type="checkbox"/> PSID	DID NOT OPEN <input type="checkbox"/>	FAILED <input type="checkbox"/>
COMMENTS REPAIRS AND/OR PARTS					
TEST AFTER REPAIRS	REDUCED PRESSURE ASSEMBLY #1 CHECK PRESS DROP _____ (A) RELIEF OPENED _____ (B) MIN 2 PSID BUFFER A - B = _____ MIN 3 PSI	D.C.V.A. CHECK #1 TIGHT <input type="checkbox"/> PSID CHECK #2 TIGHT <input type="checkbox"/> PSID	P.V.B.A. / S.V.B.A. OPENED AT PSID	PRESS DROP PSID	AFTER REPAIRS DATE _____ PASSED <input type="checkbox"/>

IN COMPLETING AND SUBMITTING THIS TEST REPORT, THE TESTER CERTIFIES THAT THE ASSEMBLY HAS BEEN TESTED AND MAINTAINED IN ACCORDANCE WITH ALL APPLICABLE RULES AND REGULATIONS OF THE WATER SYSTEM, AND STATE REGULATIONS

GUAGE CALIBRATION DATE **02-21-2022** DETECTOR METER READING _____

TESTER SIGNATURE

Gary Dohogne
B & A Plumbing
619 Estes Ave Schaumburg, IL 60193

847-985-2444

State Testers
 Certification # **XC5931**
 Gauge # **06153250**

REPORT RECEIVED BY: _____

- SERVICE RESTORED
- FOUND OFF, LEFT OFF

BACKFLOW ASSEMBLY TEST REPORT

- New
- Existing
- Removed
- Replacement

Property Owner **DOC-1710 N Randall Rd MOB, LLC**

Mailing Address **1710 N Randall Rd Elgin, IL 60123**

Phone: **866-322-4547**

Assembly Address **1710 N Randall Rd Elgin, IL 60123**

R.P.B.A. D.C.V.A. R.P.D.A. D.C.D.A. P.V.B.A. S.V.B.A. A.V.B. AIR GAP

SIZE: **1-1/2"** MAKE: **Febco** MODEL: **860U**

Syncta ID **S195-096ND** Serial # **00347**

Assembly Location: **Sprinkler room on north side of building**

INITIAL TEST RESULTS	REDUCED PRESSURE ASSEMBLY #1 CHECK PRESS DROP <u>7.0</u> (A) RELIEF VALVE OPENED AT <u>3.2</u> (B) MIN 2 PSID BUFFER A - B = <u>3.8</u> MIN 3 PSI	DOUBLE CHECK CHECK #1 TIGHT <input checked="" type="checkbox"/> LEAKED <input type="checkbox"/> PSID CHECK #2 TIGHT <input checked="" type="checkbox"/> <u>6.2</u> LEAKED <input type="checkbox"/> PSID	P.V.B.A. / S.V.B.A. AIR INLET OPENED AT PSDI DID NOT OPEN <input type="checkbox"/>	CHECK PRESS DROP PSDI FAILED <input type="checkbox"/>	INITIAL TEST PASSED <input checked="" type="checkbox"/> FAILED <input type="checkbox"/> DATE <u>01/25/23</u> SYSTEM PSI _____
	BYPASS CHECK	RELIEF VALVE PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>			
COMMENTS REPAIRS AND/OR PARTS					
TEST AFTER REPAIRS	REDUCED PRESSURE ASSEMBLY #1 CHECK PRESS DROP _____ (A) RELIEF VALVE OPENED _____ (B) MIN 2 PSID BUFFER A - B = _____ MIN 3 PSI	D.C.V.A. CHECK #1 TIGHT <input type="checkbox"/> PSID CHECK #2 TIGHT <input type="checkbox"/> PSID	P.V.B.A. / S.V.B.A. OPENED AT PSDI PSDI		AFTER REPAIRS DATE _____ PASSED <input type="checkbox"/>

IN COMPLETING AND SUBMITTING THIS TEST REPORT, THE TESTER CERTIFIES THAT THE ASSEMBLY HAS BEEN TESTED AND MAINTAINED IN ACCORDANCE WITH ALL APPLICABLE RULES AND REGULATIONS OF THE WATER SYSTEM, AND STATE REGULATIONS

GAUGE CALIBRATION DATE 02-21-2022 DETECTOR METER READING _____

TESTER SIGNATURE

Gary Dohogne
B & A Plumbing
619 Estes Ave Schaumburg, IL 60193

847-985-2444

State Testers
 Certification # **XC5931**
 Gauge # **06153250**

REPORT RECEIVED BY: _____

- SERVICE RESTORED
- FOUND OFF, LEFT OFF

- New
- Existing
- Removed
- Replacement

BACKFLOW ASSEMBLY TEST REPORT

Property Owner DOC-1710 N Randall Rd MOB, LLC

Mailing Address 1710 N Randall Rd Elgin, IL 60123

Phone: 866-322-4547

Assembly Address 1710 N Randall Rd Elgin, IL 60123

R.P.B.A. D.C.V.A. R.P.D.A. D.C.D.A. P.V.B.A. S.V.B.A. A.V.B. AIR GAP

SIZE: 2"

MAKE: Wilkins

MODEL: 975 XL

Syncta ID S588-053SI

Serial # W9783

Assembly Location: Sprinkler room on north side of building

INITIAL TEST RESULTS	REDUCED PRESSURE ASSEMBLY	DOUBLE CHECK	P.V.B.A. / S.V.B.A.		INITIAL TEST
	#1 CHECK PRESS DROP 7.2 (A)	CHECK #1 TIGHT <input checked="" type="checkbox"/>	AIR INLET	CHECK	PASSED <input checked="" type="checkbox"/>
BYPASS CHECK	RELIEF VALVE OPENED AT 3.4 (B) MIN 2 PSID	LEAKED <input type="checkbox"/> PSID	OPENED AT	PRESS DROP	FAILED <input type="checkbox"/>
	BUFFER A - B = 3.8 MIN 3 PSI	CHECK #2 TIGHT <input checked="" type="checkbox"/> 6.8	PSDI	PSDI	DATE 01/30/23
	RELIEF VALVE PASS <input checked="" type="checkbox"/> FAIL <input type="checkbox"/>	LEAKED <input type="checkbox"/> PSID	DID NOT OPEN <input type="checkbox"/>	FAILED <input type="checkbox"/>	SYSTEM PSI _____
COMMENTS REPAIRS AND/OR PARTS					
TEST AFTER REPAIRS	REDUCED PRESSURE ASSEMBLY	D.C.V.A.	P.V.B.A. / S.V.B.A.		AFTER REPAIRS
	#1 CHECK PRESS DROP _____ (A)	CHECK #1 TIGHT <input type="checkbox"/> PSID	OPENED AT	PRESS DROP	DATE _____
	RELIEF OPENED _____ (B) MIN 2 PSID	CHECK #2 TIGHT <input type="checkbox"/> PSID	PSDI	PSDI	PASSED <input type="checkbox"/>
	BUFFER A - B = _____ MIN 3 PSI				

IN COMPLETING AND SUBMITTING THIS TEST REPORT, THE TESTER CERTIFIES THAT THE ASSEMBLY HAS BEEN TESTED AND MAINTAINED IN ACCORDANCE WITH ALL APPLICABLE RULES AND REGULATIONS OF THE WATER SYSTEM, AND STATE REGULATIONS

GAUGE CALIBRATION DATE 02-21-2022 DETECTOR METER READING _____

TESTER SIGNATURE

Gary Dohogne

847-985-2444

B & A Plumbing

619 Estes Ave Schaumburg, IL 60193

State Testers

Certification # XC5931

Gauge # 06153250

REPORT RECEIVED BY: _____

SERVICE RESTORED

FOUND OFF, LEFT OFF