

CUSTOMER NAME: Landmark Michigan BUILDING NAME: Rochester Hills Health and Wellness Building BUILDING ADDRESS: 1555 South Boulevard E, Rochester Hills, MI 48307 CONTACT NAME: Dan Przyski CONTACT F-MAIL: dprzyski@continuumservices.com CONTACT ROLE: Maintenance CONTACT PHONE: 1 248-996-2489 INSPECTION TYPE: Sprinkler FREQUENCY: Quarterly WORK ORDER: 54389444 INSPECTION START DATE: 06/05/2023 INSPECTION END DATE: 06/06/2023 INSPECTOR: Andrew Green INSPECTOR LICENSE: AS0147 ACCOUNT NAME: Johnson Controls North America OFFICE ADDRESS: 24755 Halsted Road Farmington Hills OFFICE PHONE: 248-427-5029 OFFICE LICENSE: L320376 TIMEZONE: EDT

SPRINKLER INSPECTION REPORT

1. Quarterly sprinkler inspection, June 2023.

General Inspection Notes

DEVICE DEFICIENCIES

No device deficiencies in this inspection.

RECOMMENDATIONS										
Priority	Created At	Created By	Updated At	Updated By						
MEDIUM	06/06/2023	Andrew Green	06/06/2023	Andrew Green						
	Description: Fires department of	onnection will be due for year hydrosta	tic testing in August, recommend testin	ıg.						
		<section-header></section-header>								





	General	
To be a	Answered with the Owner	
1.	Have there been any changes in the occupancy classification, machinery or operations since the last inspection?	Yes
2.	Have there been any changes or repairs to the fire protection systems since the last inspection?	No
3.	Have you had an internal pipe inspection performed in the last 5 years?	Yes
4.	Date the internal pipe inspection was performed?	01/12/2021
5.	Are Special Ladders or Lifts Required to perform the 5 Year Internal Pipe Inspection? If So, please list Size and Type. (12 Foot Stepladder, 20 Foot Scissor Lift Etc)	Yes
To be a	Answered by the Inspector	
1.	Have the sprinkler systems been extended to all areas of the building?	Yes
2.	Are all exterior openings protected against the entrance of cold air?	Yes
3.	Are the building areas protected by a wet system heated, including its blind attics and perimeter areas?	Yes
4.	Date Backflow Devices Were Tested	03/04/2022
5.	Number Of Water Gauges	4
6.	Are all Tanks, Fire Pumps, and Fire Department Connections Inspected and Tested Per NFPA 25?	Yes
7.	All Systems Restored To Normal	Yes
Water	Supplies	
1.	Туре	City
Contro	ol Valve Questions	
1.	Are all sprinkler system main control valves and all other valves in the appropriate open or closed position?	Yes
2.	Are all control valves sealed, locked, or supervised, in the appropriate open or closed position?	Yes
Alarm	s	
1.	Did the electric alarms operate during testing?	Yes
2.	Did the supervisory alarms operate during testing?	Yes
Sprink	clers - Piping	- -
1.	Were All Sprinklers Made After 1920	Yes
2.	Standard Response Sprinklers 50 Years Or Older	No
3.	Quick Response Sprinklers 20 years or older?	No
4.	Do sprinklers generally appear to be free of corrosion, paint, or loading and visible obstructions?	Yes
5.	Is the buildings sprinklers inventory list located within the sprinkler spare head cabinet?	Yes
6.	Are appropriate number of extra sprinklers and sprinkler wrenches available on the premises?	Yes
7.	Type of sprinkler heads	Viking VK634 & VK462 Pendent, VK532 Upright 155°, VK302 LPC QR 155°
8.	Does there appear to be proper clearance between the top of all storage and the sprinkler deflector?	Yes
9.	Does the exposed exterior condition of piping, drain valves, check valves, hangers, pressure gauges, open sprinklers and strainers appear to be satisfactory?	Yes



INSPECTION RESULTS SUMMARY										
DEVICE TYPE	INVENTORY COUNT	PASSED	FAILED	CANNOT INSPECT						
City Connection Control Valve	2	2	0	0						
Control Valve	5	5	0	0						
Fire Dept. Connection	1	1	0	0						
Inspectors Test Valve	3	3	0	0						
Sprinkler Box	1	1	0	0						
Sprinkler Head	1	1	0	0						
Sprinkler Horn Strobe	1	1	0	0						
Tamper Switch	7	7	0	0						
Water Flow Switch	4	4	0	0						
Main Drain Test	1	1	0	0						
Wet System	4	4	0	0						

WET SYSTEMS										
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT			
1	1st Floor	In Riser Room	Wet System	_	Andrew Green	06/06/2023	Passed			
Make 8	& Model				_	L	4" Victualic			
What S	ize is This Wet Pipe valve?)					2"			
Hydrau	ılic Name Plate Present						Yes			
Record	The Coverage Area Defin	ed On The Hydraulic Plate					900 Sq Ft			
Record		417.298 GPM								
Record		30.226								
Inspec	t Alarm Valve For Exterior	Damage					Yes			
Drains	Leak Tight						Yes			
Gauge	s Reading Normal PSI						Yes			
Record	The Pressure (PSI) Showr	n On The System Side Pres	sure Gauge.				88			
Date o	f Internal Inspection of St	rainers, Filters, Restriction	Orifices				01/12/2021			
Date o	f Check Valves Internal Ins	spection					01/12/2021			
Date th	ne internal pipe inspectior	n was performed?					01/12/2021			
Date o	f Gauges Replacement						01/12/2021			
2	1st Floor	In Stair A	Wet System	-	Andrew Green	06/06/2023	Passed			
Make 8	& Model						2"			
What S	ize is This Wet Pipe valve?	,					2" Victualic			
Hydrau	ılic Name Plate Present						No			
Drains	Leak Tight						Yes			
Gauge	s Reading Normal PSI						Yes			
Record	The Pressure (PSI) Showr	n On The System Side Pres	sure Gauge.				83			
Date o	f Internal Inspection of St	rainers, Filters, Restriction	Orifices				01/12/2021			
Date o	f Check Valves Internal Ins	spection					01/12/2021			
Date th	ne internal pipe inspectior	was performed?					01/12/2021			
Date o	f Gauges Replacement						01/12/2021			



			١	NET SYSTEMS					
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT		
3	3rd Floor	In Stair A	Wet System	_	Andrew Green	06/06/2023	Passed		
Make 8	& Model			1			2" Victualic		
What S	Size is This Wet Pipe valve?)					2″		
Hydrau	ulic Name Plate Present						Yes		
Record	ecord The Coverage Area Defined On The Hydraulic Plate								
Record	l The GPM On The Hydrau	lic Plate					105.8 GPM		
Drains	Leak Tight						Yes		
Gauge	s Reading Normal PSI						Yes		
Record	l The Pressure (PSI) Showr	n On The System Side Pres	sure Gauge.				70		
Date o	f Internal Inspection of Sti	rainers, Filters, Restriction	Orifices				01/12/2021		
Date o	f Check Valves Internal Ins	spection					01/12/2021		
Date th	ne internal pipe inspection	n was performed?					01/12/2021		
Date o	f Gauges Replacement						01/12/2021		
4	2nd Floor	In Stairwell A	Wet System	-	Andrew Green	06/06/2023	Passed		
Make 8	& Model						2" Victualic		
What S	Size is This Wet Pipe valve?	,					2"		
Hydrau	ulic Name Plate Present						No		
Drains	Leak Tight						Yes		
Gauge	s Reading Normal PSI						Yes		
Record	The Pressure (PSI) Showr	n On The System Side Pres	sure Gauge.				76		
Date of Internal Inspection of Strainers, Filters, Restriction Orifices									
Date o	Date of Check Valves Internal Inspection								
Date th	ne internal pipe inspection	was performed?					01/12/2021		
Date o	f Gauges Replacement						01/12/2021		

MAIN DRAIN TESTS											
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT				
1	1st Floor	In Riser Room	Main Drain Test	_	Andrew Green	06/06/2023	Passed				
Test pi	Test pipe located										
Size of	Size of test pipe										
Previous Main Drain Test Date											
Previous Main Drain Static Pressure											
Previou	us Main Drain Residual Pre	essure					74				
Static s	upply pressure						88				
Residu	al Pressure						78				
Time to	o return to normal system	pressure					10 Seconds				
Static supply pressure after completion of test											
Main Drain PSI Comparable to previous?											
Main d	rain opened & free of obs	truction discoloration?					Yes				



Г

Customer: Landmark Michigan Building: Rochester Hills Health and Wellness Building Address: 1555 South Boulevard E, Rochester Hills, MI 48307

	FIRE DEPARTMENT CONNECTIONS										
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT				
1	1 1st Floor NE Corner of Building Fire Dept. Connection — Andrew Green 06/06/2023										
Is FDC Visible / Accessible?											
Are Co	uplings / Swivels / Plugs /	Caps in place?					Yes				
Identifi	ication Signs In Place						Yes				
Check	Valve Not Leaking / Gaske	ets In Good Condition / Bal	l Drip and Clapper in Place	e and Operating Properly	,		Yes				
FDC Hydrostatic Test Date											
FDC Ch	eck Valves Internal Inspe	ction Date					08/27/2018				

CONTROL VALVES AGG											
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT			
1	1st Floor	By Elevator	M1-15	Control Valve	_	Andrew Green	06/06/2023	Passed			
Туре а	and Size							1" Victualic Butterfly			
Easily	Accessible?							Yes			
Signs	?							Yes			
Valve	in the Appropriate Op	en or Closed Position?						Yes			
Sealed	Sealed, Locked, and/or Supervised										
Free f	rom External Leaks?							Yes			
2	1st Floor	By Elevator (Sitting Area)	M1-15	Control Valve	—	Andrew Green	06/06/2023	Passed			
Туре а	and Size							1" Victualic Butterfly			
Easily	Accessible?							Yes			
Signs	?							Yes			
Valve	in the Appropriate Op	en or Closed Position?						Yes			
Sealed	d, Locked, and/or Supe	ervised						Supervised			
Free f	rom External Leaks?							Yes			
3	1st Floor	In Riser Room (City 1)	M1-04	City Connection Control Valve	_	Andrew Green	06/06/2023	Passed			
Type a	and Size							4" Wilkins OS&Y			
Easily	Accessible?							Yes			
Signs	2							Yes			
Valve	in the Appropriate Op	en or Closed Position?						Yes			
Sealed	d, Locked, and/or Supe	ervised						Supervised			
Free f	rom External Leaks?							Yes			
4	1st Floor	In Riser Room (City 2)	M1-04	City Connection Control Valve	-	Andrew Green	06/06/2023	Passed			
Туре а	and Size							4" Wilkins OS&Y			
Easily	Accessible?							Yes			
Signs	?							Yes			
Valve	Valve in the Appropriate Open or Closed Position?										
Sealed	d, Locked, and/or Supe	ervised						Supervised			
Free f	rom External Leaks?							Yes			



				CONTROL VA	LVES AGG				
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT	
5	1st Floor	In Stair A	M1-22	Control Valve	_	Andrew Green	06/06/2023	Passed	
Type a	and Size	1		1				2" Victualic Butterfly	
Easily	Accessible?							Yes	
Signs?	Signs?								
Valve	in the Appropriate Ope	en or Closed Position?						Yes	
Sealed	d, Locked, and/or Supe	rvised						Supervised	
Free fi	rom External Leaks?							Yes	
6	2nd Floor	In Stair A	M1-112	Control Valve	—	Andrew Green	06/06/2023	Passed	
Type a	and Size							2" Victualic Butterfly	
Easily	Accessible?							Yes	
Signs?	?							Yes	
Valve	in the Appropriate Ope	en or Closed Position?						Yes	
Sealed	d, Locked, and/or Supe	rvised						Supervised	
Free fi	rom External Leaks?							Yes	
7	3rd Floor	In Stair A	M1-218	Control Valve	—	Andrew Green	06/06/2023	Passed	
Type a	and Size						·	2" Victualic Butterfly	
Easily	Accessible?							Yes	
Signs?	Signs?								
Valve	Valve in the Appropriate Open or Closed Position?								
Sealed	d, Locked, and/or Supe	rvised						Supervised	
Free fr	rom External Leaks?							Yes	

	INSPECTOR'S TEST VALVE										
#	LOCATION	DESCRIPTION	ADDRESS	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT			
1	3rd Floor	In Stair A	M1-218	Inspectors Test Valve	_	Andrew Green	06/06/2023	Passed			
2	2nd Floor	In Stair A	M1-112	Inspectors Test Valve	-	Andrew Green	06/06/2023	Passed			
3	1st Floor	In Stair A	M1-22	Inspectors Test Valve	—	Andrew Green	06/06/2023	Passed			

	HORN STROBES									
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT			
1	_	Outside FDC NE corner of the building	Sprinkler Horn Strobe	_	Andrew Green	06/06/2023	Passed			

WATER FLOW SWITCHES										
#	# LOCATION DESCRIPTION ADDRESS DEVICE TYPE BARCODE INSPECTOR DATE OF TEST							RESULT		
1	1st Floor	In Riser Room	M1-04	Water Flow Switch	-	Andrew Green	06/06/2023	Passed		
Quart	erly Visual Inspection -	Is flow switch free of da	mage with its electrica	al connections secure?				Yes		
2	1st Floor	In Stair A	M1-22	Water Flow Switch	-	Andrew Green	06/06/2023	Passed		
Quart	Quarterly Visual Inspection - Is flow switch free of damage with its electrical connections secure?									



	WATER FLOW SWITCHES									
#	# LOCATION DESCRIPTION ADDRESS DEVICE TYPE BARCODE INSPECTOR DATE OF TEST									
3	2nd Floor	In Stair A	M1-112	Water Flow Switch	_	Andrew Green	06/06/2023	Passed		
Quarterly Visual Inspection - Is flow switch free of damage with its electrical connections secure?								Yes		
4	3rd Floor	In Stair A	M1-218	Water Flow Switch	_	Andrew Green	06/06/2023	Passed		
Quarterly Visual Inspection - Is flow switch free of damage with its electrical connections secure?								Yes		

TAMPER SWITCHES								
#	LOCATION	OCATION DESCRIPTION ADDRESS DEVICE TYPE BARCODE INSPECTOR DATE OF TEST					RESULT	
1	1st Floor	By Elevator	M1-15	Tamper Switch	_	Andrew Green	06/06/2023	Passed
Quart	erly Visual Inspection -	Is tamper switch free of	damage with its elect	rical connections secur	e?			Yes
2	1st Floor	By Elevator (Sitting Area)	M1-15	Tamper Switch	_	Andrew Green	06/06/2023	Passed
Quart	erly Visual Inspection -	Is tamper switch free of	damage with its elect	rical connections secur	e?			Yes
3	1st Floor	In Riser Room After Back Flow	M1-04	Tamper Switch	-	Andrew Green	06/06/2023	Passed
Quarterly Visual Inspection - Is tamper switch free of damage with its electrical connections secure?								
4	1st Floor	In Riser Room Before Back Flow	M1-04	Tamper Switch	-	Andrew Green	06/06/2023	Passed
Quarterly Visual Inspection - Is tamper switch free of damage with its electrical connections secure?								Yes
5	1st Floor	In Stair A	M1-22	Tamper Switch	_	Andrew Green	06/06/2023	Passed
Quarterly Visual Inspection - Is tamper switch free of damage with its electrical connections secure?								Yes
6	2nd Floor	In Stair A	M1-112	Tamper Switch	_	Andrew Green	06/06/2023	Passed
Quarterly Visual Inspection - Is tamper switch free of damage with its electrical connections secure?								Yes
7	3rd Floor	In Stair A	M1-218	Tamper Switch	_	Andrew Green	06/06/2023	Passed
Quarterly Visual Inspection - Is tamper switch free of damage with its electrical connections secure?								Yes

SPRINKLER BOXES								
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT	
1	1st Floor	Located in Fire Rise Room Viking VK634 & VK462 Pendent, VK532 Upright 155°, VK302 LPC QR 155°	Sprinkler Box	_	Andrew Green	06/06/2023	Passed	

	SPRINKLER HEADS									
#	LOCATION	DESCRIPTION	DEVICE TYPE	BARCODE	INSPECTOR	DATE OF TEST	RESULT			
1	_	Various upright, pendant, and recessed sprinkler head throughout facility	Sprinkler Head	_	Andrew Green	06/06/2023	Passed			



Inspector Signature	And Dr	Inspector Name	Andrew Green	Date	06/06/2023
Signature of the Maintinence		Printed name of the Maintinence	Dan Przyski	Date	06/06/2023



Terms And Conditions

- 1. Limitation of Liability; Limitations Of Remedy. It is understood and agreed by the Customer that Company is not an insurer and that insurance coverage, if any, shall be obtained by the Customer and that amounts payable to Company hereunder are based upon the value of the services and the scope of liability set forth in this agreement and are unrelated to the value of the Customer's property and the property of others located on the premises. Customer agrees to look exclusively to the Customer's insurer to recover for injuries or damage in the event of any loss or injury and that Customer releases and waives all right of recovery against Company arising by way of subrogation. Company makes no guaranty or Warranty, including any implied warranty of merchantability or fitness for a particular purpose that equipment or services supplied by Company will detect or avert occurrences or the consequences there from that the equipment or service was designed to detect or avert.
br />It is impractical and extremely difficult to fix the actual damages, if any, which may proximately result from failure on the part of Company to perform any of its obligations under this agreement. Accordingly, Customer agrees that, Company shall be exempt from liability for any loss, damage or injury arising directly or indirectly from occurrences, or the consequences therefrom, which the equipment or service was designed to detect or avert. Should Company be found liable for any loss, damage or injury arising from a failure of the equipment or service in any respect, Company's liability shall be limited to an amount equal to the agreement price (as increased by the price for any additional work) or where the time and material payment term is selected, Customer's time and material payments to Company. Where this agreement covers multiple sites, liability shall be limited to the amount of the payments allocable to the site where the incident occurred. Such sum shall be complete and exclusive. If Customer desires Company to assume greater liability, the parties shall amend this agreement by attaching a rider setting forth the amount of additional liability and the additional amount payable by the Customer for the assumption by Company of such greater liability, provided however that such rider shall in no way be interpreted to hold Company as an insurer. IN NO EVENT SHALL COMPANY BE LIABLE FOR ANY DAMAGE, LOSS, INJURY, OR ANY OTHER CLAIM ARISING FROM ANY SERVICING, ALTERATIONS, MODIFICATIONS, CHANGES, OR MOVEMENTS OF THE COVERED SYSTEM(S) OR ANY OF ITS COMPONENT PARTS BY THE CUSTOMER OR ANY THIRD PARTY. COMPANY SHALL NOT BE LIABLE FOR INDIRECT, INCIDENTAL OR CONSEQUENTIAL DAMAGES OF ANY KIND, INCLUDING BUT NOT LIMITED TO DAMAGES ARISING FROM THE USE, LOSS OF THE USE, PERFORMANCE, OR FAILURE OF THE COVERED SYSTEM(S) TO PERFORM. The limitations of liability set forth in this agreement shall inure to the benefit of all parents, subsidiaries and affiliates of Company, whether direct or indirect, Company's employees, agents, officers and directors.
- 2. Limited Warranty. COMPANY WARRANTS THAT ITS WORKMANSHIP AND MATERIAL FURNISHED UNDER THIS AGREEMENT WILL BE FREE FROM DEFECTS FOR A PERIOD OF NINETY (90) DAYS FROM THE DATE OF FURNISHING. Where Company provides product or equipment of others, Company will warrant the product or equipment only to the extent warranted by such third party. EXCEPT AS EXPRESSLY SET FORTH HEREIN, COMPANY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO THE SERVICES PERFORMED OR THE PRODUCTS, SYSTEMS OR EQUIPMENT, IF ANY, SUPPORTED HEREUNDER. COMPANY MAKES NO WARRANTY OR REPRESENTATION, AND UNDERTAKES NO OBLIGATION TO ENSURE BY THE SERVICES PERFORMED UNDER THIS AGREEMENT, THAT COMPANY'S PRODUCTS OR THE SYSTEMS OR EQUIPMENT OF THE CUSTOMER WILL CORRECTLY HANDLE THE PROCESSING OF CALENDAR DATES BEFORE OR AFTER DECEMBER 31, 1999.
- 3. Indemnity. Customer agrees to indemnify, hold harmless and defend Company against any and all losses, damages, costs, including expert fees and costs, and expenses including reasonable defense costs, arising from any and all third party claims for personal injury, death, property damage or economic loss, including specifically any damages resulting from the exposure of workers to Hazardous Conditions whether or not Customer pre-notifies Company of the existence of said hazardous conditions, arising in any way from any act or omission of Customer or Company relating in any way to this agreement, including but not limited to the Services under this agreement, whether such claims are based upon contract, warranty, tort (including but not limited to active or passive negligence), strict liability or otherwise. Company reserves the right to select counsel to represent it in any such action.
- 4. Hazardous Materials. Customer represents that, except to the extent that Company has been given written notice of the following hazards prior to the execution of this agreement, to the best of Customer's knowledge there is no:
 - a. "permit confined space," as defined by OSHA, or space in which work must be performed that, because of its construction, location, contents or work activity therein, accumulation of a hazardous gas, vapour, dust or fume or the creation of a risk of infectious disease
 - b. need for air monitoring, respiratory protection, or other medical risk
 - c. asbestos, asbestos-containing material, formaldehyde or other potentially toxic or otherwise hazardous material contained in or on the surface of the floors, walls, ceilings, insulation or other structural components of the area of any building
 - d. All of the above are hereinafter referred to as "Hazardous Conditions". Company shall have the right to rely on the representations listed above. If hazardous conditions are encountered by Company during the course of Company's work, the discovery of such conditions shall constitute an event beyond Company's control and Company shall have no obligation to further perform in the area where the hazardous conditions exist until the area has been made safe by Customer as certified in writing by an independent testing agency, and Customer shall pay disruption expenses and re-mobilization expenses as determined by Company. This agreement does not provide for the cost of capture, containment or disposal of any hazardous waste materials, or hazardous materials, encountered in any of the Covered System(s) and/or during performance of the Services. Said materials shall at all times remain the responsibility and property of Customer. Company shall not be responsible for the testing, removal or disposal of such hazardous materials.
- 5. Equipment Disconnections. This represents Company's notice to you that the system(s)/device(s) listed on the face of this agreement as temporarily or permanently disconnected are no longer in service and, thus, cannot detect, perform and/or report
- 6. General. Unless otherwise specified, work shall be performed during company's regular business hours,, exclusive of Saturdays, Sundays and Company holidays. All work is subject to review and rebilling in accordance with the terms and conditions of Customer's agreement/contract with Company, if one is in effect. Company shall not be responsible for failure to render services due to causes beyond its control, including but not limited to material shortages, work stoppages, fires, civil disobedience or unrest, severe weather, fire or any other cause beyond the control of Company. Customer is aware that the Limitation of Liability and other provisions set forth in any existing agreement/contract, if one is in effect, or set forth above, apply to services performed and materials supplied. The terms of this agreement shall govern notwithstanding any inconsistent or additional terms and conditions in any purchase order or other document submitted by Customer.



Sprinkler-Quarterly

Customer: Landmark Michigan Building: Rochester Hills Health and Wellness Building Address: 1555 South Boulevard E, Rochester Hills, MI 48307

DEVICE NOTE IMAGE APPENDICES



BUILDING NOTES IMAGES APPENDIX

Notes: