

Johnson Control Fire Protection LP

Task # 90921733

5 Year

SR# 54960642

REPORT OF INTERNAL OBSTRUCTION INSPECTION

Date July 6, 2023

CUSTOMER BUILDING / LOCATION STREET CITY / ST / ZIP ATTN: PHONE #	INSPECTOR PHONE # LICENSE #
<u>Eden Hill Medical Center</u> <u>DOC</u> <u>200 Banning Street</u> <u>Dover, DE 19904</u> 	<u>Tad Lehman</u> <u>18 Boulden Circle Suite 24</u> <u>NewCastle, DE</u> <u>302 324 4470</u> <u>0104</u>

System Location:

1. SYSTEM INFORMATION

Type of System: WET DRY PREACTION ANTIFREEZE OTHER

Number of Risers: 1 Sizes: 6 INCH

Number of Floors: 3

2. CONDITION OF PIPE INVESTIGATED:

CROSSMAIN:

Condition: CLEAR SIZE: 2 1/2 INCH
 Picture Range: N/A

BRANCH LINE:

Condition: CLEAR SIZE: 1 INCH
 Picture Range: N/A

ALARM VALVE:

Condition: CLEAR SIZE: 6 INCH
 Picture Range: N/A

ASSOCIATED TRIM, FILTERS, STRAINERS, ETC:

Condition: CLEAR QTY: 1/4 INCH
 Picture Range: N/A

3. COMMENTS & DEFICIENCIES FOUND:

- Completed Internal Inspection (PASSED)
- Replaced Gauges

Customer: _____
 Print Name: _____

Date: 7-6-23
 Inspector Name: _____

