

Village of Oak Brook

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer / Property Name: **One Parkview Plaza**
Contact Name:
Property Address: **17W110 22nd St**
Oakbrook Terrace, IL 60181

Assembly Information

Type: **RPDA** Model #: **909DA**
Size: **4"** Serial#: **216392**
Manufacturer: **Watts** Hazard: **Domestic**
Location:
Reason for test: ☐ new ☒ existing ☐ replaced.

PASS

Assembly Test Information

Test Date: 2022-05-26

Initial Test		
Check Valve #1 8.0 (X) Closed Tight/Held () Leaked	Check Valve #2 7.4 (X) Closed Tight/Held () Leaked	Relief Valve 2.6 (X) Opened () Did Not Open
Final Test		
Check Valve #1 8.0 (X) Closed Tight/Held () Leaked	Check Valve #2 7.4 (X) Closed Tight/Held () Leaked	Relief Valve 2.6 (X) Opened () Did Not Open

As the tester of record, I affirm this test as: Passed ☒ Failed ☐ Repairs Made: No

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Vanassche, Robert**
Tester License Expiration: **05-31-2022**
Certification#: **xc5626**
Test Kit Serial #: **02192045**
Test Kit Date Tested for Accuracy: **01-04-2022**
Test Kit Mfr. & Mod. #: **Mid-West 845-5**
Testing Co Name: **A-Plus Plumbing, Inc.**
Phone: **(847) 891-7103**
Address: **733 West Estes Avenue**
Schaumburg, IL 60193

The above tester certifies that all information submitted for this report is true and accurate

The backflow prevention assembly detailed above has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters

Village of Oak Brook

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer / Property Name: **One Parkview Plaza**
Contact Name:
Property Address: **17W110 22nd St**
Oakbrook Terrace, IL 60181

Assembly Information

Type: **RP** Model #: **909**
Size: **4"** Serial#: **224324**
Manufacturer: **Watts** Hazard: **Domestic**
Location: **PARKING GARAGE**
Reason for test: ☐ new ☒ existing ☐ replaced.

PASS

Assembly Test Information

Test Date: 2022-05-26

Initial Test		
Check Valve #1 8.6 (X) Closed Tight/Held () Leaked	Check Valve #2 8.0 (X) Closed Tight/Held () Leaked	Relief Valve 2.4 (X) Opened () Did Not Open
Final Test		
Check Valve #1 8.6 (X) Closed Tight/Held () Leaked	Check Valve #2 8.0 (X) Closed Tight/Held () Leaked	Relief Valve 2.4 (X) Opened () Did Not Open

As the tester of record, I affirm this test as: Passed ☒ Failed ☐ Repairs Made: No

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Vanassche, Robert**
Tester License Expiration: **05-31-2022**
Certification#: **xc5626**
Test Kit Serial #: **02192045**
Test Kit Date Tested for Accuracy: **01-04-2022**
Test Kit Mfr. & Mod. #: **Mid-West 845-5**
Testing Co Name: **A-Plus Plumbing, Inc.**
Phone: **(847) 891-7103**
Address: **733 West Estes Avenue**
Schaumburg, IL 60193

The above tester certifies that all information submitted for this report is true and accurate

The backflow prevention assembly detailed above has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters

Village of Oak Brook

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer / Property Name: **One Parkview Plaza**
Contact Name:
Property Address: **17W110 22nd St**
Oakbrook Terrace, IL 60181

Assembly Information

Type: **RP** Model #: **825**
Size: **8"** Serial#: **N0803120609**
Manufacturer: **Febco** Hazard: **Fire Protection**
Location: **P-2 Meter Room**
Reason for test: ☐ new ☒ existing ☐ replaced.

PASS

Assembly Test Information

Test Date: 2022-05-26

Initial Test		
Check Valve #1 6.4 (X) Closed Tight/Held () Leaked	Check Valve #2 5.8 (X) Closed Tight/Held () Leaked	Relief Valve 2.8 (X) Opened () Did Not Open
Final Test		
Check Valve #1 6.4 (X) Closed Tight/Held () Leaked	Check Valve #2 5.8 (X) Closed Tight/Held () Leaked	Relief Valve 2.8 (X) Opened () Did Not Open

As the tester of record, I affirm this test as: Passed ☒ Failed ☐ Repairs Made: No

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Vanassche, Robert**
Tester License Expiration: **05-31-2022**
Certification#: **xc5626**
Test Kit Serial #: **02192045**
Test Kit Date Tested for Accuracy: **01-04-2022**
Test Kit Mfr. & Mod. #: **Mid-West 845-5**
Testing Co Name: **A-Plus Plumbing, Inc.**
Phone: **(847) 891-7103**
Address: **733 West Estes Avenue**
Schaumburg, IL 60193

The above tester certifies that all information submitted for this report is true and accurate

The backflow prevention assembly detailed above has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters

Village of Oak Brook

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer / Property Name: **One Parkview Plaza**
Contact Name:
Property Address: **17W110 22nd St**
Oakbrook Terrace, IL 60181

Assembly Information

Type: **RP** Model #: **009**
Size: **1 1/2"** Serial#: **079104**
Manufacturer: **Watts** Hazard: **Domestic**
Location: **Deli Back Room**
Reason for test: ☐ new ☒ existing ☐ replaced.

PASS

Assembly Test Information

Test Date: 2022-05-26

Initial Test		
Check Valve #1 8.0 (X) Closed Tight/Held () Leaked	Check Valve #2 7.6 (X) Closed Tight/Held () Leaked	Relief Valve 2.8 (X) Opened () Did Not Open
Final Test		
Check Valve #1 8.0 (X) Closed Tight/Held () Leaked	Check Valve #2 7.6 (X) Closed Tight/Held () Leaked	Relief Valve 2.8 (X) Opened () Did Not Open

As the tester of record, I affirm this test as: Passed ☒ Failed ☐ Repairs Made: No

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Vanassche, Robert**
Tester License Expiration: **05-31-2022**
Certification#: **xc5626**
Test Kit Serial #: **02192045**
Test Kit Date Tested for Accuracy: **01-04-2022**
Test Kit Mfr. & Mod. #: **Mid-West 845-5**
Testing Co Name: **A-Plus Plumbing, Inc.**
Phone: **(847) 891-7103**
Address: **733 West Estes Avenue**
Schaumburg, IL 60193

The above tester certifies that all information submitted for this report is true and accurate

The backflow prevention assembly detailed above has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters

Village of Oak Brook

Backflow Prevention Assembly Test and Maintenance Report



Customer Information

Customer / Property Name: **One Parkview Plaza**
Contact Name:
Property Address: **17W110 22nd St**
Oakbrook Terrace, IL 60181

Assembly Information

Type: **RP** Model #: **909**
Size: **2"** Serial#: **368040**
Manufacturer: **Watts** Hazard: **Chill Water**
Location:
Reason for test: ☐ new ☒ existing ☐ replaced.

PASS

Assembly Test Information

Test Date: 2022-05-26

Initial Test		
Check Valve #1	Check Valve #2	Relief Valve
8.2	7.8	2.0
(X) Closed Tight/Held	(X) Closed Tight/Held	(X) Opened
() Leaked	() Leaked	() Did Not Open
Final Test		
Check Valve #1	Check Valve #2	Relief Valve
8.2	7.8	2.0
(X) Closed Tight/Held	(X) Closed Tight/Held	(X) Opened
() Leaked	() Leaked	() Did Not Open

As the tester of record, I affirm this test as: Passed ☒ Failed ☐ Repairs Made: No

Additional comments or repairs made / materials (parts) used:

(no comments)

Tester Information

Tester Name: **Vanassche, Robert**
Tester License Expiration: **05-31-2022**
Certification#: **xc5626**
Test Kit Serial #: **02192045**
Test Kit Date Tested for Accuracy: **01-04-2022**
Test Kit Mfr. & Mod. #: **Mid-West 845-5**
Testing Co Name: **A-Plus Plumbing, Inc.**
Phone: **(847) 891-7103**
Address: **733 West Estes Avenue**
Schaumburg, IL 60193

The above tester certifies that all information submitted for this report is true and accurate

The backflow prevention assembly detailed above has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters