

Property at F45 Training Glen Ellyn

Backflow Prevention Assembly Test and Maintenance Report

Property Address: 369-373 Roosevelt Road, Glen Ellyn, IL 60137

Date: 02/22/2024

Assembly Information:

Type: RPZ Location: Sprinkler Rm E side top

Size: 1" Hazard: Domestic

Make: Watts Installation: Horizontal

Model: **LF009M2QT** Serial #: **100618**



Assembly Test Information:

PSID Test Result

Check Valve #1 9.4 Closed Tight/Held

Check Valve #2 2.4 Closed Tight/Held

Relief Valve 3.6 Open

Test Comments:

Left as Found ON.

Tester Information:

Device Supply Pressure: N/A

Tester Name: James Hermann
Tester License Expiration: 04/30/2024
Certification #: XC4255

As the tester of record, I affirm this test as PASS.

Test Kit Information:

Test Kit Serial #: 0042614

Test Kit Tested for Accuracy: 03/17/2023

Test Kit Mfr. & Mod. #: Watts, TK-99E

Test Company Information:

Testing Company Name: American Backflow & Fire Prevention
Address: 111 Kerry Lane, Wauconda, IL 60084

Phone: (847) 540-9910

Please call for details.













Test Comments:

Left as Found ON.

Property at F45 Training Glen Ellyn

Backflow Prevention Assembly Test and Maintenance Report

Property Address: 369-373 Roosevelt Road, Glen Ellyn, IL 60137

Date: 02/22/2024

Assembly Information:

Sprinkler Room E side **RPZ** Type: Location:

1" Size: center Irrigation Make: Watts Hazard: LF009M2QT Model: Installation: Horizontal

078686 Serial #:



Assembly Test Information:

PSID Test Result Closed Tight/Held Check Valve #1 9.4 Check Valve #2 1.4 Closed Tight/Held Relief Valve 4.2 Open

Device Supply Pressure: N/A

As the tester of record, I affirm this test as PASS.

Tester Information:

Tester Name: James Hermann Tester License Expiration: 04/30/2024 Certification #: XC4255

Test Kit Information:

Test Kit Serial #: 0042614 Test Kit Tested for Accuracy: 03/17/2023 Watts, TK-99E Test Kit Mfr. & Mod. #:

Test Company Information:

Testing Company Name: American Backflow & Fire Prevention 111 Kerry Lane, Wauconda, IL 60084 Address:

(847) 540-9910 Phone:













Property at F45 Training Glen Ellyn

Backflow Prevention Assembly Test and Maintenance Report

Property Address: 369-373 Roosevelt Road, Glen Ellyn, IL 60137

Date: 02/22/2024

Assembly Information:

RPZ Sprinkler Rm E side Type: Location:

1" Size: bottom **Domestic** Make: Watts Hazard: LF009M2QT Installation: Horizontal Model:

Serial #: 080095



Assembly Test Information:

PSID Test Result Closed Tight/Held Check Valve #1 10.2 Check Valve #2 2.8 Closed Tight/Held Relief Valve 3.0 Open

Device Supply Pressure: N/A

Test Comments:

Left as Found ON.

Tester Information:

Tester Name: James Hermann Tester License Expiration: 04/30/2024 XC4255 Certification #:

Test Kit Information:

Test Kit Serial #: 0042614 Test Kit Tested for Accuracy: 03/17/2023 Watts, TK-99E Test Kit Mfr. & Mod. #:

As the tester of record, I affirm this test as PASS.



Test Company Information:

Testing Company Name: American Backflow & Fire Prevention 111 Kerry Lane, Wauconda, IL 60084 Address:

(847) 540-9910 Phone:













Property at F45 Training Glen Ellyn

Backflow Prevention Assembly Test and Maintenance Report

Property Address: 369-373 Roosevelt Road, Glen Ellyn, IL 60137

Date: 02/22/2024

Assembly Information:

Type: **RPZ** Location: Sprinkler Room East Side

3/4" Size: Hazard: Fire By-Pass Make: Wilkins Installation: Horizontal

975XL2 Model: 4250131 Serial #:



Assembly Test Information:

PSID Test Result Closed Tight/Held Check Valve #1 11.0 Check Valve #2 2.6 Closed Tight/Held Relief Valve 3.0 Open

Device Supply Pressure: N/A

Test Comments:

Left as Found ON.

Tester Information:

Tester Name: James Hermann Tester License Expiration: 04/30/2024 Certification #: XC4255

Test Kit Information:

Test Kit Serial #: 0042614 Test Kit Tested for Accuracy: 03/17/2023 Watts, TK-99E Test Kit Mfr. & Mod. #:

As the tester of record, I affirm this test as PASS.



Test Company Information:

Testing Company Name: American Backflow & Fire Prevention 111 Kerry Lane, Wauconda, IL 60084 Address:

(847) 540-9910 Phone:













Property at F45 Training Glen Ellyn

Backflow Prevention Assembly Test and Maintenance Report

Property Address: 369-373 Roosevelt Road, Glen Ellyn, IL 60137

Date: 02/22/2024

Assembly Information:

Type: **RPDA** Location: Sprinkler Room East Side

3" Size: Hazard: **Fire Protection** Make: Wilkins Installation: Horizontal

Serial #: 1480

375ASTDA

Model:



Assembly Test Information:

Relief Valve	2.8	Open
Check Valve #2	10.8	Closed Tight/Held
Check Valve #1	11.2	Closed Tight/Held
	PSID	Test Result

Test Comments:

Left as Found ON.

Tester Information:

Device Supply Pressure: N/A

Tester Name: James Hermann Tester License Expiration: 04/30/2024 Certification #: XC4255

Test Kit Information:

Test Kit Serial #: 0042614 Test Kit Tested for Accuracy: 03/17/2023 Test Kit Mfr. & Mod. #: Watts, TK-99E As the tester of record, I affirm this test as PASS.



Test Company Information:

Testing Company Name: American Backflow & Fire Prevention 111 Kerry Lane, Wauconda, IL 60084 Address:

Phone: (847) 540-9910









