

JGC SERVICES INC.

971 East Oakton Street
 Elk Grove Village, IL 60007
 (847) 258-4412

BACKFLOW PREVENTER TESTING and CERTIFICATION REPORT

PASS FAIL

Name: Hinsdale 907 Medical Properties	Make: Apollo
Address: 907 Elm	Model: RP4A
Hinsdale, Illinois	Size: 1 1/2
Phone Number:	Serial Number: 630386
Email:	Date Tested: 5/1/2024
Service: Fire Bx Pass	Location: Sprinkler Rm
Test Kit: Midwest #10150685-845-5	Calibration Date: 8/15/23

Device: XRPZ DC DCDA PVB Supply Pressure 75 PSIG

	<u>Check Valve#1</u>	<u>Check Valve#2</u>	<u>Relief Valve</u>
Initial Test	Closed Tight <u>X</u> Leaked <u> </u>	Closed Tight <u>X</u> Leaked <u> </u>	Opened at: <u>2.5</u> PSID <u> </u> Did Not Open
Final Test	<u>6.7</u> PSID Closed Tight <u>X</u>	<u>6.2</u> PSID Closed Tight <u>X</u>	Opened at: <u>2.5</u> PSID

<u>Control Valve #1</u>	<u>Control Valve #2</u>	<u>Test Cocks</u>
Type <u>ball</u>	Type <u>ball</u>	<u>X</u> Complete
Closed Tight <u>X</u>	Closed Tight <u>X</u>	<u> </u> Missing # <u> </u>
Leaked <u> </u>	Leaked <u> </u>	<u> </u> Damaged

Special Comments: _____

The above information is correct Louis Carrozza
 Louis Carrozza
 CCCDI Approval# XC 5930
 IL License# 058-197270
 Joseph G. Carrozza
 CCCDI Approval# XC 2366
 IL License# 058-162777
 Chicago License# PL 14725

JGC SERVICES INC.

971 East Oakton Street
 Elk Grove Village, IL 60007
 (847) 258-4412

BACKFLOW PREVENTER TESTING and CERTIFICATION REPORT

PASS

FAIL

Name: <u>Hinsdale 907 Medical Properties</u>	Make: <u>Watts</u>
Address: <u>907 Elm</u>	Model: <u>009 M2</u>
<u>Hinsdale, IL</u>	Size: <u>2" M</u>
Phone Number:	Serial Number: <u>315861</u>
Email:	Date Tested: <u>5/1/24</u>
Service: <u>Irrigation</u>	Location: <u>Mech Pm</u>
Test Kit: <u>Midwest #1052685-8453</u>	Calibration Date: <u>8/15/23</u>

Device: XRPZ DC DCDA PVB Supply Pressure 65 PSIG

	<u>Check Valve#1</u>	<u>Check Valve#2</u>	<u>Relief Valve</u>
Initial Test	Closed Tight <input checked="" type="checkbox"/>	Closed Tight <input checked="" type="checkbox"/>	Opened at:
	Leaked <u>8.8</u> PSID	Leaked <u>7.0</u> PSID	<u>3.0</u> PSID
Final Test	Closed Tight <input checked="" type="checkbox"/>	Closed Tight <input checked="" type="checkbox"/>	Did Not Open
			Opened at: <u>3.0</u> PSID

<u>Control Valve #1</u>	<u>Control Valve #2</u>	<u>Test Cocks</u>
Type <u>ball</u>	Type <u>ball</u>	<input checked="" type="checkbox"/> Complete
Closed Tight <input checked="" type="checkbox"/>	Closed Tight <input checked="" type="checkbox"/>	<input type="checkbox"/> Missing # <u> </u>
Leaked <u> </u>	Leaked <u> </u>	<input type="checkbox"/> Damaged

Special Comments: _____

The above information is correct _____
 Louis Carrozza
 CCCDI Approval# XC 5930
 IL License# 058-197270

Joseph G. Carrozza
 CCCDI Approval# XC 2366
 IL License# 058-162777
 Chicago License# PL 14725

JGC SERVICES INC.

971 East Oakton Street
 Elk Grove Village, IL 60007
 (847) 258-4412

BACKFLOW PREVENTER TESTING and CERTIFICATION REPORT

PASS

FAIL

Name: Hinsdale 907 Medical Proper	Make: Apollo
Address: 907 Elm	Model: RPDA-4A
Hinsdale, Illinois	Size: 4"
Phone Number:	Serial Number: 47530
Email:	Date Tested: 5/1/2024
Service: Fire Protection	Location: Sprinkler Rm
Test Kit: Midwest #10152685-845-5	Calibration Date: 8/15/23

Device: RPZ DC DCDA PVB Supply Pressure 75 PSIG

	<u>Check Valve#1</u>	<u>Check Valve#2</u>	<u>Relief Valve</u>
Initial Test	Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/> <u>8.1</u> PSID	Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/> <u>6.0</u> PSID	Opened at: <u>2.2</u> PSID <input type="checkbox"/> Did Not Open
Final Test	Closed Tight <input checked="" type="checkbox"/>	Closed Tight <input checked="" type="checkbox"/>	Opened at: <u>2.2</u> PSID

<u>Control Valve #1</u>	<u>Control Valve #2</u>	<u>Test Cocks</u>
Type <u>OSY</u>	Type <u>OSY</u>	<input checked="" type="checkbox"/> Complete
Closed Tight <input checked="" type="checkbox"/>	Closed Tight <input checked="" type="checkbox"/>	<input type="checkbox"/> Missing # <u> </u>
Leaked <input type="checkbox"/>	Leaked <input type="checkbox"/>	<input type="checkbox"/> Damaged

Special Comments: _____

The above information is correct Luis Carrozza

Louis Carrozza
 CCCDI Approval# XC 5930
 IL License# 058-197270

Joseph G. Carrozza
 CCCDI Approval# XC 2366
 IL License# 058-162777
 Chicago License# PL 14725

JGC SERVICES INC.

971 East Oakton Street
 Elk Grove Village, IL 60007
 (847) 258-4412

BACKFLOW PREVENTER TESTING and CERTIFICATION REPORT

PASS

FAIL

Name: Hinsdale 907 Medical Properties	Make: Wilken
Address: 907 Elm	Model: 375
Hinsdale, IL	Size: 3"
Phone Number:	Serial Number: 16567C
Email:	Date Tested: 5/1/2024
Service: Domestic	Location: Sprinkler Rm
Test Kit: Minirest 8455-#10152685	Calibration Date: 8/15/23

Device: RPZ DC DCDA PVB Supply Pressure 70 PSIG

	<u>Check Valve#1</u>	<u>Check Valve#2</u>	<u>Relief Valve</u>
Initial Test	Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Closed Tight <input checked="" type="checkbox"/> Leaked <input type="checkbox"/>	Opened at: <u>2.1</u> PSID <input type="checkbox"/> Did Not Open
Final Test	<u>6.5</u> PSID Closed Tight <input checked="" type="checkbox"/>	<u>6.0</u> PSID Closed Tight <input checked="" type="checkbox"/>	Opened at: <u>2.1</u> PSID

<u>Control Valve #1</u>	<u>Control Valve #2</u>	<u>Test Cocks</u>
Type <u>gate</u>	Type <u>gate</u>	<input checked="" type="checkbox"/> Complete
Closed Tight <input checked="" type="checkbox"/>	Closed Tight <input checked="" type="checkbox"/>	<input type="checkbox"/> Missing # <u> </u>
Leaked <input type="checkbox"/>	Leaked <input type="checkbox"/>	<input type="checkbox"/> Damaged

Special Comments: _____

The above information is correct Luis Carrozza

<input checked="" type="checkbox"/> Louis Carrozza CCCDI Approval# XC 5930 IL License# 058-197270	<input type="checkbox"/> Joseph G. Carrozza CCCDI Approval# XC 2366 IL License# 058-162777 Chicago License# PL 14725
---	---