



2760 Beverly Dr.
Suite 9
Aurora, IL 60502
630.506.5535
www.allegiantfire.net

Report to: Remedy Medical Properties, Inc. **Date:** 02/06/2025
Property: RMP, 901 N Elm St **Job Number:** 38255039
Address: 901 North Elm Street
City: Hinsdale **Technician:** Mario Zavaleta
State: IL **Zip:** 60521

FIRE EXTINGUISHER INSPECTION REPORT

Service Information

Annual Inspection: ☒ Monthly Inspection: ☐ Quantity of Fire Extinguishers at location: 23
Service Call: ☐ Survey: ☐ Quantity of Extinguishers Needing Return Trip: 4

Extinguisher Annual Inspection

| Quantity | Size | Type |
|----------|--------|------|
| 19 | 10 lb. | ABC |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

Extinguishers Serviced During This Inspection

| Quantity | Size | Type | Reason |
|----------|------|------|--------|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Extinguishers To Be Serviced

| Quantity | Size | Type | Reason |
|----------|--------|------|----------|
| 3 | 10 lb. | ABC | 6 YEAR |
| 1 | 10 lb. | ABC | RECHARGE |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

Miscellaneous

| Quantity | Part | Notes |
|----------|------|-------|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

COMMENTS

All FE passed inspection and were in green charge zone upon departure.

Please sent quote for repairs.

LEE-26- (13)

INSPECTION & SUGGESTED IMPROVEMENTS WERE DISCUSSED WITH THE UNDERSIGNED OWNER OR OWNER'S REPRESENTATIVE:

By this signature, I certify that the information on this form is correct at the time and place of my inspection, and that all equipment tested at this time was left in operational condition upon completion of this inspection except as noted in comments above.

- ☒ Service work completed during this inspection
☐ Service work not completed due to insufficient equipment available

- ☐ Service work declined by owner/representative
☐ Special order items needed to complete job

OWNER / REPRESENTATIVE SIGNATURE

Steve Swat
PRINT NAME

2-6-2025
DATE

INSPECTOR SIGNATURE

Mario Zavaleta
PRINT NAME

LICENSE #



2760 Beverly Dr.
Suite 9
Aurora, IL 60502
630.506.5535
www.allegiantfire.net

Report to: Remedy Medical Properties, Inc.
Property: RMP, 901 N Elm St
Address: 901 North Elm Street
City: Hinsdale
State: IL **Zip:** 60521

Date: 02/06/2025
Job Number: 38255039
Technician: Mario Zavaleta

FIRE EXTINGUISHER LIST

[illegible]