

Inspection Report

Cross-Connection and Backflow-Prevention Assembly

Fox Valley Fire & Safety
2730 PINNACLE DR.
Elgin, IL 60123
224-802-8081


Date/Time of Test 2025-09-25
PASS / FAIL PASS

Device Notes Completed repair

Site Name Royal Blvd Condo Association CCN/Site ID _____
Address 2350 Royal Blvd City Elgin State IL Zip 60123
Location of Assembly Sprinkler Room Control Valve Type Ball Valve
Type of Service Irrigation Type of Assembly RPZ Device ID DEV55964
Mfg Wilkins Size 1-1/2 Inch Model # 975XL Serial # 1151493
Position Horizontal

TESTED BY

Company Backflow Testing Services Address 1051 E. Main Street, Unit 107 - East Dundee, IL 60118

Name of Tester	CCCDI#	License #	Test Kit S/N (MIDWEST 845)
<input checked="" type="checkbox"/> Roy C. Thompson	XC 3849	058-136490	10231485 
<input type="checkbox"/> Michael A. Popp	XC 3845	058-165952	05190231
<input type="checkbox"/> Nicholas Ross	XC5148	058-197421	TG04192018
<input type="checkbox"/> Roy Thompson	XC 5977	058-198708	11201079
<input type="checkbox"/> Brandon Meisner	XC5761	058-175357	04232083

Calibration Date: 2024-12-02

Date of Retest: 2026-09-25

Line Pressure at Time of Test (psi): 50

DOF B-P

CHECK VALVE #1

Initial Test

Leaked

Closed Tight: 7.8

Repairs

Cleaned

Replaced

Disc

Spring

Guide

O-Rings

Seat

Other

Comments:

Final Test

Closed Tight: 7.8

CHECK VALVE #2

Initial Test

Leaked

Closed Tight: 7.6

Repairs

Cleaned

Replaced

Disc

Spring

Guide

O-Rings

Seat

Other

Comments:

Final Test

Closed Tight: 7.676

DIFFERENTIAL PRESSURE RELIEF VALVE

Initial Test

Did Not Open

Opened at Reduced Pressure (psid): 2.6

Repairs

Cleaned

Replaced

Disc, upper

Disc, lower

Spring

Spacer, lower

Diaphragm, LG

Upper

Lower

Diaphragm, SM

Upper

Lower

Other

Comments:

Final Test

Opened at reduced pressure (psid): 2.6

Inspection Report

Cross-Connection and Backflow-Prevention Assembly

Fox Valley Fire & Safety
2730 PINNACLE DR.
Elgin, IL 60123
224-802-8081


Date/Time of Test 2025-09-25
PASS / FAIL PASS

Device Notes Completed repair

Site Name Royal Blvd Condo Association CCN/Site ID _____
Address 2350 Royal Blvd City Elgin State IL Zip 60123
Location of Assembly Sprinkler Room Control Valve Type Ball Valve
Type of Service Domestic Line Type of Assembly RPZ Device ID DEV55965
Mfg Watts Size 2 Inch Model # 909 Serial # 359621
Position Horizontal

TESTED BY

Company Backflow Testing Services Address 1051 E. Main Street, Unit 107 - East Dundee, IL 60118

Name of Tester	CCCDI#	License #	Test Kit S/N (MIDWEST 845)
<input checked="" type="checkbox"/> Roy C. Thompson	XC 3849	058-136490	10231485 
<input type="checkbox"/> Michael A. Popp	XC 3845	058-165952	05190231
<input type="checkbox"/> Nicholas Ross	XC5148	058-197421	TG04192018
<input type="checkbox"/> Roy Thompson	XC 5977	058-198708	11201079
<input type="checkbox"/> Brandon Meisner	XC5761	058-175357	04232083

Calibration Date: 2024-12-02

Date of Retest: 2026-09-25

Line Pressure at Time of Test (psi): 60

DOF B-P

CHECK VALVE #1	CHECK VALVE #2	DIFFERENTIAL PRESSURE RELIEF VALVE
Initial Test <input type="checkbox"/> Leaked Closed Tight: <u>8</u>	Initial Test <input type="checkbox"/> Leaked Closed Tight: <u>7.6</u>	Initial Test <input type="checkbox"/> Did Not Open Opened at Reduced Pressure (psid): <u>2.4</u>
Repairs <input type="checkbox"/> Cleaned <input checked="" type="checkbox"/> Replaced <input checked="" type="checkbox"/> Disc <input type="checkbox"/> Spring <input type="checkbox"/> Guide <input checked="" type="checkbox"/> O-Rings <input type="checkbox"/> Seat <input type="checkbox"/> Other	Repairs <input type="checkbox"/> Cleaned <input checked="" type="checkbox"/> Replaced <input checked="" type="checkbox"/> Disc <input type="checkbox"/> Spring <input type="checkbox"/> Guide <input checked="" type="checkbox"/> O-Rings <input type="checkbox"/> Seat <input type="checkbox"/> Other	Repairs <input type="checkbox"/> Cleaned <input checked="" type="checkbox"/> Replaced <input checked="" type="checkbox"/> Disc, upper <input checked="" type="checkbox"/> Disc, lower <input type="checkbox"/> Spring <input checked="" type="checkbox"/> Spacer, lower <input type="checkbox"/> Diaphragm, LG <input type="checkbox"/> Upper <input type="checkbox"/> Lower <input type="checkbox"/> Diaphragm, SM <input type="checkbox"/> Upper <input type="checkbox"/> Lower <input type="checkbox"/> Other
Comments:	Comments:	Comments:
Final Test Closed Tight: <u>8</u>	Final Test Closed Tight: <u>7.6</u>	Final Test Opened at reduced pressure (psid): <u>2.4</u>