

ROYAL BLVD CONDO ASSOCIATION 2350 ROYAL BLVD ELGIN, IL 60123

Annual Fire Alarm Inspection



0

Seq #	Device Number	Device	Zone / Device #	MFG	Model	Floor	Location	MM/ZP	Technician Initials
								01/12/26	Start Date
								Status	NFPA Reference / Comments
2	1	ANN		NOTIFIER	LCD-80	1	MAIN ENTRANCE VESTIBULE	P-1/12/26	
124	1	B		POTTER	PBA1206	1	SPRINKLER RM	P-1/12/26	
18	1	DD	D11	NOTIFIER	FSD-751P	100	ABOVE CEILING IN EXAM RM 7	P-1/12/26	FSD GOOD
27	2	DD	D09	SYS. SENSOR	DNR	100	ABOVE CEILING BEHIND NURSES STATION BY RTS	P-1/12/26	FSD GOOD MODEL UPDATED 1/12/26
31	3	DD	D17	NOTIFIER	FSD-751P	600	ABOVE CEILING IN INSURANCE OFFICE	P-1/12/26	FSD GOOD
42	4	DD	D19	NOTIFIER	FSD-751P	600	ABOVE CEILING BEHIND NURSES STATION	N/T	FSD GOOD/ RTS ONLY PER MEDICAL DIRECTOR
49	5	DD	D13	NOTIFIER	FSD-751P	200	ABOVE RTS BY RECEPTION	P-1/12/26	FSD GOOD
87	6	DD	D21	NOTIFIER	FSD-751P	500	ABOVE CEILING BY EXAM RM 7	P-1/12/26	FSD GOOD
104	7	DD	D23	NOTIFIER	FSD-751P	500	ABOVE CEILING BY NURSES STATION	P-1/12/26	FSD GOOD
113	8	DD	D25	NOTIFIER	FSD-751P	400	ABOVE RTS BY EXAM RM 3	P-1/12/26	FSD GOOD
141	9	DD	D15	NOTIFIER	FSD-751P	300	ABOVE CEILING IN EXAM RM 9	P-1/12/26	FSD GOOD
151	10	DD	D27	NOTIFIER	FSD-751P	1	HALLWAY SUITE 400 STORAGE CLOSET BY SPRINKLER RM	P-1/12/26	FSD GOOD
3	1	HS		SYS. SENSOR	P241575	1	BY MAIN ENTRANCE VESTIBULE	P-1/12/26	
4	2	HS		SYS. SENSOR	P241575	100	IN WAITING AREA	P-1/12/26	
8	3	HS		SYS. SENSOR	P241575	100	BY NURSES STATION	P-1/12/26	
21	4	HS		SYS. SENSOR	P241575	100	REAR EXIT	P-1/12/26	
32	5	HS		SYS. SENSOR	P241575	600	BY EXAM RM 6	P-1/12/26	
44	6	HS		SYS. SENSOR	P241575	600	REAR EXIT	P-1/12/26	
47	7	HS		SYS. SENSOR	P241575	200	IN WAITING AREA	P-1/12/26	
59	8	HS		SYS. SENSOR	P241575	800	BY REAR RESTROOM (THRU SUITE 200)	P-1/12/26	
67	9	HS		SYS. SENSOR	P241575	800	MRI ENTRANCE (THRU SUITE 200)	P-1/12/26	
70	10	HS		SYS. SENSOR	P241575	200	BY DARK RM	P-1/12/26	
73	11	HS		SYS. SENSOR	P241575	200	REAR EXIT	P-1/12/26	
78	12	HS		SYS. SENSOR	P241575	200	BY REAR SUITE 700 ENTRANCE	P-1/12/26	
80	13	HS		SYS. SENSOR	P241575	700	THERAPY RM (THRU SUITE 200)	P-1/12/26	
81	14	HS		SYS. SENSOR	P241575	700	THERAPY ENTRANCE (THRU SUITE 200)	P-1/12/26	
84	15	HS		SYS. SENSOR	P241575	500	BY RECEPTION	P-1/12/26	OUT OF SYNC
98	16	HS		SYS. SENSOR	P241575	500	REAR EXIT	P-1/12/26	OUT OF SYNC
107	17	HS		SYS. SENSOR	P241575	400	IN WAITING AREA	P-1/12/26	
115	18	HS		SYS. SENSOR	P241575	400	REAR EXIT	P-1/12/26	
117	19	HS		SYS. SENSOR	P241575	1	IN HALL BY RESTROOMS	P-1/12/26	
127	20	HS		SYS. SENSOR	P241575	1	EXIT BY SPRINKLER RM	P-1/12/26	
131	21	HS		SYS. SENSOR	P241575	300	IN WAITING AREA	P-1/12/26	
152	22	HS		SYS. SENSOR	P241575	300	BY EXAM RM 2	P-1/12/26	
143	23	HS		SYS. SENSOR	P241575	300	REAR EXIT	P-1/12/26	
144	24	HS		SYS. SENSOR	P241575	300	BY EXAM RM 10	P-1/12/26	
149	25	HS		SYS. SENSOR	P241575	300	BY ADMINISTRATIVE OFFICE	P-1/12/26	
63	1	MISC	M46	NOTIFIER	FMM-1	800	HALL BY MRI TECH OFFICE (ABOVE FM-200 SYSTEM) - FM-200 ALARM	P-1/12/26	CIRCUIT TESTED - ADDED 10/17/24
64	2	MISC	M47	NOTIFIER	FMM-1	800	HALL BY MRI TECH OFFICE (ABOVE FM-200 SYSTEM) - FM-200 TROUBLE	P-1/12/26	CIRCUIT TESTED - ADDED 10/17/24
153	3	MISC	M43	NOTIFIER	FRM-1	1	SPRINKLER RM ABOVE FACP	P-1/12/26	
1	1	PS	M37	NOTIFIER	NBG-12LX	1	MAIN ENTRANCE VESTIBULE	P-1/12/26	

Seq #	Device Number	Device	Zone / Device #	MFG	Model	Floor	Location	01/12/26	Start Date	Status	NFPA Reference / Comments
20	2	PS	M29	NOTIFIER	NBG-12LX	100	REAR EXIT			P-1/12/26	
45	3	PS	M34	NOTIFIER	NBG-12LX	600	REAR EXIT			P-1/12/26	
66	4	PS	M36	NOTIFIER	NBG-12LX	800	MRI ENTRANCE (THRU SUITE 200)			P-1/12/26	
72	5	PS	M30	NOTIFIER	NBG-12LX	200	REAR EXIT			P-1/12/26	
82	6	PS	M35	NOTIFIER	NBG-12LX	700	THERAPY ENTRANCE (THRU SUITE 200)			P-1/12/26	
97	7	PS	M33	NOTIFIER	NBG-12LX	500	REAR EXIT			P-1/12/26	
116	8	PS	M32	NOTIFIER	NBG-12LX	400	REAR EXIT			P-1/12/26	
126	9	PS	M38	NOTIFIER	NBG-12LX	1	EXIT BY SPRINKLER RM			P-1/12/26	
142	10	PS	M31	NOTIFIER	NBG-12LX	300	REAR EXIT			P-1/12/26	
57	1	RP/PS	(M45)	HONEYWELL	HPF-PS6	200	MECHANICAL ROOM - 12V/18AH BATTERIES			P-1/12/26	
128	2	RP/PS	(B01)	NOTIFIER	FCPS-24F	1	SPRINKLER RM - 12V/7AH BATTERIES			F-1/12/26	BATTERIES FAILED
129	3	RP/PS	(B01)	NOTIFIER	FCPS-24F	1	SPRINKLER RM - 12V/7AH BATTERIES			F-1/12/26	BATTERIES FAILED
130	4	RP/PS	(B01)	NOTIFIER	FCPS-24F	1	SPRINKLER RM - 12V/7AH BATTERIES			F-1/12/26	BATTERIES FAILED
17	1	RTS		SYS. SENSOR	RTS451	100	IN HALL BY EXAM RM 6			P-1/12/26	
26	2	RTS		SYS. SENSOR	RTS451	100	BEHIND NURSES STATION			P-1/12/26	
30	3	RTS		SYS. SENSOR	RTS451	600	IN INSURANCE OFFICE			P-1/12/26	
41	4	RTS		SYS. SENSOR	RTS451	600	BEHIND NURSES STATION			P-1/12/26	
48	5	RTS		SYS. SENSOR	RTS451	200	BY RECEPTION			P-1/12/26	
86	6	RTS		SYS. SENSOR	RTS451	500	IN HALL BY EXAM RM BY RECEPTION			P-1/12/26	
103	7	RTS		SYS. SENSOR	RTS451	500	BY NURSES STATION			P-1/12/26	
112	8	RTS		SYS. SENSOR	RTS451	400	IN HALL BY EXAM RM 4			P-1/12/26	
140	9	RTS		SYS. SENSOR	RTS451	300	BY EXAM RM 6			P-1/12/26	
150	10	RTS		SYS. SENSOR	RTS451	1	SUITE 400 STORAGE CLOSET BY SPRINKLER RM			P-1/12/26	
58	1	SD	D30	NOTIFIER	FSP-951-IV	200	MECHANICAL ROOM			P-1/12/26	
125	2	SD	D01	NOTIFIER	FSP-751	1	SPRINKLER RM			P-1/12/26	
5	1	ST		SYS. SENSOR	S241575	100	BY RECEPTION			P-1/12/26	
6	2	ST		SYS. SENSOR	S241575	100	BY BUSINESS OFFICE			P-1/12/26	
7	3	ST		SYS. SENSOR	S241575	100	EMPLOYEE BREAK RM			P-1/12/26	
9	4	ST		SYS. SENSOR	SC241575W	100	EXAM RM 10			P-1/12/26	
10	5	ST		SYS. SENSOR	SC241575W	100	EXAM RM 9			P-1/12/26	
11	6	ST		SYS. SENSOR	S241575	100	RESTROOM BY EXAM RM 9			P-1/12/26	
12	7	ST		SYS. SENSOR	SC241575W	100	EXAM RM 8			P-1/12/26	
13	8	ST		SYS. SENSOR	S241575	100	IN RESTROOM BY EXAM RM 8			P-1/12/26	
14	9	ST		SYS. SENSOR	S241575	100	IN RESTROOM BY EXAM RM 6			P-1/12/26	
15	10	ST		SYS. SENSOR	SC241575W	100	EXAM RM 7			P-1/12/26	
16	11	ST		SYS. SENSOR	SC241575W	100	EXAM RM 6			P-1/12/26	
19	12	ST		SYS. SENSOR	SC241575W	100	EXAM RM 5			P-1/12/26	
22	13	ST		SYS. SENSOR	SC241575W	100	EXAM RM 4			P-1/12/26	
23	14	ST		SYS. SENSOR	SC241575W	100	EXAM RM 3			P-1/12/26	
24	15	ST		SYS. SENSOR	SC241575W	100	EXAM RM 2			P-1/12/26	
25	16	ST		SYS. SENSOR	SC241575W	100	EXAM RM 1			P-1/12/26	
28	17	ST		SYS. SENSOR	S241575	600	IN WAITING AREA			P-1/12/26	
29	18	ST		SYS. SENSOR	S241575	600	BY RECEPTION			P-1/12/26	
33	19	ST		SYS. SENSOR	SC241575W	600	EXAM RM 6			P-1/12/26	

Seq #	Device Number	Device	Zone / Device #	MFG	Model	Floor	Location	01/12/26	Start Date	Status	NFPA Reference / Comments
34	20	ST		SYS. SENSOR	S241575	600	EXAM RM 5			P-1/12/26	
35	21	ST		SYS. SENSOR	SC241575W	600	EXAM RM 4			P-1/12/26	
36	22	ST		SYS. SENSOR	SC241575W	600	EXAM RM 3			P-1/12/26	
37	23	ST		SYS. SENSOR	SC241575W	600	EXAM RM 7			P-1/12/26	
38	24	ST		SYS. SENSOR	SC241575W	600	EXAM RM 2			P-1/12/26	
39	25	ST		SYS. SENSOR	S241575	600	RESTROOM BY EXAM RM 2			P-1/12/26	
40	26	ST		SYS. SENSOR	SC241575W	600	EXAM RM 1			P-1/12/26	
43	27	ST		SYS. SENSOR	S241575	600	IN RESTROOM BY REAR EXIT			P-1/12/26	
46	28	ST		SYS. SENSOR	S241575	600	EMPLOYEE BREAK RM			P-1/12/26	
50	29	ST		SYS. SENSOR	SC241575W	200	EXAM RM 1			P-1/12/26	
51	30	ST		SYS. SENSOR	S241575	200	IN RESTROOM BY EXAM RM 2			P-1/12/26	
52	31	ST		SYS. SENSOR	SC241575W	200	EXAM RM 2			P-1/12/26	
53	32	ST		SYS. SENSOR	SC241575W	200	EXAM RM 6			P-1/12/26	
54	33	ST		SYS. SENSOR	SC241575W	200	EXAM RM 3			P-1/12/26	
55	34	ST		SYS. SENSOR	SC241575W	200	EXAM RM 4			P-1/12/26	
56	35	ST		SYS. SENSOR	SC241575W	200	EXAM RM 5			P-1/12/26	
60	36	ST		SYS. SENSOR	S241575	800	IN RESTROOM (THRU SUITE 200)			P-1/12/26	
61	37	ST		SYS. SENSOR	SR	800	MRI CHANGING ROOM BY TECH OFFICE (THRU SUITE 200)			P-1/12/26	
62	38	ST		SYS. SENSOR	SR	800	MRI TECH OFFICE (THRU SUITE 200)			P-1/12/26	
65	39	ST		SYS. SENSOR	SCR	800	WAITING AREA (THRU SUITE 200)			P-1/12/26	
68	40	ST		SYS. SENSOR	SC2475W	800	EMPLOYEE BREAK RM (THRU SUITE 200)			P-1/12/26	
69	41	ST		SYS. SENSOR	S241575	200	DARK RM			P-1/12/26	
71	42	ST		SYS. SENSOR	SC241575W	200	IN X-RAY RM			P-1/12/26	
74	43	ST		SYS. SENSOR	S241575	200	CONFERENCE RM RESTROOM BY REAR EXIT			P-1/12/26	
75	44	ST		SYS. SENSOR	S241575	200	IN RESTROOM BY CONFERENCE RM			P-1/12/26	
76	45	ST		SYS. SENSOR	S241575	200	REAR RESTROOM			P-1/12/26	
77	46	ST		SYS. SENSOR	S241575	200	EMPLOYEE BREAK RM			P-1/12/26	
79	47	ST		SYS. SENSOR	S241575	700	IN RESTROOM (THRU SUITE 200)			P-1/12/26	
83	48	ST		SYS. SENSOR	S241575	500	IN WAITING AREA			P-1/12/26	OUT OF SYNC
85	49	ST		SYS. SENSOR	SC241575W	500	EXAM RM BY RECEPTION			P-1/12/26	OUT OF SYNC
88	50	ST		SYS. SENSOR	SC241575W	500	EXAM RM 6			P-1/12/26	OUT OF SYNC
89	51	ST		SYS. SENSOR	S241575	500	WAITING AREA BY EXAM RM 6			P-1/12/26	OUT OF SYNC
90	52	ST		SYS. SENSOR	SC241575W	500	EXAM RM 5			P-1/12/26	OUT OF SYNC
91	53	ST		SYS. SENSOR	SC241575W	500	EXAM RM BY EXAM RM 5			P-1/12/26	OUT OF SYNC
92	54	ST		SYS. SENSOR	SC241575W	500	EXAM RM BY EXAM RM 5			P-1/12/26	OUT OF SYNC
93	55	ST		SYS. SENSOR	SC241575W	500	EXAM RM BY EXAM RM 5			P-1/12/26	OUT OF SYNC
94	56	ST		SYS. SENSOR	SC241575W	500	EXAM RM REAR HALL			P-1/12/26	OUT OF SYNC
95	57	ST		SYS. SENSOR	S241575	500	IN OFFICE REAR HALL			P-1/12/26	OUT OF SYNC
96	58	ST		SYS. SENSOR	S241575	500	HEARING EXAM RM REAR HALL			P-1/12/26	OUT OF SYNC
99	59	ST		SYS. SENSOR	SC241575W	500	EXAM RM BY REAR EXIT			P-1/12/26	OUT OF SYNC
100	60	ST		SYS. SENSOR	SC241575W	500	EXAM RM BY REAR EXIT			P-1/12/26	OUT OF SYNC
101	61	ST		SYS. SENSOR	SC241575W	500	EXAM RM 2			P-1/12/26	OUT OF SYNC
102	62	ST		SYS. SENSOR	SC241575W	500	EXAM RM 1			P-1/12/26	OUT OF SYNC
105	63	ST		SYS. SENSOR	S241575	500	EMPLOYEE BREAK RM			P-1/12/26	OUT OF SYNC

								01/12/26	Start Date
Seq #	Device Number	Device	Zone / Device #	MFG	Model	Floor	Location	Status	NFPA Reference / Comments
106	64	ST		SYS. SENSOR	S241575	500	IN RESTROOM BY EMPLOYEE BREAK RM	P-1/12/26	OUT OF SYNC
108	65	ST		SYS. SENSOR	SC241575W	400	EXAM RM 1	P-1/12/26	
109	66	ST		SYS. SENSOR	SC241575W	400	EXAM RM 2	P-1/12/26	
110	67	ST		SYS. SENSOR	SC241575W	400	EXAM RM 3	P-1/12/26	
111	68	ST		SYS. SENSOR	SC241575W	400	EXAM RM 4	P-1/12/26	
114	69	ST		SYS. SENSOR	S241575	400	IN RESTROOM BY REAR EXIT	P-1/12/26	
118	70	ST		SYS. SENSOR	S241575	1	IN WOMENS RESTROOM	P-1/12/26	
119	71	ST		SYS. SENSOR	S241575	1	IN MENS RESTROOM	P-1/12/26	
132	72	ST		SYS. SENSOR	SC241575W	300	EXAM RM 1	P-1/12/26	
133	73	ST		SYS. SENSOR	SC241575W	300	EXAM RM 2	P-1/12/26	
134	74	ST		SYS. SENSOR	S241575	300	IN RESTROOM BY EXAM RM 1	P-1/12/26	
135	75	ST		SYS. SENSOR	SC241575W	300	EXAM RM 3	P-1/12/26	
136	76	ST		SYS. SENSOR	S241575	300	IN RESTROOM BY EXAM RM 3	P-1/12/26	
137	77	ST		SYS. SENSOR	SC241575W	300	EXAM RM 4	P-1/12/26	
138	78	ST		SYS. SENSOR	SC241575W	300	EXAM RM 5	P-1/12/26	
139	79	ST		SYS. SENSOR	SC241575W	300	EXAM RM 6	P-1/12/26	
145	80	ST		SYS. SENSOR	SC241575W	300	EXAM RM 10	P-1/12/26	
146	81	ST		SYS. SENSOR	SC241575W	300	EXAM RM 7	P-1/12/26	
147	82	ST		SYS. SENSOR	SC241575W	300	EXAM RM 8	P-1/12/26	
148	83	ST		SYS. SENSOR	S241575	300	EMPLOYEE BREAK RM	P-1/12/26	
120	1	VT	M42	MILWAUKEE	B-FLY	1	ABOVE FACP IN SPRINKLER RM	P-1/12/26	REPORTS AS TROUBLE
121	2	VT	M39	POTTER	OSYSU-2	1	SPRINKLER RM	P-1/12/26	REPORTS AS TROUBLE
122	3	VT	M40	POTTER	OSYSU-2	1	SPRINKLER RM	P-1/12/26	REPORTS AS TROUBLE
123	1	WF	M41	POTTER	VSR-F	1	SPRINKLER RM	P-1/12/26	