

# Fire Alarm Systems

# 2026



## Wheaton Office

120 East Liberty Drive  
Wheaton, IL 60187  
630-230-1221

**Building Contact:** Nathan Sands  
**Title:** Property Manager  
  
**Company:** SMG & CAS Security Holdings LLC  
**Contact:** Roland Pizarro  
**Title:** Inspections

**Inspection Date: Jan 19, 2026**  
**Tested to NFPA 72 Standards**



This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.



# EXECUTIVE SUMMARY

Generated by: BuildingReports.com

## Building Information

<b>Wheaton Office</b> 120 East Liberty Drive Wheaton, IL 60187 United States of America	<b>Contact:</b> Nathan Sands
	<b>Phone:</b> 630-230-1221
	<b>Fax:</b>
	<b>Mobile:</b>
	<b>Email:</b> nsands@wavelandprop.com

## Inspection Performed By

<b>SMG &amp; CAS Security Holdings LLC</b> 120 King Street Elk Grove Village, Illinois 60007-1111 United States of America	<b>Inspector:</b> Roland Pizarro
	<b>Phone:</b> 708-238-0345
	<b>Fax:</b>
	<b>Mobile:</b> 708-238-0345
	<b>Email:</b> rpizarro@smgsecurity.com

## System Control Unit

<b>Manufacturer:</b> Silent Knight	<b>Inspection Date:</b> 01/19/2026	<b>IDC Style:</b>
<b>Model Number:</b> IFP-1000	<b>Install Date:</b> 09/18/2014	<b>SLC Style:</b>
<b>Software Version:</b>	<b>Version Date:</b> 09/18/2014	<b>NAC Style:</b> Y
<b>Location:</b> Pump Room FACP	<b>Disconnect Location:</b>	<b>Disconnect Type:</b>
<b>Current Protection:</b> Breaker		

## Monitoring

<b>Company:</b> DuCom	<b>Phone:</b> 6306908245	<b>Account #:</b> 6339
-----------------------	--------------------------	------------------------


## Inspection Summary

Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	28	20.44%	28	100.00%	28	100.00%	0	0.00%
Indicating	1	0.73%	1	100.00%	1	100.00%	0	0.00%
Initiating	87	63.50%	87	100.00%	86	98.85%	1	1.15%
Supervisory	21	15.33%	21	100.00%	21	100.00%	0	0.00%
<b>Totals</b>	<b>137</b>	<b>100%</b>	<b>137</b>	<b>100.00%</b>	<b>136</b>	<b>99.27%</b>	<b>1</b>	<b>0.73%</b>

## Certification

**Company:** SMG & CAS Security Holdings LLC


**Inspector:** Roland Pizarro



**Signed:** Jan 19, 2026

**Building:** Wheaton Office

**Contact:** Nathan Sands



**Signed:** Jan 19, 2026

# DISCREPANCY REPORT

## Deficiency, Impairment, and Observation

Generated by: [BuildingReports.com](http://BuildingReports.com)

The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is subject to a recall or part of a manufacturer's replacement/upgrade program is included.

**Building:** Wheaton Office

### Items listed for Recall or Replacement/Upgrade

Device Type	Manufacturer	Model Number	Date	Qty
-------------	--------------	--------------	------	-----

No recalled items found during this inspection.

**Building:** Wheaton Office

**Control Panel:** 1 - Silent Knight IFP-1000

### Discrepancies

ScanID	Location	Problem	Address	Reference
--------	----------	---------	---------	-----------

#### INITIATING

#### Duct Detector

32703893	3rd West Office By Cubicle 3-109 SD-3W	Failed Operation	1-M33 M62	NFPA72 14.2.1.2.2
----------	--	------------------	-----------	----------------------

### Code References

<b>NFPA72 14.2.1.2.2</b>	System defects and malfunctions shall be corrected.
--------------------------	---

# PROPOSED SOLUTIONS REPORT

Generated by: BuildingReports.com

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

**Building:** Wheaton Office

**Control Panel:** 1 - Silent Knight IFP-1000

ScanID	Location	Solution	Model #	Cost	Fix
<b>INITIATING</b>					
<b>Duct Detector</b>					
32703893	3rd West Office By Cubicle 3-109 SD-3W	Investigate	RTS451	T/M	<input type="checkbox"/>
		<b>Customer WO/PO #:</b> (none)	<b>Internal WO/PO #:</b> (none)	<b>Total:</b> T/M	

# NOTES & RECOMMENDATIONS

Generated by: BuildingReports.com

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

**Building:** Wheaton Office

**Control Panel:** 1 - Silent Knight IFP-1000

Note	Device Type	Location	Comment	ScanID
<b>INITIATING</b>				
1	Pull Station	Suite 190 North Main Entrance	Passed	A3345875
Trim around Pull station will not allow it to be pulled or opened to be reset.				
2	Pull Station	Suite 190 West Kitchen Exit	Passed	76318903
Allen key lock rounded no way to open pull station for reset. Did not test.				

# INSPECTION & TESTING

Generated by: [BuildingReports.com](https://BuildingReports.com)

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other . Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

**Building:** Wheaton Office

**Control Panel:** 1 - Silent Knight IFP-1000

Device Type	Location	Service	Time	Date
<b>PASSED</b>				
<b>Control</b>				
Annunciator	1st North Main Entrance	Tested	8:52:03 AM	01/19/2026
Battery	Pump Room FACP Battery	Tested	7:18:27 AM	01/19/2026
Battery	Pump Room FACP Battery	Tested	7:19:12 AM	01/19/2026
Battery	Pump Room FCPS Battery	Tested	7:17:41 AM	01/19/2026
Battery	Pump Room FCPS Battery	Tested	7:18:08 AM	01/19/2026
Battery	Suite 140 Electric Room NAC Battery	Tested	8:56:44 AM	01/19/2026
Battery	Suite 140 Electric Room NAC Battery	Tested	8:57:48 AM	01/19/2026
Battery	Suite 190 FCPS NAC Battery	Tested	12:57:25 PM	01/19/2026
Battery	Suite 190 FCPS NAC Battery	Tested	12:57:56 PM	01/19/2026
Battery	2nd MPOP Room NAC Battery	Tested	9:33:04 AM	01/19/2026
Battery	2nd MPOP Room NAC Battery	Tested	9:33:35 AM	01/19/2026
Battery	4th MPOP Room 3rd Floor NAC Battery	Tested	8:34:22 AM	01/19/2026
Battery	4th MPOP Room 3rd Floor NAC Battery	Tested	8:34:55 AM	01/19/2026
Battery	4th MPOP Room 5th Floor NAC Battery	Tested	8:29:23 AM	01/19/2026
Battery	4th MPOP Room 5th Floor NAC Battery	Tested	8:29:51 AM	01/19/2026
Battery	4th MPOP Room For 4th Floor NAC Battery	Tested	8:36:41 AM	01/19/2026
Battery	4th MPOP Room For 4th Floor NAC Battery	Tested	8:36:56 AM	01/19/2026
Battery	4th MPOP Room NAC Battery	Tested	8:31:53 AM	01/19/2026
Battery	4th MPOP Room NAC Battery	Tested	8:32:37 AM	01/19/2026

Device Type	Location	Service	Time	Date
<b>PASSED</b> (continued)				
<b>Control</b> (continued)				
Control Panel	Pump Room FACP	Tested	7:16:55 AM	01/19/2026
Power Supply	Pump Room NAC	Tested	7:17:24 AM	01/19/2026
Power Supply	Suite 140 Electric Room NAC	Tested	8:57:56 AM	01/19/2026
Power Supply	Suite 190 Rear Kitchen By Freezer NAC	Tested	12:56:28 PM	01/19/2026
Power Supply	2nd MPOP Room NAC	Tested	9:32:15 AM	01/19/2026
Power Supply	4th MPOP Room	Tested	8:31:25 AM	01/19/2026
Power Supply	4th MPOP Room 3rd Floor NAC	Tested	8:33:25 AM	01/19/2026
Power Supply	4th MPOP Room 5th Floor NAC	Tested	8:27:22 AM	01/19/2026
Power Supply	4th MPOP Room For 4th Floor NAC	Tested	8:35:37 AM	01/19/2026
<b>Initiating</b>				
Duct Detector	Suite 190 Beverage Area	Tested	1:02:19 PM	01/19/2026
Duct Detector	Suite 190 Beverage Area	Tested	1:02:52 PM	01/19/2026
Duct Detector	Suite 190 Rear Kitchen By Freezer	Tested	12:58:28 PM	01/19/2026
Duct Detector	2nd North Lobby Storage Room East Duct	Tested	10:22:41 AM	01/19/2026
Duct Detector	2nd West Electrical closet By Copier/Kitchen	Tested	9:45:29 AM	01/19/2026
Duct Detector	3rd East Hallway By Locker Rooms	Tested	10:28:48 AM	01/19/2026
Duct Detector	4th East Office By East Stairs SD-4E	Tested	8:18:38 AM	01/19/2026
Duct Detector	4th West Office By Room 4-154 SD-4W	Tested	8:39:04 AM	01/19/2026
Duct Detector	5th SD-5E By IT Lab	Tested	8:02:01 AM	01/19/2026
Duct Detector	5th West Office By Room 5-137 SD-5W	Tested	8:10:48 AM	01/19/2026
Heat Detector	Pump Room Above FACP	Tested	11:18:41 AM	01/19/2026
Heat Detector	1st Electrical Room By Elevators	Tested	2:14:15 PM	01/19/2026
Heat Detector	1st Emergency Electrical Room By Managers Office	Tested	2:16:57 PM	01/19/2026
Heat Detector	1st MPOP Room	Tested	2:14:24 PM	01/19/2026
Heat Detector	1st Main Electrical Room By Managers Office	Tested	2:16:46 PM	01/19/2026

Device Type	Location	Service	Time	Date
<b>PASSED</b> (continued)				
<b>Initiating</b> (continued)				
Heat Detector	2nd Electrical Room	Tested	2:04:15 PM	01/19/2026
Heat Detector	2nd MPOP Room	Tested	2:05:55 PM	01/19/2026
Heat Detector	3rd Electrical Room	Tested	1:59:45 PM	01/19/2026
Heat Detector	3rd MPOP Room	Tested	2:00:17 PM	01/19/2026
Heat Detector	4th Electrical Room	Tested	1:48:35 PM	01/19/2026
Heat Detector	4th MPOP Room	Tested	1:51:30 PM	01/19/2026
Heat Detector	5th Electrical Room	Tested	1:38:02 PM	01/19/2026
Heat Detector	5th Elevator 1 & 2 Machine Room	Tested	1:40:23 PM	01/19/2026
Heat Detector	5th Elevator 3 Machine Room	Tested	1:42:19 PM	01/19/2026
Heat Detector	5th MPOP Room	Tested	1:45:29 PM	01/19/2026
Heat Detector	5th Elevators 1 Shaft	Tested	1:31:58 PM	01/19/2026
Heat Detector	5th Elevators 1 & 2 Shaft	Tested	1:31:39 PM	01/19/2026
Heat Detector	Garage Electrical Room	Tested	3:49:00 PM	01/19/2026
Heat Detector	Garage Pit	Tested	1:29:00 PM	01/19/2026
Heat Detector	Garage Elevator Pit	Tested	1:30:31 PM	01/19/2026
Heat Detector	Garage Elevator Pit Pit	Tested	1:30:02 PM	01/19/2026
Pull Station	Pump Room Exit Door	Tested	10:51:28 AM	01/19/2026
Pull Station	Suite 100 North Exit	Tested	10:12:23 AM	01/19/2026
Pull Station	Suite 140 Main Entrance	Tested	8:53:40 AM	01/19/2026
Pull Station	Suite 190 North Exit	Tested	12:50:38 PM	01/19/2026
Pull Station	Suite 190 North Main Entrance	Tested	12:53:05 PM	01/19/2026
Pull Station	Suite 190 West Dining Room Exit	Tested	12:53:41 PM	01/19/2026
Pull Station	Suite 190 West Kitchen Exit	Tested	12:55:03 PM	01/19/2026
Pull Station	1st East Hallway	Tested	12:20:18 PM	01/19/2026
Pull Station	1st Main Electric Room By Managers Office Exit Door	Tested	11:04:35 AM	01/19/2026

Device Type	Location	Service	Time	Date
<b>PASSED</b> (continued)				
<b>Initiating</b> (continued)				
Pull Station	1st North Vestibule	Tested	10:01:49 AM	01/19/2026
Pull Station	1st South Vestibule	Tested	10:03:23 AM	01/19/2026
Pull Station	2nd East Stairs	Tested	9:35:13 AM	01/19/2026
Pull Station	2nd West Stairs	Tested	9:34:33 AM	01/19/2026
Pull Station	3rd East Stairs	Tested	8:45:02 AM	01/19/2026
Pull Station	3rd West Stairs	Tested	7:31:52 AM	01/19/2026
Pull Station	4th East Stairs	Tested	8:18:15 AM	01/19/2026
Pull Station	4th West Stairs	Tested	8:20:24 AM	01/19/2026
Pull Station	5th East Stairs	Tested	8:16:21 AM	01/19/2026
Pull Station	5th West Stairs	Tested	8:13:40 AM	01/19/2026
Pull Station	Garage East Stairs	Tested	10:55:26 AM	01/19/2026
Pull Station	Garage West Stairs	Tested	10:59:45 AM	01/19/2026
Smoke Detector	Pump Room Above FACP	Tested/Cleaned	10:48:28 AM	01/19/2026
Smoke Detector	1st Electrical Room By Elevators	Tested/Cleaned	10:02:01 AM	01/19/2026
Smoke Detector	1st Elevator Lobby	Tested/Cleaned	9:56:25 AM	01/19/2026
Smoke Detector	1st Emergency Electrical Room By Managers Office	Tested/Cleaned	10:36:44 AM	01/19/2026
Smoke Detector	1st MPOP Room	Tested/Cleaned	10:15:15 AM	01/19/2026
Smoke Detector	1st Main Electrical Room By Managers Office	Tested/Cleaned	10:37:18 AM	01/19/2026
Smoke Detector	1st Service Elevator Lobby	Tested/Cleaned	10:04:26 AM	01/19/2026
Smoke Detector	2nd Electrical Room	Tested/Cleaned	9:27:22 AM	01/19/2026
Smoke Detector	2nd Elevator Lobby	Tested/Cleaned	9:24:33 AM	01/19/2026
Smoke Detector	2nd MPOP Room	Tested/Cleaned	9:29:45 AM	01/19/2026
Smoke Detector	3rd Electrical Room	Tested/Cleaned	8:43:21 AM	01/19/2026
Smoke Detector	3rd Elevator Lobby	Tested/Cleaned	8:41:42 AM	01/19/2026

Device Type	Location	Service	Time	Date
<b>PASSED</b> (continued)				
<b>Initiating</b> (continued)				
Smoke Detector	3rd MPOP Room	Tested/Cleaned	9:03:43 AM	01/19/2026
Smoke Detector	4th Electrical Room	Tested/Cleaned	8:22:42 AM	01/19/2026
Smoke Detector	4th Elevator Lobby	Tested/Cleaned	8:21:05 AM	01/19/2026
Smoke Detector	4th MPOP Room	Tested/Cleaned	8:25:42 AM	01/19/2026
Smoke Detector	5th Electrical Room	Tested/Cleaned	8:13:47 AM	01/19/2026
Smoke Detector	5th Elevator 1 & 2 Machine Room	Tested/Cleaned	8:08:06 AM	01/19/2026
Smoke Detector	5th Elevator 3 Machine Room	Tested/Cleaned	8:05:39 AM	01/19/2026
Smoke Detector	5th Elevator Lobby	Tested/Cleaned	7:53:13 AM	01/19/2026
Smoke Detector	5th MPOP Room	Tested/Cleaned	7:56:27 AM	01/19/2026
Smoke Detector	5th Shaft	Tested/Cleaned	1:32:30 PM	01/19/2026
Smoke Detector	5th Elevators 1 & 2 Shaft	Tested/Cleaned	1:32:20 PM	01/19/2026
Smoke Detector	Garage Electrical Room	Tested/Cleaned	10:57:39 AM	01/19/2026
Smoke Detector	Garage Elevator Lobby	Tested/Cleaned	10:53:50 AM	01/19/2026
Smoke Detector	Garage Elevator 3 Pit	Tested/Cleaned	1:29:33 PM	01/19/2026
Smoke Detector	Garage Elevators 1 & 2 Pit	Tested/Cleaned	1:29:25 PM	01/19/2026
Waterflow Switch	LL East Stairs Waterflow	Tested	12:22:42 PM	01/19/2026
Waterflow Switch	Pump Room 1st Floor Riser Waterflow	Tested	11:46:41 AM	01/19/2026
Waterflow Switch	Pump Room Stairwell Standpipe Waterflow	Tested	11:48:31 AM	01/19/2026
Waterflow Switch	2nd East Stairs	Tested	12:16:08 PM	01/19/2026
Waterflow Switch	3rd East Stairs Waterflow	Tested	12:12:35 PM	01/19/2026
Waterflow Switch	4th East Stairs Waterflow	Tested	12:10:29 PM	01/19/2026
Waterflow Switch	5th East Stairs Waterflow	Tested	11:58:47 AM	01/19/2026
<b>Supervisory</b>				
Fire Pump Power	Pump Room Pump Power	Tested	7:49:59 AM	01/19/2026
Tamper Switch	LL East Stairs Tamper	Tested	12:21:36 PM	01/19/2026

Device Type	Location	Service	Time	Date
<b>PASSED</b> (continued)				
<b>Supervisory</b> (continued)				
Tamper Switch	Pump Room Gate Valves	Tested	11:28:34 AM	01/19/2026
Tamper Switch	Pump Room Gate Valves	Tested	11:30:03 AM	01/19/2026
Tamper Switch	Pump Room Tamper	Tested	11:29:42 AM	01/19/2026
Tamper Switch	Pump Room Tamper	Tested	11:30:09 AM	01/19/2026
Tamper Switch	Pump Room Tamper	Tested	11:30:40 AM	01/19/2026
Tamper Switch	Pump Room Tamper	Tested	11:31:11 AM	01/19/2026
Tamper Switch	Pump Room Tamper	Tested	11:31:46 AM	01/19/2026
Tamper Switch	Pump Room Tamper	Tested	11:32:12 AM	01/19/2026
Tamper Switch	Pump Room Tamper	Tested	11:32:39 AM	01/19/2026
Tamper Switch	Pump Room Test Header CLOSED	Tested	7:46:00 AM	01/19/2026
Tamper Switch	Pump Room Waterflow	Tested	11:33:06 AM	01/19/2026
Tamper Switch	1st Maintenance Garage Tamper	Tested	11:38:01 AM	01/19/2026
Tamper Switch	1st West Stairs Tamper Between 1st & 2nd Floor Landing	Tested	12:36:16 PM	01/19/2026
Tamper Switch	2nd East Stairs Tamper	Tested	12:15:47 PM	01/19/2026
Tamper Switch	3rd East Stairs Tamper	Tested	12:11:30 PM	01/19/2026
Tamper Switch	4th East Stairs Tamper	Tested	12:07:25 PM	01/19/2026
Tamper Switch	5th East Stairs Tamper	Tested	11:56:16 AM	01/19/2026
Tamper Switch	Garage Elevator 3 Pit Tamper	Tested	12:30:52 PM	01/19/2026
Tamper Switch	Garage Garage Elevator 1 & 2 Tamper	Tested	12:32:22 PM	01/19/2026
<b>FAILED/OTHER</b>				
<b>Initiating</b>				
Duct Detector	3rd West Office By Cubicle 3-109 SD-3W	Tested	9:10:09 AM	01/19/2026

# SERVICE SUMMARY

Generated by: BuildingReports.com

The Service Summary section provides an overview of the services performed in this report.

**Building:** Wheaton Office

Device Type	Service	Quantity
<b>PASSED</b>		
Annunciator	Tested	1
Battery	Tested	18
Control Panel	Tested	1
Duct Detector	Tested	10
Fire Pump Power	Tested	1
Heat Detector	Tested	21
Power Supply	Tested	8
Pull Station	Tested	21
Smoke Detector	Tested/Cleaned	27
Tamper Switch	Tested	20
Waterflow Switch	Tested	7
<b>Total</b>		<b>135</b>
<b>FAILED/OTHER</b>		
Duct Detector	Tested	1
<b>Total</b>		<b>1</b>
<b>Grand Total</b>		<b>136</b>

# SOUND AND VISUAL TESTING

Generated by: [BuildingReports.com](https://BuildingReports.com)

The Sound and Visual Testing section lists various points throughout your building where audible and visual alarm notification devices were tested. Any bar-coded audible and visual devices will appear in the Inspection and Testing section of this report. Items in this section are grouped by Passed or Failed/Other. Where specific decibel readings were recorded, they will appear under the ambient and alarm columns. The Voice column indicates whether the Sound Test Point passed the Voice Intelligibility requirements. The STI or Sound Transmission Index is shown if recorded.

## Building: Wheaton Office

Location	Comment	Ambient	Alarm	Voice Intelligibility	STI	Sound Test
<b>PASSED</b>						
Throughout Building Tested ok 1 /19/2026	Passed			<input type="checkbox"/>		0001

# TIME, TEMPERATURE & LEVEL TESTING

Generated by: BuildingReports.com

The Time, Temperature, & Level Testing section details the measurements taken from various devices that are designed to respond in a certain amount of time, respond at a certain temperature, or respond within the acceptable range of volume or level. Items are grouped by Passed or Failed/Other.

**Building:** Wheaton Office

**Control Panel:** 1 - Silent Knight IFP-1000

Type	Location	Comment	Sec	Deg	Lvl	ScanID
<b>PASSED</b>						
<b>Waterflow Switch</b>						
	LL East Stairs Waterflow	Passed	20	n/a	n/a	32703867
	Pump Room 1st Floor Riser Waterflow	Passed	35	n/a	n/a	30565189
	Pump Room Stairwell Standpipe Waterflow	Passed	30	n/a	n/a	57331475
	2nd East Stairs	Passed	15	n/a	n/a	32703866
	3rd East Stairs Waterflow	Passed	15	n/a	n/a	32703863
	4th East Stairs Waterflow	Passed	15	n/a	n/a	32703862
	5th East Stairs Waterflow	Passed	25	n/a	n/a	32703860

# BATTERY & POWER SUPPLY TESTING

Generated by: BuildingReports.com

The Battery & Power Supply Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

**Building:** Wheaton Office

**Control Panel:** 1 - Silent Knight IFP-1000

## Battery

Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah	MFG Date
<b>PASSED</b>								
Sealed Lead Acid	Pump Room FACP Battery	18	12					06/21 /2022
Sealed Lead Acid	Pump Room FACP Battery	18	12					06/21 /2022
	Suite 140 Electric Room NAC Battery	8	12					01/19 /2026
	Suite 140 Electric Room NAC Battery	8	12					01/19 /2026
Sealed Lead Acid	Suite 190 FCPS NAC Battery	8	12					06/21 /2022
Sealed Lead Acid	Suite 190 FCPS NAC Battery	8	12					06/21 /2022
Sealed Lead Acid	2nd MPOP Room NAC Battery	8	12					06/21 /2022
Sealed Lead Acid	2nd MPOP Room NAC Battery	8	12					06/21 /2022
Sealed Lead Acid	4th MPOP Room 3rd Floor NAC Battery	8	12					06/21 /2022
Sealed Lead Acid	4th MPOP Room 3rd Floor NAC Battery	8	12					06/21 /2022
Sealed Lead Acid	4th MPOP Room 5th Floor NAC Battery	8	12					06/21 /2022

Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah	MFG Date
<b>PASSED</b> (continued)								
Sealed Lead Acid	4th MPOP Room 5th Floor NAC Battery	8	12					06/21/2022
Sealed Lead Acid	4th MPOP Room For 4th Floor NAC Battery	8	12					06/21/2022
Sealed Lead Acid	4th MPOP Room For 4th Floor NAC Battery	8	12					06/21/2022
Sealed Lead Acid	4th MPOP Room NAC Battery	8	12					06/21/2022
Sealed Lead Acid	4th MPOP Room NAC Battery	8	12					06/21/2022

# INVENTORY & WARRANTY REPORT

Generated by: [BuildingReports.com](https://BuildingReports.com)

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

## Building: Wheaton Office

Device or Type	Category	% of Inventory	Quantity
Annunciator	Control	0.73%	1
Battery	Control	13.14%	18
Control Panel	Control	0.73%	1
Duct Detector	Initiating	8.03%	11
Fire Pump Power	Supervisory	0.73%	1
Heat Detector	Initiating	15.33%	21
Power Supply	Control	5.84%	8
Pull Station	Initiating	15.33%	21
Smoke Detector	Initiating	19.71%	27
Sound Test	Indicating	0.73%	1
Tamper Switch	Supervisory	14.60%	20
Waterflow Switch	Initiating	5.11%	7

## Building: Wheaton Office

## Control Panel: 1 - Silent Knight IFP-1000

Type	Qty	Model #	Description	Install Date
<b>IN SERVICE - 3 YEARS TO 5 YEARS</b>				
<b>DURACELL ULTRA</b>				
Battery	2	DURA12-8F2		06/18/2022
Battery	8	DURA12-8F2	Sealed Lead Acid	06/21/2022
Battery	2	DURA12-8F2	Sealed Lead Acid	06/18/2022

Type	Qty	Model #	Description	Install Date
<b>IN SERVICE - 3 YEARS TO 5 YEARS</b> (continued)				
<b>DuraCell</b>				
Battery	2	Dura12-18NB	Sealed Lead Acid	06/21/2022
Battery	2	Dura12-8F	Sealed Lead Acid	06/21/2022
<b>Duracell</b>				
Battery	2	Dura12-8F	Sealed Lead Acid	06/21/2022
<b>IN SERVICE - 10 YEARS TO 15 YEARS</b>				
<b>AES</b>				
Smoke Detector	1	SD505-APS	Photoelectric	09/18/2014
<b>Fire Lite</b>				
Power Supply	1	FL-PS6		09/18/2014
Pull Station	1	BG-12LX	Dual Action	09/18/2014
<b>Master</b>				
Fire Pump Power	1	MCA-50-46-HX		09/18/2014
<b>Milwaukee</b>				
Tamper Switch	2	BSB-SCSO		09/18/2014
<b>Potter Electric</b>				
Tamper Switch	3	OSYSU-2		09/18/2014
Waterflow Switch	2	VSR-F		09/18/2014
<b>Silent Knight</b>				
Annunciator	1	RA-100	LED List	04/18/2014
Control Panel	1	IFP-1000	Addressable	09/18/2014
Heat Detector	2	SD505-APS		09/18/2014
Heat Detector	16	SD505-HT		09/18/2014
Heat Detector	3	SD505-HT	Fixed Temperature	09/18/2014
Power Supply	1	5495		09/18/2014
Power Supply	6	5499		09/18/2014
Pull Station	1	PS-DA		09/18/2014

Type	Qty	Model #	Description	Install Date
<b>IN SERVICE - 10 YEARS TO 15 YEARS</b> (continued)				
<b>Silent Knight</b> (continued)				
Pull Station	19	PS-DA	Dual Action	09/18/2014
Smoke Detector	26	SD505-APS	Photoelectric	09/18/2014
<b>System Sensor</b>				
Duct Detector	7	RTS451	Photoelectric	09/18/2014
Duct Detector	4	RTS451KEY	Photoelectric	09/18/2014
Waterflow Switch	5	WFD25		09/18/2014
<b>Victaulic</b>				
Tamper Switch	1	705		09/18/2014
Tamper Switch	12	705W		09/18/2014
Tamper Switch	2	728		09/18/2014

# ZONE ADDRESS REPORT

Generated by: [BuildingReports.com](https://BuildingReports.com)

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

**Building:** Wheaton Office

**Control Panel:** 1 - Silent Knight IFP-1000

Address	Device Type	Location	Type	ScanID
<b>ZONE/CIRCUIT: M</b>				
03	Fire Pump Power	Pump Room Pump Power		32703771
05	Tamper Switch	Pump Room Test Header CLOSED		30565181
26	Heat Detector	Garage Pit		32703779
32	Heat Detector	Garage Elevator Pit Pit		32703778
34	Heat Detector	Garage Elevator Pit		32703777
83	Smoke Detector	5th Shaft	Photoelectric	32703781
107	Waterflow Switch	4th East Stairs Waterflow		32703862
<b>ZONE/CIRCUIT: M31</b>				
05	Tamper Switch	Pump Room Tamper		30565176
M01	Waterflow Switch	Pump Room 1st Floor Riser Waterflow		30565189
M02	Waterflow Switch	Pump Room Stairwell Standpipe Waterflow		57331475
M03	Tamper Switch	Pump Room Tamper		30565184
M03	Tamper Switch	Pump Room Waterflow		30565185
M04	Tamper Switch	Pump Room Gate Valves		30565172
M04	Tamper Switch	Pump Room Gate Valves		30565173
M05	Tamper Switch	Pump Room Tamper		30565178
M05	Tamper Switch	Pump Room Tamper		30565179
M05	Tamper Switch	Pump Room Tamper		30565180
M05	Tamper Switch	Pump Room Tamper		30565182
M05	Tamper Switch	Pump Room Tamper		30565183

Address	Device Type	Location	Type	ScanID
<b>ZONE/CIRCUIT: M31</b> (continued)				
M51	Tamper Switch	1st Maintenance Garage Tamper		A3345873
M64	Tamper Switch	1st West Stairs Tamper Between 1st & 2nd Floor Landing		32703775
M103	Waterflow Switch	2nd East Stairs		32703866
M104	Tamper Switch	2nd East Stairs Tamper		32703865
M105	Waterflow Switch	3rd East Stairs Waterflow		32703863
M106	Tamper Switch	3rd East Stairs Tamper		32703864
M108	Tamper Switch	4th East Stairs Tamper		32703861
M109	Waterflow Switch	5th East Stairs Waterflow		32703860
M110	Tamper Switch	5th East Stairs Tamper		32703859
M123	Tamper Switch	Garage Garage Elevator 1 & 2 Tamper		32703772
M124	Tamper Switch	Garage Elevator 3 Pit Tamper		32703773
M125	Waterflow Switch	LL East Stairs Waterflow		32703867
M126	Tamper Switch	LL East Stairs Tamper		32703868
<b>ZONE/CIRCUIT: M33</b>				
98	Pull Station	Suite 190 North Exit	Dual Action	39732918
M01	Pull Station	Suite 100 North Exit	Dual Action	39732916
M03	Pull Station	Suite 140 Main Entrance	Dual Action	39732917
M06	Pull Station	1st East Hallway	Dual Action	32703913
M007	Heat Detector	Pump Room Above FACP	Fixed Temperature	A3345872
M008	Smoke Detector	Pump Room Above FACP	Photoelectric	A3345871
M09	Pull Station	Pump Room Exit Door	Dual Action	32703915
M10	Smoke Detector	1st Emergency Electrical Room By Managers Office	Photoelectric	32703997
M11	Heat Detector	1st Emergency Electrical Room By Managers Office		32703998
M12	Pull Station	1st South Vestibule	Dual Action	32703914

Address	Device Type	Location	Type	ScanID
<b>ZONE/CIRCUIT: M33</b> (continued)				
M13	Pull Station	1st Main Electric Room By Managers Office Exit Door	Dual Action	32703912
M14	Heat Detector	1st Main Electrical Room By Managers Office		32703999
M15	Smoke Detector	1st Main Electrical Room By Managers Office	Photoelectric	32704000
M16	Smoke Detector	1st Service Elevator Lobby	Photoelectric	32704001
M17	Smoke Detector	1st Electrical Room By Elevators	Photoelectric	32704003
M18	Heat Detector	1st Electrical Room By Elevators		32704002
M19	Smoke Detector	1st Elevator Lobby	Photoelectric	32703986
M22	Smoke Detector	1st MPOP Room	Photoelectric	32703996
M23	Heat Detector	1st MPOP Room		32703995
M24	Heat Detector	Garage Electrical Room	Fixed Temperature	32703970
M25	Smoke Detector	Garage Electrical Room	Photoelectric	32703969
M27	Smoke Detector	Garage Elevator 3 Pit	Photoelectric	32703783
M28	Smoke Detector	Garage Elevator Lobby	Photoelectric	32703971
M31	Smoke Detector	Garage Elevators 1 & 2 Pit	Photoelectric	32703782
M35	Pull Station	Garage West Stairs	Dual Action	32703911
M36	Pull Station	Garage East Stairs	Dual Action	32703910
M37	Pull Station	2nd East Stairs	Dual Action	32703909
M39	Duct Detector	2nd North Lobby Storage Room East Duct	Photoelectric	32703897
M40	Smoke Detector	2nd Electrical Room	Photoelectric	32703974
M41	Heat Detector	2nd Electrical Room		32703973
M42	Smoke Detector	2nd Elevator Lobby	Photoelectric	32703975
M45	Heat Detector	2nd MPOP Room		32703972
M46	Smoke Detector	2nd MPOP Room	Photoelectric	32703994
M47	Pull Station	2nd West Stairs	Dual Action	32703908

Address	Device Type	Location	Type	ScanID
<b>ZONE/CIRCUIT: M33</b> (continued)				
M49	Duct Detector	2nd West Electrical closet By Copier /Kitchen	Photoelectric	32703895
M50	Pull Station	3rd East Stairs	Dual Action	32703905
M52	Duct Detector	3rd East Hallway By Locker Rooms	Photoelectric	32703894
M53	Heat Detector	3rd Electrical Room		32703988
M54	Smoke Detector	3rd Electrical Room	Photoelectric	32703989
M55	Smoke Detector	3rd Elevator Lobby	Photoelectric	32703990
M56	Pull Station	Suite 190 West Dining Room Exit	Dual Action	39732920
M57	Pull Station	Suite 190 West Kitchen Exit	Dual Action	76318903
M58	Heat Detector	3rd MPOP Room		32703987
M59	Smoke Detector	3rd MPOP Room	Photoelectric	32703984
M60	Pull Station	3rd West Stairs	Dual Action	32703904
M61	Pull Station	1st North Vestibule	Dual Action	32703903
M62	Duct Detector	3rd West Office By Cubicle 3-109 SD-3W	Photoelectric	32703893
M63	Pull Station	4th East Stairs		32703902
M65	Duct Detector	4th East Office By East Stairs SD-4E	Photoelectric	32703892
M66	Heat Detector	4th Electrical Room		32703981
M67	Smoke Detector	4th Electrical Room	Photoelectric	32703982
M68	Smoke Detector	4th Elevator Lobby	Photoelectric	32703983
M70	Duct Detector	Suite 190 Beverage Area	Photoelectric	32703966
M71	Heat Detector	4th MPOP Room		32703976
M72	Smoke Detector	4th MPOP Room	Photoelectric	32703977
M73	Pull Station	4th West Stairs	Dual Action	32703901
M75	Duct Detector	4th West Office By Room 4-154 SD-4W	Photoelectric	32703891
M76	Pull Station	5th East Stairs	Dual Action	32703900
M78	Duct Detector	5th SD-5E By IT Lab	Photoelectric	32703890

Address	Device Type	Location	Type	ScanID
<b>ZONE/CIRCUIT: M33</b> (continued)				
M80	Heat Detector	5th Electrical Room		32703856
M81	Smoke Detector	5th Electrical Room	Photoelectric	32703857
M84	Heat Detector	5th Elevator 3 Machine Room		32703855
M85	Smoke Detector	5th Elevator 3 Machine Room	Photoelectric	32703854
M86	Smoke Detector	5th Elevator Lobby	Photoelectric	32703858
M87	Duct Detector	Suite 190 Beverage Area	Photoelectric	32703968
M88	Duct Detector	Suite 190 Rear Kitchen By Freezer	Photoelectric	32703967
M89	Heat Detector	5th Elevators 1 Shaft		32703898
M90	Smoke Detector	5th Elevators 1 & 2 Shaft	Photoelectric	32703780
M91	Heat Detector	5th Elevators 1 & 2 Shaft		32703896
M92	Pull Station	Suite 190 North Main Entrance	Dual Action	A3345875
M93	Heat Detector	5th Elevator 1 & 2 Machine Room		32703852
M94	Smoke Detector	5th Elevator 1 & 2 Machine Room	Photoelectric	32703853
M95	Heat Detector	5th MPOP Room	Fixed Temperature	32703873
M96	Smoke Detector	5th MPOP Room	Photoelectric	32703872
M97	Pull Station	5th West Stairs	Dual Action	32703899
M99	Duct Detector	5th West Office By Room 5-137 SD-5W	Photoelectric	32703889