

# DETECTION

SYSTEMS & SERVICE INC.

## CERTIFICATION / INSPECTION REPORT

SUBSCRIBER		ALARM COMPANY	
Name Office park of hinsdale		DETECTION SYSTEMS & SERVICE, INC.	
Address 12 salt creek ln		17W725 Butterfield, Suite D	
C-S-Z Hinsdale, IL		Oakbrook Terrace, IL 60181	
Phone		Phone: (630) 705-9585	

FIRE ALARM CONTROL PANEL											
Manufacturer/model: Vigilant VS4						Number of Zones:					
Does panel indicate normal condition:	Y	<input checked="" type="checkbox"/>	N	<input type="checkbox"/>	Does the silence switch operate:	Y	<input checked="" type="checkbox"/>	N	<input type="checkbox"/>		
Are all indicating lights in working order:	Y	<input checked="" type="checkbox"/>	N	<input type="checkbox"/>	Are the batteries Properly charged:	Y	<input checked="" type="checkbox"/>	N	<input type="checkbox"/>		
Does trouble light operate:	Y	<input checked="" type="checkbox"/>	N	<input type="checkbox"/>	Batteries:	Qty: 2	Volt: 12	AH: 12			

FIRE DETECTION INITIATION AND ANNUNCIATION DEVICES											
Device	Qty	Tested	Cleaned	Pass	Fail	Device	Qty	Tested	Cleaned	Pass	Fail
Remote Annun.	1	1		1		Smoke Det. (Photo)	153	153	153	153	
Audio/Visual	76	76		76		Smoke Det.(Ion)					
Visuals only	79	79		79		Smoke Det. (Duct)	21	21		21	
Bells	2	2		2		Thermal Det. (ROR)	6	4		4	
Waterflow (Paddle)	8	8		8		Thermal Det. (FT)					
Waterflow (Pressure)						Manual Pull Station	14	14		14	
Valve Tamp. (OS&Y)	10	10		10							
Valve Tamp. (PIV)											
NAC Power Expander	7	7		7							

SPRINKLER SYSTEM SUPERVISORY DEVICES						
Main Drain Test	Static Pressure 70 psi			Residual Pressure (flowing) 60 psi		
Waterflow	Riser #1	Riser #2	Riser #3	Riser #4	Riser #5	Riser #6
	4th fl	3rd fl	2nd fl	1st fl	Main	East/west
Delay (secs)	45	41	35	40	40	39/41

REMOTE MONITORING			
Monitoring Station Type: Central	Transmitter Type: Radio		
Monitoring Performed by: Ducom	Connection Date:		
Phone / Channel numbers used in transmission:			
Did Fire Alarm panel transmit properly for:	Alarm: yes	Trouble: yes	Alarm Trouble Over Ride: yes

**NOTES/COMMENTS**  
Tested dampers and 2nd floor door closures. Tested standpipe waterflow Manually tested ok.

Inspector name: \_\_\_\_\_ Inspection: \_\_\_\_\_ Pass:  Fail:

**DEVIATIONS FROM NFPA72**

**INSPECTION**  
Inspection performed by: Manuel Godinez NICET NO 236623 Date: 12-24-2025